

Douglas County Surveyor's Record of
Government Corners Renewed

T 29 T. S. R 6 R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 21881

250

1/4 Corner for Secs. 25 and 36.
Set - At midpoint set 5/8" x 30" Iron rod and alum. cap.
BT's - 6" Fir, N.6°W., 27.2 ft.
5" Fir, S.87°E., 5.0 ft.

Howard Johnstone
For: Roseburg Lbr.
Company
April 1978
R M 3 - 12

1/4 Corner for Section 36 and Sec. 31 of T29-5
Set - At midpoint set 5/8" x 30" Iron rod and alum. cap.
BT's - 7" Oak, S.40°W., 3.5 ft.
9" Oak, S.58°E., 5.5 ft.
Found - 3/4" I.P. S.48°W., 51.9 ft. Ren. #188

251

252

Section corner for 36; and 31 of T29-5, Sec. 1 of T30-6, Sec. 6 of T30-5.
Found - 3/4" I.P. and 4 BTs (all down.) Ren. #189
Set - 5/8" x 30" Iron rod and alum cap in Iron pipe.
New BT's - 6" Pine, N.4 1/2°W., 50.0 ft.
8" Pine, N.67°E., 3.6 ft.
12" Pine S.85°W., 31.3 ft.
8" Pine S.29°E., 41.3 ft.

April 1978

253

1/4 Corner for sections 34 and 35.
Found - A 5/8" x 30" I. Rod with alum. cap set 1.0 ft. above ground
and marked "T29S R6W 34 35 1/4 S LS 498 1978" Ren. #248
At location of improperly set 1/4 corner, a 5/8" I.R. bears
N.6 1/2°W., 30.1 ft. I attach an alum. cap marked "Douglas
Co. Surveyor" 1978. Ren. #122.
A 18" Fir stump now bears N.22°E., 56.4 ft. (Rec. N.48 1/2°E.,
33.0 ft.) with scribing "BT" in bottom blaze.
A 12" now 16" Fir is uprooted. Root hole bears N.45°W., 41.8 ft.
(Rec. N.84 3/4°W., 27.0 ft.) with scribing "T29S R6W 1/4
S34 CS BT" in a partly healed double blaze.
A 40" Fir snag, 70 ft. high bears N.84°E., 23.9 ft. (Rec. S.45 3/4°
E., 39.6 ft.)
Set - A 1" x 36" I.P. with brass cap set 4" above ground marked "Douglas
County Surveyor". I set alum. cap under north edge of brass cap.
Cap also marked T29S R6W 1/4 S34 S35 1978.
No new accessories. Corner is approx 40 ft. east of fence.

6/29/78

R. B. Kimberling
S. J. Flause
Doug. Co. Surveyor
June 29, 1978
C.S. 60/11

1-79

254

Howard W. Johnstone
LS# 498
For: Roseburg Lumber
June 1980
M 84 - 10

1/4 Corner to Secs. 28 and 29 See Ren. #40
Set - 5/8" x 30" Iron rod and alum. cap.
BT's - 8" Maple bears S.49°W., 39.4 ft.
24" Maple bears N.6°E., 54.9 ft.
No evidence of corner set by County Surveyor in 1924. Set corner by stan-
dard subdivision procedure.

255

William Ruppert
LS #866
For: Carl Fisher
July, 1981
M 88 - 20 A & B

SW corner DLC #40.
Set - Brass Cap on a 3/4" x 36" I.P., marked: T29S R6W
DLC 40
PLS 866
1981
BT's - 20" B Oak bears N.1°12'W., 51.4-ft., scribed SW C40 BT
BO's - 2" steel post, fence North & East bears N.3°16'E., 49.8-ft.
Utility pole C8845 N.87°45'E., 78.2-ft. See Narrative M88-20B.

7/81

256

Gregory Quibell, Dep.
Doug. Co. Surveyors Off.
John Powell-Randy Smith
Jan. 28, 1983
C.S. 62/7

Township corner, Sec. 31; Sec. 36, T.29-7; Sec. 1, T.30-7; Sec. 6, T.30-6
Found - 1962 Doug. Co. Surveyors Office brass cap properly mkd. and firmly
set. Ren. #163
1968 BLM brass cap per resurvey properly marked and firmly set
with what appears to be the original corner stone buried along-
side. Doug. Co. brass cap bears S.23 1/2°E., 1.65ft. from
BLM cap.
Found all accessories as described in 1968 resurvey and 1982
Lloyd Smith survey. (M 93-45)

My measurements to the two remaining orig. BTs from each of the brass caps,
plus faint notches on all four edges of the fd. stone cause me to accept the
position of the BLM location. I cut the DCSO BC off and drive a yellow nylon
cap inside the remaining 1" I.P. Cap mkd. "Doug. Co. Surveyor"