

Douglas County Surveyor's Record of  
Government Corners Renewed

T 29

T. S.

R 6

R. W. W. M.

FORE-CHAPMAN CO., EUGENE, ORE. 97501

257

Section corner for Secs. 25 and 36; and 30 & 31 of T.29-5

Found - 1977 County brass cap with a 1" iron pipe along side of pipe with brass cap. Ren. #244

38" W. fir stump which bears S.60°W., 11.2 ft. scribes visible.

40" fir stump bearing S.73 1/4°E., 55.5 ft. scribes visible.

34" fir stump bearing N.67 1/2°W., 42.2 ft. This stump cut too low for any scribing to remain.

All other bearing trees were destroyed in logging. Also the 30" fir stump 64.2 ft. east is gone.

New BTs - 10" W. fir bears N.67°E., 38.4 ft. marked T29S R5W S30 BT.

6" fir bears N.52°W., 74.4 ft. marked T29S R6W S25 BT.

8/7/85

Section corner for Sections 8, 9, 17 and 16.

258

Found - 1958 BLM brass cap, properly mkd., on a 2 1/2" O.D. iron pipe is firmly set and protrudes 9" from the ground. (This monument leans approx. 5" to the northwest of plumb; because it does not appear to be disturbed, bearings and dist. to accessories are measured from center of cap).

At west edge of above monument is a DCSO brass cap monument, as described in Ren. #135, which is firmly set and protruding 10" above ground. (Ren. #135 notes DCSO cap stamped 1957, is 1954)

At west edge of DCSO brass cap, is a 3/4" bolt with a 1 1/4" x 1 1/4" square top, noted as found in Ren. #135, firmly set and protruding 3" above ground. Origin of bolt unknown.

From 1917 Hicks survey filed at DCSO as M 13 - 71:

12" R. Fir now a 22" DNH D. fir, fallen with a chopped out rotted blaze, has a root depression which bears S.75°W., 8.0 ft. dist.

12" R. Fir now a 24" DBH D. fir with a fully healed single blaze bears N.50°E., 12.2 ft. dist.

16" R. fir now a 24" diam. 4 ft. tall fir stump, old blaze opened to reveal scribing "R6W" bears S.22°E., 17.0 ft. dist.

(No evidence of NW bearing tree found. Hicks survey states his corner set from original Gov't notes)

From Renewal #135:

a 9" R. fir now a 9" diam. 4 ft. tall rotted fir stump with scribing S17 T29S R6W CS BT visible bears S.22°W., 50.5 ft. dist.

12" R. fir now a 2 1/2 ft. tall, 12" diam. rotted fir stump with a rotted blaze. No scribing visible, bears S.02°W., 31.7 ft.

15" R. fir now a 21" DBH D. fir with a fully healed double blaze, bears N.70 1/4°E., 32.8 ft. (Rec. N.72°E., 32.8 ft.)

A root hole depression is found near correct bearing and dist. for NW bearing tree, tree not found.

From 1958 BLM dependent resurvey:

A fir, 7" dia. now an 13" DBH D. fir with a partially healed single blaze with the scribing 9S R6W S visible bears S.85°E., 58.1 ft.

A 7" fir now an 18" DBH D. Fir with a fully healed single blaze bears N.67 1/2°W., 43.6 ft. (Rec. N.67 1/2°W., 44.9 ft.) This is a slope measurement.)

Since monument is firmly set and the center of the BLM brass cap agrees with the majority of the accessories, the monument position is accepted as is and is not reset to plumb. Corner lies at tree line on north edge of cleared pasture 200 ft. west of point where a jeep road leaves a stand of timber and climbs a cleared ridge running south by southwest.

11/14/85

259

Center 1/4 Section corner for Section 29

Set - 5/8" iron rod with alum. cap marked: T29S R6W C 1/4 S29 LS 418 1987"

From which new BTs:

29" madrone bears S.66°W., 11.2 ft. which I scribed "C 1/4 S29 BT".

15" cedar bears N.76°W., 30.9 ft. which I scribed "C 1/4 S29 BT".

1" Iron pipe bears N.58°W., 0.4 ft.

2" iron pipe 3 ft. above ground, in old N-S fence line bears S.79°W., 31.8 ft.

3/87

Burton W. Holt  
L.S. #418  
Sun Studs, Inc.  
Gary Angiolet  
Aug. 7, 1985  
C.S. 63/8

Douglas County Surveyors Office  
Deputies: S. J. Flause  
R. W. Smith  
November 14, 1985  
C.S. 62/29

Burton W. Holt  
For: Crooked River  
Properties, Inc.  
March 1987  
M 104 - 3  
C.S. 63/53