

Douglas County Surveyor's Record of
Government Corners Renewed

T 29

T. S.

R 6

R.W.W.M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

Howard Johnstone
For: Roseburg
Resources, Inc.
August, 1989
M 101 - 60

1/4 Corner for Section 19 (only) West 260
Set - 5/8" x 48" iron rod and alum. cap mkd. "1/4 S 19 only"
New BTs-10" fir N.24°E., 13.0 ft. scribed "1/4 S 19 BT".
36" madrone S.74°E., 3.5 ft. scribed "1/4 S 19 BT".

East 1/4 Corner Section 24 (only) of T.29-7 261
Set - 5/8" x 48" iron rod and alum. cap marked "1/4 Cor Sec 24 only."
New BTs-10" fir S.36°W., 3.2 ft. scribed "1/4 S 24 BT"
21" fir N.51°W., 5.7 ft. scribed "1/4 S 24 BT".

8/89

Howard Johnstone
For: Roseburg
Resources Inc.
Jan. 23, 1990
C.S. 63/104

True Closing Corner Sections 31 and 32. (SE Sec. Cor. 31) 262
Found - 1980 Cadastral brass cap on iron pipe. (Vol. 45 Pg. 17259)
6" fir, N.72 3/4°W., 58.4 ft. high stumped. Gone 1980 Cad.
8" fir N.64 1/2°E., 35.6 ft. good face high stumped. 1980
23.1 ft. north to AM-CC brass cap. (1958 Cad.)
Tied corner to remaining BTs for the AM-CC:
50" D. fir stump bark scribed, N.36°W., 67.0 ft.
18" Fir healed face - N.37°E., 45.5 ft.
25" W. fir healed face, N.54°E., 49.6 ft.

Corner lays in NE corner of 1989-90 clear cut unit logging all around the corner. About 200 ft. south of road.

1/23/90

Douglas County
Surveyors Office
Randall Smith
Steven Flause
Feb. 6, 1990
C.S. 64/5

Section Corner for Sec. 6; and Sec. 31 of T.28-6; Sec. 36 of T.28-7 and Sec. 1 of T.29-7 263
Found - A 1985 DCSO 2 1/2" dia. brass cap on a 1 1/4" O.D. iron pipe which protrudes 16" above ground. Ren. #144
Orig. 10" laurel now 24" dia. at base 3 ft. high rotted oak stump with axe mark (mix-up in orig. rec. See Ren. #67 in T.28-7) bears N.71 1/4°W., 39.6 ft. (agrees with orig. and Ren. #71 in T.28-6. Possible problem with dist. in Ren. #67, T.28-7.
15" now 20" dia. D. fir with a fully healed double blaze, bears N.27°E., 55.6 ft. Ren. No. 144
15" now 23" dia. D. fir with a fully healed double blaze, bears N.28°W., 47.9 ft. Ren. No. 144
13" now 18" dia. D. fir with a fully healed double blaze, bears S.54°W., 124.6 ft. Ren. No. 144
18" dia. 4 ft. high rotted D. fir stump, previously opened with illegible scribing visible, blaze faces west, stump is in a slide area, bears S.60°W., 54.7 ft. (One of Eppstein's BTs, Ren. No. 67 in T.28-7) (See Comments in Ren. No. 144)
SE BT of Eppstein's looked for, not found.
Other BTs by Eppstein not looked for.

New BT - 12" madrone, bark scribed "T29S R6W S6 CS BT" bears S.43°E., 39.0'. Corner lies on a westerly slope.

2/6/90

1/4 Corner for Sections 18 and 19. 264
Set - A 5/8" iron rod and alum. cap.
new BT's - 16" maple bears N.45°W., 3.5 ft. scribed "1/4 S18 BT"
13" fir bears N.89°E., 26.7 ft. scribed "1/4 S18 BT"
20" fir bears S.14°E., 36.5 ft. scribed "1/4 S19 BT"
9" fir bears S.13°W., 28.7 ft scribed "1/4 S19 BT"
1958 Cad. BCIP bears N 89°16'25"W., 43.61 ft.

Section Corner for Sections 17,18,19, and 20. 265
Set - A 5/8" x 48" Iron rod with alum. cap at record bearing and dist. from original NW BT Ren #235
Found - A 28" oak bears N.27 1/2°W., 21.8 ft. reverse scribe OBT now stump.
New BT's - 10" fir bears N.15°W., 44.4 ft., scribed "S18 BT"
12" fir bears N.47°E., 42.2 ft., scribed "S17 BT"
10" fir bears S.65°E., 26.6 ft., scribed "S20 BT".
10" cedar bears S.39°W., 72.5 ft., scribed "S19 BT".
1958 Cad. BCIP bears S.88°11'06"W., 81.88 ft.

1/4 Section Corner for Sections 19 and 20. 266
Found - A 4" fir corner tree down scribe visible. See Ren #57
Chinquapin clump stump bears N.53° ., 17.8 ft.
12" fir stump bears S.52 1/2°E., 37.3 ft.
Set - A 5.8" x 48" iron rod and alum. cap.