

Douglas County Surveyor's Record of
Government Corners Renewed

T 29

T. S. R 6

R. W. W. M.

KOBE-CHAPMAN CO., EUGENE, ORE. 97501

274

Section Corner for Secs. 17, 18, 19 and 20

Found - A 2" dia. alum. cap on a 5/8" iron rod protruding 15" above ground. Ren. #265

2 1/2" dia. DCSO brass cap on a 1 1/2" I.P. protruding 6" above ground goes to corner position of 1958 BLM survey. Ren. #235

BLM recently destroyed scribing in BTs from 1958 BLM survey, WE axed out scribing in BTs established in Ren. #235.

Measurements taken from 1989 Alum. cap/I.R. (Ren. #265):

6" now 28" dia. 2 1/2 ft. high Oak stump with reverse illegible scribe mark and old axe marks visible on a previously opened blaze bears N.32 1/2°W., 21.8 ft. (Rec. N.27 1/2°W., 21.8 ft., it is possible wrong side of compass read in Ren. #265) Orig. BT

10" dia. D. fir scribing is visible on an unhealed single blaze "S18 BT" bears N.18 3/4°W., 43.6 ft. (Rec. N.15°W., 44.4 ft. Ren. #265)

12" dia. W. fir scribing is visible on an unhealed single blaze "S17 BT" bears N.45 1/2°E., 42.2 ft. (rec. N.47°E., 42.2 ft. Ren. No. 265)

10" dia. D. fir, scribing is visible on an unhealed single blaze "S20 BT" bears S.67°E., 26.6 ft. (Record S.65°E., 26.6 ft. Ren. #265)

10" dia. I. Cedar scribing is visible on an unhealed single blaze "S19 BT" bears S.40°W., 71.7 ft. (Record S.39°W., 72.5 ft. Ren. #265)

1 1/2" iron pipe with yellow plastic cap bears S.88 1/4°W., 81.9 ft. (agrees with record determined in Ren. No. 265, formly DCSO BC/IP from Ren. No. 235)

Note - Brass cap is sawed off of 1977 DCSO BC/IP. A yellow plastic cap is put in center of iron pipe marked "Doug. Co. Surveyor". I.P. now protrudes 4" above ground.

7/16/90

275

Section Corner for Secs. 9, 10, 15 and 16

Found - 3 1/4" BLM brass cap on a 2 1/2" O.D. Iron pipe protrudes 8" above ground. (1971 BLM)

3/4" I. Rod protrudes 10" above ground along West edge of BLM BC/IP (Set by RLS #934 in 1971) V.M. McLind - Ren. #218

13" now 15" dia. 3 ft. high split Alder stump with a partially healed double blaze, scribing visible "29S R6W S10" bears N.49°E., 158.4 ft. (agrees w/rec) Ren. No. 218

24" now 29" dia. B.Oak with a fully healed double blaze, bears S.41°E., 254.1 ft. (agrees w/rec.) Ren. No. 218

27" now 40" dia. down Oak with a partially healed double blaze scribing visible "T29S R6W S9" bears N.73°W., 155.6 ft. (Rec. N.73°W., 158.4 ft. possible slope measurement)

New Accessories:

PPL Power pole with tags "PPL 40T", "PPL SW97", "PPL B7909" bears N.33 1/2°E., 97.8 ft.

4" Maple double blazed and scribed "X BT" bears S.84 1/2°E., 46.9 ft.

6" Cedar double blazed and scribed "X BT" bears S.60 1/2°W., 111.7 ft.

Sec. cor for 20, 21, 28, & 29

Found - 3 1/4" dia. BLM brass cap on a 2 1/2" O.D. I.P. protruding 4" above ground. (1990 BLM pending resurvey)

DEPT. OF THE INTERIOR

T 29 S R 6 W

S20 | S21

S29 | S28

1990

BUR. OF LAND MANAGEMENT

I.P. noted in renewals not found

Accessories found -

All Orig BT's and BT's from renewals 80 & 82 now gone

BT's form ren #96

14" now 24" dia., 4' high D. Fir stump with a fully healed double blaze, bears S.89°W., 5.5' (agrees with rec.)

276

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
Terrie Franssen
July 16, 1990
C.S. 64/10

Douglas County
Surveyors Office
Randall Smith, Deputy
Stephen Flause
Aug. 11, 1992
C.S. File 64/32

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
6/20/94
C.S. 64/52