

Douglas County Surveyor's Record of
Government Corners Renewed

29 T. S. 7 R. W. W. M.

Ben B. Irving Deputy County Surveyor
Witnesses
N. E. Richardson
Frank Royer
Robinette
Bill Weichtman
May 1934. M 1-27
c.s. 37/17

N. E. Richardson
F. C. Frear
Wit.
P. D. Wolford
J. H. Wolford
N. E. Richardson
April 15, 1936.
C.S. 23/30

Surv.
N. E. Richardson
Wit.
M. E. Godfrey
L. S. Kershner

Ben B. Irving-Cnty. Surv.
A. R. Evans- Deputy Cnty. Surv.
M. E. Godfrey - Witness
Sept.-Oct. 1948

- SECTION CORNER BETWEEN 24 and 25.
Original B.T.s as described in Government field notes.
Set New Wood Post 4" x 4" x 36" -- S. 24-25 C.S. **RENEWED, SEE CORNER NO. #114** 39
- SECTION CORNER BETWEEN 25 and 36.
Original B.T.s as described in Government field notes.
Set Fir Post 4" x 4" x 36" -- S. 25-36 C.S. **RENEWED, SEE CORNER NO. #110** 40
- SECTION CORNER BETWEEN 25, 30, 36 and 31.
Original tree for corner in place but badly rotted.
Original B.T.s as described in Government field notes.
Set 4" x 4" x 36" Fir Post. (see c.s. 37/17 & M 1-27 for trees) **SEE CORNER NO. 53+ 95** 41
c.s. 4/24 Feb 1952 Boyer Corner. 1/23/52
- SECTION CORNER BETWEEN 25 and 30. E. LINE OF TWP.
Rock as described in Government Field Notes knocked out.
One Original E.T. down, other okay. Reset original Rock.
Reset O.B.T.
A 14" Fir S. 80° E., 16 lks.
A 36" Fir S. 78° W., 23 lks. New B.T. **RENEWED, SEE CORNER NO. #106** 42
- CLOSING CORNER -- SECTION CORNER BETWEEN 24 and 25.
Rock as described in Government Field Notes. One
Original B.T. stump remains. No new trees suitable for
marking close. **RENEWED, SEE CORNER NO. 107** 43
- CORNER SECTION BETWEEN 25 and 26.
Post rotted off. Original B.T.s as described in original
field notes. Set Fir Post 4" x 4" x 36". **NOT FOUND JMP. 10/69 49/139** 44
C.S. FILE
- N.W. CORNER OF JNO. BYRON D.L.C. 38.
Found 1 old B.T., marked new trees and drove a 1" x 30"
Iron Bar for corner from which
A 12" Fir S. 56° 45' E., 5.0 ft.
A 12" Fir N. 83° 00' W., 8.9 ft.
A 36" Cedar S. 26° 30' W., 16 ft.
A 14" White Oak N. 20° W., 101.6 ft. **RENEWED, SEE CORNER NO. #11+90** 45
- CORNER BETWEEN SECTIONS 8, 9, 16, and 17.
Renewed from old Bearpaw trees. **RENEWED, SEE CORNER NO. 62** 46

 - A 24" Cedar S. 38° 15' W., 133.6 ft.
 - A 24" Fir N. 50° 45' W., 89.6 ft.
 - A 20" White Oak S. 124° E., 172.9 ft. Old B.T. in good condition. **Ren. #35**
- COR. SEC. 7 W Bdy.
Found and Iron Pipe with a brass cap, the O. B.T. bears
N 47° E, 33 lks. **SEE CORNER NO. 98** 47

 - Set new bearing trees
 - A Fir 14" diam., bears N 72 1/2° E 30.3 ft. dist.
 - A Fir 14" diam., bears S 50° E 46.2 ft. dist.
- SEC. COR. 31-32-6-5 (N bdy. T 29) July 29, 1947 **SEE CORNER NO. 78** 48
Identified from O. B. T.s
Laurel XXXXXX' N 69° 55' W 16.5 ft., broken and rotting
48" Fir N 21° 10' E 11.9 ft., down, scribe marks legible. **#142**
Maple, B T under log, down
B.T. S 28° E, broken off, blaze and scribe visible.
Fir N 24° E 52 ft., standing, blaze not chopped out.
O.B.T. Laurel S 4° W, down, scribe marks visible.
Oak, S 43° W down and rotting.
New B. T. - Set 6x8x20 inch rock lying flat, x on side, set on end and new mound of rock.
30" Fir S 83° E 78.2 ft.
6" Fir S 80° W 21.7 ft.
8" Fir S 20° W 38.9 ft.
24" Fir N 32° E 54.4 ft.
- COR. 32-5 (N bdy. Sec. 5) **SEE ALSO #21 & #79** 49
Found sandstone 8"x12"x4" in mound, mkd. 1/4 S. 16" Laurel B. T. alive and marked 1/4 S, standing, bears S 27° 15' W 11.5 ft. 10" Laurel, dead and down bears N 88° 15' E 20.0 ft., stump bears N 64° 15' E 18.0 ft. - **Ren. #21**
Scribed New B.T. 12" Laurel N 84° W 30.9 ft., C.S.B.T. **99**

Ed 8/21/52
S. 9/12/52
Done by
c.s. 62/11