

Douglas County Surveyor's Record of
Government Corners Renewed

29

T. S.

7

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97198

Township corner to secs. 36, 31, 6 & 1, Twps. 29 & 30., Rgs. 6 & 7-W. **80**
Point for corner determined by O. B. Ts. **CORNER NO. 105**
A 24 inch W. O., bears N73E., 14.5 feet dist., - I rescribe S 31 B. T.
A 20 inch W. O., bears S20E., 33.0 feet dist., - I rescribe S 6 B. T.
A 44 inch Y. Pine windfall bears S.19°W., 30.4 feet dist. - O. B. T.
At corner point set 2 inch x 36 inch solid steel bolt,
from which:
A 21 inch W. O., bears N49W., 177.0 feet dist., mkd. S 36 T29S, R7W., B.T.
A 22 inch La. bears N4E., 55.0 feet distant mkd. S 31, T29S, R6W., B. T.
A 14 inch W. O., bears S33E., 30.5 feet dist., mkd. S 6, T30S, R6W., B.T.
An old fence runs N - S.

John H. Markham Jr.
Work done for Stomar
Lumber Co.
Sept. 17, 1956
C. S. File No. 42/191.

$\frac{1}{4}$ corner to sec. 35, T29S, R7W., and Sec. 2, T30S, R7W. **81**
Point for corner determined by O. B. T.:
A 14 inch La. bears S.60°E., 30.4 feet dist. - found scribe.
At corner point set 1 inch x 36 inch truck axle with flange up,
from which:
A 42 inch La. bears N.50°E., 42.5 feet dist. mkd. $\frac{1}{4}$ S 35 T29S, R7W.,
2880 B. T.
A 9 inch Fir bears S18E., 41.8 feet dist. mkd. $\frac{1}{4}$ S 2 B. T.
Old fences run N - S - W from corner.
Fence corner bears S.46°E., 17.3 feet distant.

Section corner to secs. 35 & 36, T29S, R7W., and secs. 1 & 2, T30S, R7W. **82**
Point for corner determined by O. B. T.:
A 24 inch La. bears S68E., 27.7 feet dist. - found scribe.
At corner point set $\frac{3}{4}$ inch x 30 inch iron pipe, **CORNER NO. #258**
from which:
An 18 inch La. bears S86W., 34.0 feet dist. mkd. S 2, T30S, R7W., B.T.
A 30 inch La. bears N21W., 35.0 feet dist. mkd. S 35, T29S, R7W., B.T.
A 15 inch La. bears N39E., 36.0 feet dist. mkd. S 36, T29S, R7W., B. T.
A 35 inch La. bears S24E., 45.0 feet dist. mkd. S 1, T30S, R7W., W.M., B.T.

John H. Markham Jr.
Work done for Stomar Lumber Co.
April - September, 1956.
C. S. File No. 42/192.

$\frac{1}{4}$ corner to sec. 36, T29S, R7W., and sec. 1, T30S, R7W. **83**
Point for corner determined by O. B. T.: **SEE ALSO REN #51**
A 67 inch Pine stump bears N40E., 141.0 feet dist. - found scribe.
At corner point set 2 inch x 16 inch solid steel shaft,
from which:
An 8 inch W. O., bears N23W., 38.0 feet dist. mkd. $\frac{1}{4}$ S 36 B.T.
A 15 inch Cedar, bears S18E., 39.6 feet dist. mkd. $\frac{1}{4}$ S S 1 B.T.
Road bears East 230.0 feet.

Section corner to secs. 16, 17, 20 and 21. **84**
This corner was renewed in 1954 by County Surveyor. I find the N.E. BT **#232**
uprooted and Brass Cap lying 50 feet downhill. All other B. T.s **Ren #64**
uprooted except the N.W. BT which is still standing which I use to
replace the Brass Cap.
Blaze and scribe new B. T.s:
16 inch R. Fir, S.38°E., 62.0 feet, mkd. T 29 S, R 7 W., S 21 CS BT.
5 inch W. Fir, N.24°W., 41.2 feet, mkd. S 17 CS BT.

James W. Byron,
Dep. Co. Surveyor.
March 22, 1957.
C. S. File No.
47/165.