

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 29 S. T. S. R. 7 W. R.W.W.M.

HOKE-CHAPMAN CO., EUGENE, ORE. 21881

James W. Byron, Deputy County Surveyor  
Dale McFarland and John Powell  
May 1962  
C. S. File No. 49/139

1/4 Corner to Sections 32 and 33. 127  
Found - Brass Cap at Corner & N.E. BT. N.W. BT. not found.  
New BT: 13" R. Fir bears N. 80° W. 9.0 ft. scribed 1/4 S32 CS BT.

Section Corner to Sections 20 - 21 - 28 - 29. 128  
Found - Brass Cap at Corner & one BT. standing, a 7" R. Fir S. 50 1/2° W. 15.0 ft.  
New BT's: 10" R. Fir N. 4° W. 56.6 ft. scribed S20 T29SR7W CS BT. REN. No. 65  
12" R. Fir bears N. 56 1/2° E. 88.0 ft. scribed S21 T29S R7W CS BT.  
No trees near to S. E.

1/4 Corner to Sections 31 and 32. 129  
Found - Brass Cap at Corner. B. Oak to S.E. down. Pine to S.W., now stump,  
shows small scribe mark at top of cut.  
New BT's: 24" Laurel bears S. 65 1/2° E. 45.6 ft. scribed 1/4 S32 CS BT.  
5" Chinquipin bears N. 64° W. 14.0 ft. scribed 1/4 S31 CS BT.

Section Corner to Sections 29 - 30 - 32 - 31. 130  
Found - Brass Cap at Corner. All BT's. gone. Corner checks call to old road.  
This area cleared and burned years ago.  
New BT's: 5" Fir bears N. 14° W. 13.5 ft. scribed S30 CS BT T29  
8" Laurel bears N. 53° E. 10.7 ft. scribed S29 CS BT. T29S R7W  
7" R. Fir bears S. 69° E. 25.5 ft. scribed S32 CS BT.  
5" Laurel bears S. 88° W. 22.8 ft. scribed S31 CS BT.

Section Corner to Sections 31 and 32 only. 131  
Found - Brass Cap at Corner. 12", now 20" Fir S31/S32 N. 70° E. 54.1 ft., alive  
and in good condition.  
12", now 18" Maple N. 4 1/2° W. 28.4 ft. Center Rotted, I rescribe this  
BT S31 CS BT.

Corner S31/S32 T29 1/2 S R7W 132  
Found - 10", now down, 14" Fir S. 53° W. 27.1 ft., shows good scribing "S".  
Dogwood to S.E. not found but we do find 12" Yewood, checks  
bearing & distance to S.E. BT.  
Note - Brass Cap set for Corner not found. Falls in old cat road &  
about 10 feet south of creek channel.  
New BT's: 12" Yewood bears S. 66° E. 23.2 ft. scribed S32 T29 1/2 S R7W CS BT.  
18" W. Fir bears S. 81 1/2° W. 79.7 ft. scribed S31 T29 1/2 S R7W CS BT.

Renew AP <sup>3</sup> #1 Tr. 48. 133  
Found <sup>1924</sup> Brass Cap at Cor. & BT. as recorded, now 36" W. Oak N. 79 1/2° E.  
106.9 ft., center rotted. We rescribe TR. 48 AP <sup>3</sup> CS BT.  
\*3 Per research done 6/94 D.C.S.-O.

West 1/4 Corner to Section 6 only. 134  
Found - 1924 Brass Cap at Cor. & Both BT's.  
We do not find Corner Stone. See #10

West 1/4 Corner to Section 18 only. 135  
Found - Brass Cap at Corner & N.E. BT. S.E. BT., now stump hole only.  
New BT: 7" R. Fir bears S. 48° E. 12.6 ft. scribed 1/4 S18 CS BT.

Renew Tr. 50 136  
AP 3 T29S R8W  
AP 2  
Tr. 51 Found - Brass Cap at Corner & N.E. BT., now snag, shows  
S.E. BT. Gone good scar.  
New BT's: 8" E. Fir N. 12° E. 28.7 ft. scribed AP 3 Tr 50 CS BT.  
R. Fir S. 16° E. 10.9 ft. scribed AP 2 Tr 51 CS BT.

RE RENEWED SEE CORNER NO. #219