

Douglas County Surveyor's Record of
Government Corners Renewed

29. T. S. 7. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21861

East $\frac{1}{4}$ Corner to Section 13 only, T.29S. R8W. 137
Found - Brass Cap at Corner & S.W. BT., shows good scar.
Find Low Cut Stump that checks N. 87° W., not S. 87° W. #
New BT: 9" R. Fir bears N. 87° W. 16.0 ft. scribed $\frac{1}{4}$ S13 CS BT. 222

Renew Corner to Section 18 and 19 only, T29-7W. 138
Found - Brass Cap at Corner & now 16" Yewood, shows good scribing
on rotted face bears S. 3 $\frac{1}{2}$ ° E. 7.9 ft., not S. 70° E.
N. E. Bearing Tree now stump
New BT: Rescribe, now 16" Yewood S. 3 $\frac{1}{2}$ ° E. 7.9 ft. S19 T29S R7W CS BT.
6" Fir bears N. 86° E. 26.7 ft. scribed S18 CS BT.

Renew

S 7	T29-7W.
S18	Found - Brass Cap at Corner. N.E. BT. shows scrib-

ing, now dead. S. E. BT. O.K., shows good scar.
New BT: 19" R. Fir N. 49° E. 17.7 ft. scribed S 7 T29S R7W CS BT. 139

Renew

S12	Found - Brass Cap at Corner & Both BT's.
S13	S.W. BT. in poor condition. #223

T29-8W New BT: 19" Pine bears S. 62° W. 10.3 ft. scribed S13 T
T29S R8W CS BT. 140

Cor. REFERENCED 11-2-81 by G.E. QUIBELL
DUE TO PENDING ROAD WORK... SEE C.S. 59/30

Renew Corner to

S 6	T29S R7W
S 7	Found - Brass Cap at Corner. N.E. BT. now stump, shows old face.

S. E. BT. O.K. & at edge of roadway. - ~~REN. NO. 30~~
New BT: 10" R. Fir bears S. 22° E. 50.8 ft. scribed S7 T29S R7W CS
Notice County Road 16.0 ft. South of Corner, Also 1" I.P.
bears S. 1° W. 47.0 ft. 141

Renew Corner

S 1	T29-8W
S12	Found - Brass Cap at Corner & Both BT's. now stumps.

N.W. BT. shows good scribing.
New BT's: 10" R. Fir bears S. 21 $\frac{1}{2}$ ° E. 23.3 ft. scribed S7 T29SR7WCSBT.
13" B. Oak bears N. 55° E. 21.4 ft. scribed S7 T29SR7WCSBT.
Fence Corner Thus:



$\frac{1}{4}$ Corner to Section 19 and 30. 143
Found - Brass Cap at Corner. S.W. BT. now snag.
N.W. BT. shows good scar.
New BT: 14" W. Fir S. 26° W. 30.6 ft. scribed $\frac{1}{4}$ S30 CS BT.

$\frac{1}{4}$ Corner to Sections 19 and 20. 144
Count - Brass Cap at Corner & on North Bank of Creek. #215
Both 1924 BT's gone. We find 24" Fir Stump that checks
bearing & distance for Orig. S.W. BT.
New BT: 13" R. Fir bears N. 16° W. 34.0 ft. scribed $\frac{1}{4}$ S19 CS BT.

Renew

S25	T29S
R8W	S36
	R7W

Found - Orig. 40", now 44" Fir N. 59° W. 108.2 ft., shows good scar.
Orig. S.W. BT. down. Also find Brass Cap at corner
& at East edge of 4.0 ft. down BT.
New BT's: 10" Cedar bears N. 37° W. 32.5 ft. scribed S25 T29S R8W CS BT.
7" Fir bears S. 28° W. 6.5 ft. scribed S36 CS BT. 145

Renew W. Exterior L. Corner to Claim 46. 146
Found - 2" I.P. at Corner & now 27" Fir Stump bears N. 86° E. 121.0 ft.
New BT: 21" Pine bears N. 91° E. 89.4 ft. scribed W Ex L Cl 46 CS BT.

James W. Hyron, Deputy County Surveyor
Dale McFarland and John Powell
May and June 1962
C. S. File No. 49/139

RE-RENEWED, SEE CORNER NO. #270

RE-RENEWED, SEE CORNER NO. #215

RE-RENEWED, SEE CORNER NO. #257