

Douglas County Surveyor's Record of
Government Corners Renewed

T. 29 S. T. S. R. 7 W. R. W. W. M.

HOKE-CHAPMAN CO., EUGENE, ORE. 21881

FD. OK
10/18/84
H. J. JAHNKE
12/97-54

East $\frac{1}{4}$ Corner to Section 22. 22* 156
Found - Brass Cap set in 1924 & BT's. as follows:
16" Fir S.23°W. 72 ft. (stump)
10" Fir N.56°W. 42 ft. (windfall, scribing visible)
New BT's: 7" W. Fir N.71°W. 27.6 ft. mkd: E $\frac{1}{4}$ S22 CS BT.
14" D. Fir South 28.5 ft. mkd: E $\frac{1}{4}$ S22 CS BT.

West $\frac{1}{4}$ Corner to Section 23. 157
Found - 20" Fir, now 27", N.76°E. 39 ft.
36" Fir S.36°E. 26 ft. (down) chopped open & found scribing.
Did not find Brass Cap set in 1924, as corner falls in small ravine that has been sliding.
Set - Brass Cap Mkd: County Surveyor's Office, 1962 T29S R7W $\frac{1}{4}$ S23
New BT: 20" Maple N.18°E. 26.5 ft. Mkd: W $\frac{1}{4}$ S23 CS BT.

$\frac{1}{4}$ Corner to Sections 18 and 19. 158
Found - Brass Cap at Corner & N.E. BT., shows good scribing.
S. E. BT. now down.
New BT: 8" R. Fir bears N.85°W. 10.6 ft. scribed $\frac{1}{4}$ S19 CS BT.
FD. OK. L. MANREAN, Co. Surveyor's Off. 2/2/77 C.S. 59/29

Corner to Sections 32 and 33 only. 159
Found - Brass Cap set in 1924 & Fir Stump bears N.72°W. 10.6 ft.
Cat Road where Laurel BT. would have been. - REN. No 32
New BT's: 13" Fir N.34 $\frac{1}{2}$ °E. 57.4 ft. scribed T29S R7W S33 CS BT.
15" Fir N.28°W. 88.8 ft. scribed T29S R7W S32 CS BT.

North $\frac{1}{4}$ Corner to Section 33, T29 $\frac{1}{2}$ S R7W. 160
Found - Brass Cap set in 1924. S.E. BT. is a rotted stump, scribing ("S 33 T29 $\frac{1}{2}$ BT) visible.
S.W. BT. down, shows good scar.
New BT's: 11" Fir S.42°W. 28.5 ft. scribed N $\frac{1}{4}$ S33 CS BT.
8" Cedar S.28°E. 48.4 ft. scribed N $\frac{1}{4}$ S33 CS BT.

South $\frac{1}{4}$ Section 32 only, T29-7W. 161
Found - Brass Cap set in 1924 & 8" R. Fir scribed by B. Irving, 1954, now 5' snag, scribing visible. REN. No. 68
10" R. Fir N.51°E. 12.0 ft., O.K.
New BT: 7" R. Fir N.62°W. 20.8 ft. scribed S $\frac{1}{4}$ S32 CS BT.

North $\frac{1}{4}$ Section 32 only, T29 $\frac{1}{2}$ S R7W. 162
Found - Brass Cap set in 1924 & BT's. as follows:
14" W. Fir S. 0°30'E. 90.0 ft.
10" R. Fir (snag) N.83°E. 93.4 ft.
New BT: 7" Cedar S.53°E. 42.2 ft. scribed N $\frac{1}{4}$ S32 CS BT.

$\frac{1}{4}$ Corner to Sections 7 and 8. 163
Found - Brass Cap at Corner & 8" under surface. S.E. BT., now stump.
S.W. BT. is o.k., shows good scars. REN. No. 88
Note - 28" W.O. bears S.50°E. 156.0 ft. We do not scribe this tree.
Set - $\frac{3}{4}$ " I. Rod South 23.8 ft. from corner & under East-West Fence.

Witness Point in Section 35, T29S R7W. 164
(Ford's old Sec. Cor. renewed 1924 Survey $\frac{35}{21}$ | $\frac{36}{1}$)
Found - Orig., now 30" Fir S.55°W. 6.6 ft., shows old scar, also bark scribing "WP", 1924.
Both 1924 BT's. N.W. BT., down.
Open N.E. BT. & find good scribing "BT".
We do not find Brass Cap at corner. There has been no logging in this area nor other activity to remove or destroy Brass Cap.
Set - Brass Cap at Cor. & Mkd: County Surveyor's Office, 1962
W P S35 T29S R7W
Note - Corner is on East slope & about 100 ft. West of Draw.

James W. Byron, Deputy County Surveyor
Dale McFarland and John Powell
June 1962
C. S. File No. 49/139

FD. OK 12/90
M III - 17

None for Victoria.
Ask FRITZ FOR
FOR I. D. #