

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 29 S. T. S. R. 7 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Marvin C.  
Ramsey  
C.S. File 51/258

(continued)  $\frac{1}{4}$  Cor. Sec. 1, T29-7 & Sec. 6, T29-6W.  
from which new Bearing Trees:  
18" B.Oak bears N.68 $\frac{1}{2}$ °E. 317 lks. Mkd:  $\frac{1}{4}$  S6 RS4.04 BT.  
6" Madrona bears S.31 $\frac{1}{2}$ °W. 192 lks. Mkd:  $\frac{1}{4}$  S1 RS4.04 BT.  
81 $\frac{1}{2}$ ° 7/93 NW

181  
~~181~~

(#182 Not used)

183

Corner to Sections 22 and 27 only.  $\frac{S22}{S27}$   
Found - Brass Cap, GLO 1924, at Corner & 30" R.Fir S.70°W. 43.6 ft.,  
shows good scar. See Ren. #27  
Rotted Stump of Northwest BT.  
New BT: 6" R.Fir bears N.54°W. 11.4 ft. scribed S22 CS BT.

James W. Byron, Deputy  
Mike Darby & J. Halterman  
Nov. 27, 1963  
C. S. File No. 49/139

184

Corner to Sections 23 and 26 $\frac{1}{2}$  only.  $\frac{S23}{S26\frac{1}{2}}$   
Found - Brass Cap, GLO 1924, at Corner. See Ren #121  
All BT's., now dead, burned at the time house burned.  
New BT's: Cedar bears S.73°E. 70.0 ft. scribed S26 $\frac{1}{2}$  T29S R7W CS BT.  
7" Pine bears N.59°E. 83.0 ft. scribed S23 CS BT.

Bruce R. Rogers, Deputy  
For C. & D. Lumber Co.  
April 20, 1965  
C. S. 54/2 M 29 - 48

Center  $\frac{1}{4}$  Corner to Section 15.  
Set - Brass Cap at Center  $\frac{1}{4}$  Cor. Mkd: County Surveyor's Office, 1965  
Center of Sec. 15  
T29S. R7W.  
New BT: 13" D. Fir S. 35° E. 172.5 ft. Mkd: CS 15 CS BT.  
15" D. Fir S. 17° E., 158.2 ft. Mkd: CS 15 CS BT.  
**Note:** The position for the center  $\frac{1}{4}$  corner determined after running a closed traverse, beginning at the N $\frac{1}{4}$  corner to the S $\frac{1}{4}$  corner to the E $\frac{1}{4}$  corner to the N $\frac{1}{4}$  corner and back to the N $\frac{1}{4}$  corner.

**RE-REVIEWED SEE CORNER NO. #267**

185

MICROFILM TO HERE 10/67

186

$\frac{1}{4}$  Corner to Sections 2 and 1.  
Found - Remains of old fence corner at corner point with only traces of fences N. & E.  
30" Fir, now 38" sawed stump, N.30°E. 3.0 ft., "CSBT" bark scribe in poor condition. See Ren. #19.  
18" Fir, now 24" sawed stump, too low, no scribe found, N.86°W. 27.5 ft. (Rec. S.86°W).  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1969 T. 29 S. R. 7 W.  $\frac{1}{4}$  S 2 | S 1  
New BT's: 28" D.Fir N. 31° E. 58.5 ft. mkd: " $\frac{1}{4}$  S 1 CS BT".  
13" D.Fir N. 53° W. 53.1 ft. mkd: " $\frac{1}{4}$  S 2 CSBT".  
This corner lies on steep southerly slope very sparsely covered with D. Fir and dense brush. 3/6/69

Vernon "Ray" Tracy  
Frank Jones & V.Perron  
March 6, 1969  
Q.S.File No. 49/139

Section Corner to Secs. 35 & 36, T28-7 & Secs. 1 & 2, T29-7. 187  
Found - BT's. as recorded by Cole, C.S. File 6/33, as follows:  
14", now 16" Fir, N.72 $\frac{1}{2}$ °E. 17.0 ft.(face) bark scribed "S36 CS BT".  
We Rescribe: T28S R7W S36 CS BT".  
10", now 13" Fir Stump, S.3 $\frac{1}{2}$ °W. 12.0 ft.(Face) bark scribed "S1 CS BT".  
10", now 13" Fir Stump, S.65°W. 18.0 ft.(face) No scribe fd., cut offlow  
12", now 16" Fir, N.25°W. 16.2 ft.(face) bark scribed "S35 CS BT".  
We Rescribe: "T28S R7W S35 CS BT"  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1969 T28S R7W  $\frac{S 35}{S 2}$  |  $\frac{S 36}{S 1}$   
New BT's: 12" D.Fir S.55°E. 21.9 ft.(center) mkd: T29S R7W S1 CS BT.  
13" D.Fir S.71°W. 77.1 ft.(center) mkd: T29S R7W S2 CS BT.  
The only remains of original BT's. were down & out of place, no scribe.  
Fence Corner bears N. 15° E. 5.5 ft., fence E. & N.

James W. Byron, Co. Surveyor  
V. "Ray" Tracy & Crew  
March, 1969  
C. S. File No. 54/83  
Map File M 37 - 44