

Douglas County Surveyor's Record of
Government Corners Renewed

T 29 T. S. R 7 R.W.W.M.

FOKE-CHAPMAN CO., EUGENE, ORE. 21881

230

Section Corner For Secs. 7, 8, 18 and 17.

Found - 1924 GLO brass cap firmly set and properly stamped.

From Which:

A 10" Fir, now and 11" Stump bears S.88 1/2°E., 47.5 ft. scribing "7W S17 BT" visible on rotted face.

A 30" Fir, now a 36" stump bears S.67°W., 26.4 ft. We open and find scribing "R7W visible.

A 10" now 18" D. Fir bears S.59°E., 17.5 ft. healthy and shows double blaze. Ren. #153

A 4" now 12" D. Fir bears N.40 1/2°E., 21.6 ft. Tree is alive and shows faint double blaze. Ren. #153

A 9" now 15" D. Fir bears S.9°W., 33.5 ft. Tree is alive and shows good double blaze. Ren. #153

We find no other evidence.

New BT's - A 7" D. Fir bears N.65°W., 28.7 ft. mkd. "T29S R7W S7 CS BT" in a double blaze.

1/13/77

231

1/4 Corner for Secs. 7 and 18.

See Renewals #87 and 207 and 1924 U.S.G.L.O. Resurvey.

Found - The 1924 U.S. General Land Office brass cap which agrees with the position of the bearing tree established by Baughman in 1973. Ren. #207. However, we find the found 1924 B. Cap in disagreement with the remains of the orig. NE bearing tree, the BT's marked in 1924 and the remaining BT marked by Byron in 1957. Ren. #87

At a point which satisfies the relationships of the found evidence,

We Set - 1924 U.S.G.L.O. brass cap which is a 1" x 36" I.P. 30" in the ground with brass cap attached properly marked. We Add the markings "CS 1977" to the brass cap.

From Which:

A 5/8" x 30" I. Rod with alum. cap inscribed "Douglas Co. Surveyor" bears S.6°E., 3.4 ft.

Note: This was the found location of the 1924 brass cap.

The remains of the orig. NE BT, a down & rotten black Oak with evidence of opening made in 1957 by Byron, no markings found, bears N.40°E., 19.1 ft. (Rec. N.40°E., 19.1 ft.).

A 16" Fir, now a 22" stump marked in 1924, with burnt face exposed, no markings found, bears N.8°W., 43.6 ft.

An 18" Fir, now a 24" stump marked in 1924, with burnt face exposed, no markings found, bears S.41°E., 29.7 ft. (Rec. S.43°E., 29.7 ft.)

A 12" now 15" D. Fir, alive and well-healed bears S.65°W., 52.2 ft. Ren. #87

Byron's NW BT a 30" B. Oak is down, face apparently buried.

And a BT established by Baughman, Ren. #207, a 7" D. Fir now a 7" P. Pine with illegible scribing visible on partially healed blaze bears S.2°W., 5.6 ft. (Rec. S.12 1/2°W., 2.2 ft.)

1/26/77

232

Section Corner for Secs. 16, 17, 20 and 21.

Found - 1954 County Surveyors Brass cap. Ren. #64

1957 U.S. GLO brass cap properly marked.

An Orig. 10" R. Fir (now 42" sawed stump) bears N.20°E., 44.9 ft. No visible scribing on prev. opened blaze.

The SE, NW and SW orig. BT's not found.

Found - Per Ren. #64

A 10" R. Fir now a down 10" Fir bears N.52°E., 1 ft. partial scribing visible

A 10" R. Fir now a 13" tipped out stump bears S.58°E., 18.7 ft. No scribing visible.

A 10" R. Fir now a 13" bears N.75°W., 14.5 ft. with healed over double blaze.

A 8" R. Fir now a 9" Tipped out stump bears S.22°W., 25.8 ft. No visible scribing.

Two unrecorded BT's per Ren. #64 not found.

Found - Per Ren. #84

A 16" R. Fir now a 18" Down Fir bears S.38°E., 62 ft. with healed over double blaze.

A 5" W. Fir (now 16") bears N.24°W., 41.2 ft. with healed double blaze.

CONT. NEXT PAGE

Gary L. Langlitz, Larry E. Monrean, Douglas Co. Surveyors Office
P. L. Earle, K. Cheney, A. Vic Cangie, Mike Tompkins
Jan. 1977
C.S. 59/29

FD. OK 12/90 M111-17

L. E. Monrean
K. Cheney
P. Earle
Doug. Co. Surveyors
Office
Jan. 12, 1977
C.S. 59/29

FD. OK 6/92
GLANG M115-30