

**Douglas County Surveyor's Record of  
Government Corners Renewed**

T 29

T. S.

R 7

R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 21001

274

1/4 Corner for Sec. 4 and Sec. 33 of T.28-7

Found - No original post found.

A 6" x 12" quartz rock (origin unknown) now 13" x 8" x 6" quartz rock as used in 1957 survey by A. Boyer and 1973 survey by G. Baughman, M 12 - 72 and RM 2 - 46 respectively, Douglas County records. No marks on stone.

A 40" diam. B. Oak with previously cut out blaze, rotted center bears S.25°E., 106.3 ft. dist. (Rec. brg. & dist.) This tree was referred to as the orig. 6" B. Oak in the above mentioned surveys. No visible scribe found.

Set - A 1" x 30" iron pipe with brass cap stamped "Douglas County Surveyor T28S 1/4 S33 R7W S4 T29S 1982", at record bearing and distance from 40" oak, which is the position of found stone, protruding 10" above the ground with quartz rock along south side of cap. Set this corner to perpetuate a used corner position.

New Accessories:

A 13" diam. B. Oak scribed "1/4 S4 CS BT" in a double blaze bears S.11 3/4°W., 128.1 ft. dist.

A 5/8" x 30" iron rod with aluminum cap stamped "BO 1" bears N.43°W., 32.95 ft. dist. Set flush with ground. Cap stamped Doug. Co. Surveyor.

A 5/8" x 30" iron rod with alum. cap stamped "BO 2" bears N.62°E., 35.60 ft. dist. Set flush with ground. Cap also stamped Doug. Co. Surveyor.

No other trees within reasonable range.

Corner falls on a west slope 0.9 ft. west of a N-S fence

8/24/82

Karen Reed, Deputy  
Doug. Co. Surveyors  
Office  
Terrie Plouff  
Aug. 24, 1982  
C.S. 62/1

Center 1/4 Corner of Sec. 36.

275

Set - 1 1/2" x 36" Alum. Pipe with 3 3/4" Alum. Cap, 34" in ground, mkd: Oregon State Department of Forestry.

New BTs - 8" fir bears S.9°W., 31.2-ft. w/yellow metal location poster.  
13" fir bears N.36 1/2°W., 24.1-ft.

Access. - White painted cedar post bears N.21°E., 3.4-ft. 12/82

Lloyd D. Smith  
PLS #1101  
For: State of OR,  
Dept. of Forest.  
Dec. 13, 1982  
M 93 - 45

276

Township corner, Sec. 36; Sec. 31, T.29-6; Sec. 1, T.30-7; Sec. 6, T.30-6

Found - 1962 Doug. County Surveyors brass cap properly marked and firmly set. Ren. #105

1968 BLM brass cap per resurvey properly marked and firmly set with what appears to be the original corner stone buried alongside. DCSO brass cap bears S.23 1/2°E., 1.65 ft. from BLM cap.

Found all accessories as described in 1968 resurvey and Lloyd Smith survey. (M 93-45)

My measurements to the two remaining original BTs from each of the brass caps plus faint notches on all four edges of the found stone cause me to accept the position of the BLM brass cap as the proper corner location. I then cut the DCSO brass cap off and drive a yellow nylon cap inside the remaining 1" iron pipe. Cap marked "Doug. Co. Surveyor".

1/28/83

Westerly NW corner for DLS 46

277

Found - 2" I.P. firmly set and protruding 5 in. from ground. Pipe leans slightly north. This monument possibly set by Boyer in 1943. See C.S. 31/15.

No trace of original BTs.

A triple trunk D. fir approx. 50" in overall diam. with a healed single blaze bears S.88°E., 121.0 ft. (Rec. N.89°E., Ren. #69; N.86 1/2°E., Ren. #146; and S.87°E., Ren. #257)

A 21" DBH now a 26" DBH P. pine with a healed double blaze is now dead, fallen and dislocated from stump hole. Stump hole bears N.31°E., 89.4 ft. Ren. #146 and #257.

A 12" DBH now a 14" DBH P. pine with a healed double blaze bears N.53°W., 14.9 ft. Ren. 257.

New Accessory:

A 5/8" diam. Iron rod with an alum. cap marked "Douglas Co. Rd. Dpt. R/W .30" firmly set and protruding 4 inches from ground bears N.59 3/4°E., 91.4 ft.

Note: Monument is located approx. 400 ft. NW of upper Ollala Co. Rd. #38 and gravelled access road to Berry Creek Dam structure (Ben B. Irving Reservoir).

Fd OK  
BY HELEN SWANER  
4/92 1992-0035

Gregory Quibell  
Deputy, Doug. Co.  
Surveyors Office  
John Powell -  
Randy Smith  
January 28, 1983  
C.S. 62/7

Larry E. Monrean,  
Deputy, Doug. Co.  
Surveyors Office  
Field Crew:  
S. Flause and R.  
Smith  
June 7, 1984  
C.S. 62/18