

Douglas County Surveyor's Record of
Government Corners Renewed

T. 29 T. S. R. 7 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 91891

James Artman Surveying
For: Keller Lumber &
Clarence Beeman
December 1990
M 111 - 17

1/4 Corner for sections 5 and 8 294
Found: 22" black oak bears S 77 1/2° E. 7.9 ft. reverse scribes "1/4 S"
on back of chopped and rotted face (original B.T.)
Set: 5/8" X 30" iron rod with 1" cap marked "Artman RLS 2268"
New BT's 7" cedar bears N.18° E., 17.2 ft. (scribed 1/4 S5 BT)
5" cedar bears S 19° E., 21.1 ft. (scribed 1/4 S8 BT)
10" D. fir bears S 6° W., 24.6 ft. (scribed 1/4 S8 BT)
7" pine bears N.89° W. 36.6 ft. (scribed 1/4 S5 BT)
Corner falls 15 ft. south of an E-W fence line.

Dec. 1990

Center 1/4 for section 8. 295
Set: 5/8" X 30" iron rod with 1" cap marked "Artman RLS 2268"
New BT's 18" oak (in 36" cluster) bears N.86° E., 111.3' ft, with
alum. tag marked "Artman RLS 2268" in side and center.
30" pine bears S.28° E., 63.2 ft., with alum. tag marked
"Artman RLS 2268" in side and center.
P. pole no. 1B-3 bears S.73° W., 33.3 ft.
IL
N.W. corner of cinder block chimney bears S.18° E., 104.1 ft.
Corner falls 6' north of E-W fence line, iron rod buried 8".

Dec. 1990

Section Corner for 34 and 35; 3 & 2 of T.30-7 296
Found - A 3 1/2" dia. 1924 GLO brass cap on a 3" O.D. Iron pipe protruding
14" above ground.
16" now 27" dia. D.Fir with a fully healed double blaze, bears
N.52 1/2° E., 44.9 ft. (Rec. N.54° E., 44.9 ft.) 1924 GLO
1924 GLO S.75° E., 27.7 ft. BT is gone.
8" now 11" dia. 2 ft. high Cedar stump, tree is down along
side stump, scribing visible "R7" bears S.26° W., 13.9 ft.
(agrees with record) 1924 BT.
30" now 36" dia. D.Fir with a fully healed double blaze, bears
N.27 1/2° W., 56.8 ft. (agrees with record) 1924 BT
6" now down and rotting 6" D.Fir with illegible scribing visible,
bears N.34° E., 25.1 ft. (agrees with record) Ren. No. 151
13" now 12" dia. 7 ft. high D.Fir stump with a fully healed single
blaze, bears S.51° E., 13.9 ft. (Rec. S.54° E., 45.9 ft.) (tagged
by B. Moyer in 1958, tag reads N.24 1/2° E., 21 lks.) unsure of
reason for bad brg's and dists. 1964 GLO
8" now 13" dia. W.Fir with a fully healed single blaze bears
S.36° W., 25.5 ft. (Rec. S.36° W., 26.1 ft. dist. to center of
trunks) 1964 BT.
New BT - 8" D.Fir double blazed and scribed "T29S R7W S35 CS BT" bears
N.43° E., 8.4 ft.

Corner lies at the intersection of a south and east running cut lines,
clear cut to the southeast. Approx. 125 ft. north of a gravel road.

1/4 Corner for Sections 19 & 20. 297
Found - Iron pipe with 1924 BLM Brass cap.
Fir stump, poor condition, bears S.68° W., 6 lks.
21" Cedar, N.20 1/4° W., 35.2 ft. - tall stump, tag nailed to
top of stump. See renewal # 215
13" Fir snag, N.17 1/4° W., 34.0 ft. - tall stump, tag nailed to
top of stump.
13" Fir, S.78 1/4° E., 93 lks - good - healed face
New Accessories -
10" Fir, N.4° E., 30.0 ft. scribed "1/4 BT"
12" Fir, N.6° E., 31.0 ft. scribed "1/4 BT"
11" Alder, S.80° E., 28.6 ft. scribed "1/4 BT"

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
December 19, 1991
C.S. File 64/21

Mark Smalley
For: Roseburg Forest
Products
Oct. 4, 1993
C.S. File 63/153