

Douglas County Surveyor's Record of
Government Corners Renewed

29

T. S.

8

R. W. W. M.

✓ S.E. CORNER OF CLIAM 44. March 20, 1926.
Located this corner. Original B.T., as described by Cole
in place. Line tree still in place. Both trees killed
when slashing was burned. Set new B.T.
A 12" Fir S.2°W., 96.6 ft. scribed Cl. 44 C.S.B.T.

8

SEE ALSO
RENEW #7

Mar. 2, 1926
Powker
Wit.
Geo. Spaur
N. W. Chapman

✓ SECTION CORNER BETWEEN 30 and 31 T. 29-8 and 25 and 36 E. 29-9.
Set 4" x 4" x 4" Post from one original B.T. which
bears S. 88°W., 319 lks. No other trees standing or near.
(See Also Cole F. 8. 43 (P. 16+) (1920) (Ren # 2 T. 29-9))

9

C.S. 341

117

✓ CORNER SECTIONS 5, 6, 7 and 8.
Set 1" x 1" x 30 Iron Bar from old B.T., S.E. Marked
new B.T.s
A Red Fir 30" dia. S. 66°30'W., 34.0 ft.
A Red Fir 20" dia. S. 15°00'W., 5.9 ft.
A Red Fir 24" dia. N. 76°00'E., 131.0 ft.

10

SEE CORNER NO. 70

H. L. Epstein
T. S. Crear
W. G. Reetz
R. T. Duntton
C. J. Wiley
W. G. Reetz

✓ 1/2 CORNER BETWEEN SECTIONS 7 and 12 (Rs. 8 and 9 W.)
Set Rifle Barrel for corner from one old B.T. Cut down
but B.T. scribe marks plain. Marked new B.T.s
Red Fir 20" dia. S. 65°W., 71.5 ft.
Red Fir 24" dia. S. 20°E., 61.0 ft.

11

SEE CORNER NO. 71

✓ S.W. CORNER OF DRYER D.L.C. # 41.
Identified and set from stump of original B.T. scribe
marks plainly visible. Set Iron rod 1" x 1" x 136" for
corner in North side of county road. Marked new B.T.s
A 16" Cedar N. 25°W., 114 lks. scribed Cl. 41 C.S.B.T.

12

153

✓ N.E. CORNER MARTINDALE D.L.C. # 42.
Identified by old rock used as corner for many years.
This rock is in South edge of County Road. New B.T.s
A 14" White Oak S. 62°W., 599 lks. scribed Cl. 42
C.S.B.T.
A 20" Fir N. 76 3/4°E., 433 lks. scribed
Reburied this rock and filled hole with gravel.

13

152

December 13 and 14, 1927
Ben B. Irving Dep. Co. Sur.
Witnesses
W. S. Crear
C. McCann
Wm. M. Porter

✓ 1/2 SECTION BETWEEN SECTION 17 and 20.
Set Sandstone 3" x 10" x 16" chiseled X and I from original
B.T. Old blazed badly scorred up. Set new B.T.s
A 14" Fir S. 85 1/2°E., 338 lks. scribed 1/2 S. 20 C.S.B.T.
A 14" Fir N. 60°E., 392 lks. scribed 1/2 S. 17 C.S.B.T.

14

SEE CORNER NO. 73

✓ 1/2 SECTION CORNER BETWEEN SECTIONS 20 and 21.
Set Ford axle with gear attached for corner from one
original B.T. which I remarked in the bark.
A 30" Fir S. 20°E., 16 lks.
A 28" Fir N. 60°W., 60 lks. marked 1/2 S. 20 C.S.B.T., new B.T.
(NOTE: This tree has been cut down and grubbed out, 28" Fir.
Set new B.T.
An 18" Fir N. 13°E., 91.0 ft. Marked 1/2 S. 21 C.S.B.T.
bark blaze. A. Boyer Wit. Ralph Richter
May 15, 1936.)

15

42

M1-63
V 3 Pg 281

✓ 1/2 SECTION CORNER BETWEEN SECTIONS 18 and 19.
Set sandstone 10" x 10" x 20" chiseled X and 1/4 14"
under ground. Set from original B.T. S. 77°E., 242 lks.
which we chopped into and found scribe marks, B.T.
New B.T.s
A 12" White Oak S. 69°24'E., 201 lks. scribed 1/2 S. 19
C.S.B.T.
A 20" White Oak N. 40°20'E., 311 lks. scribed 1/2 S. 18
C.S.B.T.

16

C 5-7/38

✓ 1/2 SECTION CORNER BETWEEN SECTIONS 17 and 18.
Found 12" Ash in position with proper blazes but figures
burned and rotted off. Also old oak which appeared to have
formerly been the original B.T. found marked 1" long which
seemed to be a scribe mark. Oak down and stump burned off.
Bank washed out where it formerly stood. Bearing and distances
check exactly. Set sandstone for corner 6" x 8" x 20" chiseled

17

104