

Douglas County Surveyor's Record of  
Government Corners Renewed

29

T. S.

8

R. W. W. M.

✓ SECTION CORNER BETWEEN 2 and 3, 29/8 and 34 and 35 26/8. **25**  
Renewed one tree only from corner as located from trees  
now in,  
A 12" Red Fir S.72°W., 50.5 ft.  
Original trees still in are,  
A 40" Fir N.43°W., 97 lks.  
A 36" Fir N.62°E., 113 lks.  
A 24" Oak S.75°E., 42 lks. **43**

✓ 1/4 CORNER BETWEEN 21 and 22. **26**  
Chinquapin B.T. to S.W. head and fallen down. Set 3" x 3"  
square post for corner from original  
An 18" Fir to the N.E.  
and blazed a 40" Fir and scribed it--for B.T. in Section 21--  
N.40°W., 36.5 ft. from 1/4 Corner. **85**

✓ 1/4 CORNER BETWEEN 9 and 10. **27**  
Set a 3" x 30" Iron rod from a 50" Fir, Original, in  
good condition, N.1°W., and a 20" Fir down but in good  
condition, Original, N.1°E., and at near bottom of steep  
North hillside. Marked and blazed two new trees as follows **133**  
A 30" Hemlock, bears N.70°30'W., 55.7 ft.  
A 48" Fir, bears S.46°E., 37.6 ft. scribed on bark.

✓ 1/4 CORNER BETWEEN 4 and 9. **28**  
Set a 3" x 30" Iron Bar from a 12" Oak S.40°W., 1.37 chs.  
and this Oak was rotted down, found old blazes but no scribe  
marks. Found 36" Fir scribed on bark, same original 18"  
Fir. Scribed following witness trees  
A 36" Fir N.9°30'E., 1.64 chs. blazed and scribed  
C.S.B.T. Original  
A 16" Fir S.10°W., 66 ft. blazed and scribed. New tree.

✓ 1/4 CORNER BETWEEN 8 and 9. **29**  
Set a 3" x 30" Iron Rod from original B.T.  
A 12" Fir N.78°E., 17 lks. is stump in poor condition  
A 10" Fir S.32°W., 13 lks. has been cut open.  
Tree in fair condition. Blazed and scribed two new trees  
as follows  
A 24" Fir bears S.43°30'W., 25.8 ft.  
A 40" Fir bears S.78°15'E., 48.0 ft.

1/4 COR. 28-33 **30**  
Set a 4" x 4" x 4" Fir post marked 1/4 S 28 on N face and 1/4 S 33 on S.  
12" Fir bears N 37° W 9.0 ft., mkd. 1/4 S 28 T 29 S R 8 W B T 1581. **134**  
14" Fir bears S 10° E 18.6 ft., mkd. 1/4 S 33 T 29 S R 8 W B T 1581.

SEC. COR. 27-28-33-34 **31**  
Set 4" x 4" x 4" Fir post for cor, mkd. S 27, S 28, S 33, S 34 on  
respective faces from which **135**  
32" Fir bears N 65° E 53.5 ft., mkd. S 27 T 29 S R 8 W B T 1581  
50" Fir bears S 63° 20' E 73.7 ft. mkd. S 34 T 29 S R 8 W B T 1581.  
22" Fir bears S 22° 45' W 59.7 ft. mkd. S 33 T 29 S R 8 W B T 1581.  
Fir 38" bears N 47° 10' W 27.0 ft. mkd. S 28 T 29 S R 8 W B T 1581.

1/4 COR. BET. 27-34 **32**  
Found original fir B.T. S 68° E 12 lks. mkd. 1/4 S plainly., also found  
original B.T. N 29° E 27 lks., tree down., mkd. new B.T. **139**  
12" Incense Cedar mkd. 1/4 S 27 B T 1581.  
Reset cor. with 2 x 3 x 4 live oak post marked 1/4 S 27 on N face and  
1/4 S 34 on S face.

1/4 COR BET. 27-28 **33**  
Found tree being 46 lks. North of cor. Reset cor. with 4 x 4 x 4 fir post  
marked 1/4 S 27 on E face and 1/4 S 28 on W face from which  
20" Fir bears N 57° E 18.5 ft. mkd. 1/4 S 27 T 29 S R 8 W B T 1581.  
14" Fir S 18° W 20.9 ft. mkd. 1/4 S 28 T 29 S R 8 W B T 1581.

9/10/10

5/20/50

Sept. 14, 1939

Dec. 29, 1939

4/1/92

April 1949

A. Boyer  
Oct. 22, 1935  
Wit.  
Ralph Heister

A. Boyer  
Aug. 25, 1936  
Wit.  
C. McCann  
Lewis Morris

Set by C.S.  
A. Boyer D.C.S. Set by C.W. Crocker  
of Oregon State Highway Dept.  
Sept. 14, 1939

Art Boyer - Surveyor #1581  
R. H. Gee  
R. J. Henrikson - Witnesses

RE-NEWED, SEE CORNER NO. 137