

Douglas County Surveyor's Record of  
Government Corners Renewed

29 T. S. 8 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97106

(continued)

# 53 (Cont.)

to expose part of upper blaze. Find good scribing "W" & "S 36".  
Fir Stump, now 40" diam. N.50°W. 48.2 ft. Opened lower scar  
but found only charred face.  
Remains of badly rotted Laurel Stump S.10°E. 46.2 ft.  
Set Brass Cap 10 ft. North of true Corner for Witness Corner Mkd:

T29S "County Surveyor's Office, 1958  
W.C. Corner 10 ft. S.

Blaze R9W  $\frac{S36|S31}{S1|S6}$  R8W

T30S  
& Scribe: 16" D. Fir S.49½°W. 27.5 ft. Mkd. "T30S R9W W.C. S1 CS BT."  
24" D. Fir N.60°W. 32.6 ft. Mkd. "T29S R9W W.C. S36 CS BT."  
45" S. Pine (N. E. BT. for true cor.) S.25°E. 10.0 ft.  
Mkd. "T30S R8W W.C. S6 CS BT."  
19" W. Fir N.73°E. 33.4 ft. Mkd. "T29S R8W W.C. S31 CS BT."

FD 1976  
BLM - SEE  
GIS FILE

James W. Byron, Deputy  
M. Godfrey  
S. Bilow  
C.S. File No. 49/100  
July, 1958

Sections 5 & 6 T30S, R8W to Sec. 32, T29S R8W. 54

Found - Orig. 14", now 26" Hemlock N.21°E. 21.1 ft., previously  
opened, face shows good scribing "S32 T29S R8W".  
Orig. 36", now 46" R. Fir S.30°W. 25.1 ft., shows good bark  
scribing.

Remains of Cedar Stump that checks bearing & distance for  
Orig. S. E. BT. 7/65 - GOV'T. BRASS CAP SET - (NOT C.I. CORNER)

Set Brass Cap at Corner Mkd: S32 T29S R8W  
County Surveyor's Office, 1958 S6|S5 T30S  
New BT's: 7" Hemlock bears S.26½°E. 33.1 ft. scribed T30S S5 R8W  
CC CS BT.  
4" Cedar bears S.11°W. 43.1 ft. scribed S6 CS BT.

Corner to Secs. 31 & 32, T29S R8W, & Sec. 6, T30S, R8W. 55

Found - Orig. 15", now dead 24" Hemlock N.33°E. 17.2 ft. I  
open & find good scribing "BT".  
Orig. 30", partly rotted Fir Snag S.50°E. 2.0 ft.  
Stump Holes that check bearing & distance for S.W. &  
N. W. BT's.

Drove ¾" x 30" Rod at Corner.  
New BT's: 12" Hemlock bears N. 2°W. 79.0 ft. scribed S31 T29S  
R8W CS BT.  
16" Hemlock bears S.61°W. 38.5 ft. scribed S6 T30S R8W  
CS BT.

Note: Sketch in file shows exact location of Corner.

¼ Section Corner to Section 31, only T29S R8W, & ~~Sec. 6, T30S, R8W.~~ 56

Found - Orig. 15", now 24" Stump previously opened, shows good  
scribing "BT".  
Stump Hole that checks bearing & distance for Orig. S.W. BT.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1958  
¼ S31 T29S R8W 7/65 GOV'T. B.C. SET.  
S6 T30S R8W ¼ C.C. SEC. 31 ONLY  
New BT's: 15" R. Fir bears N.37°E. 39.3 ft. scribed S31 ¼ CS BT.  
22" R. Fir bears S.22°E. 47.3 ft. scribed ¼ S6 CS BT.  
DON BECK'S INFO.

FD 1976 BLM  
SEE GIS FILE

¼ Section Corner to Sections 31 & 32. 57

Found - Both Orig. BT's & scribed "CS" Stake bears S.20°W. 3.7 ft.  
Orig. 60", now 60" Rotted Fir Snag S.22°E. 9.9 ft. I open  
near base & find lower part of old blaze & small scribe mk.  
Orig. 40", now 48" Fir down N.7°W. 27.1 ft. I open &  
find good scribing "B".

Set Brass Cap at Corner Mkd: ¼ S31/S32 T29S R8W County Surveyor's  
Office, 1958  
New BT's: 18" Cedar bears N.54½°W. 41.0 ft. scribed ¼ S31 CS BT.  
14" W. Fir bears N.20° E. 12.4 ft. scribed ¼ S32 CS BT.

Note: I believe this corner was renewed by County Surveyor about  
20 to 25 years ago & by the same County Surveyor who renewed  
¼ Corner to Sections 21 & 28, T29S R8W. Neither Corner of  
record.

(Possibly  
C.S. 16/25)

James W. Byron, Deputy  
Chafmen: Milo Godfrey  
S. A. Bilow  
September 1958  
C.S. File No. 49/100