

**Douglas County Surveyor's Record of
Government Corners Renewed**

29 T. S. 8 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Section Corner to Sections 15, 16, 21, & 22.
Found - Three Orig. BT's:

- 60", now 66" Fir Stump bears S.8°E. 6.6 ft., No scribing found.
- 12", now 20" Oak Snag N.32°W. 42.2 ft., open & find good scribing "BT".
- 12", now 28" Laurel N.70°E. 30.4 ft., shows old scar. I do not open.
- S. W. BT. would be in Logging Road.

Note: I find 1" Iron Pipe bears N.7½°W. 14.3 ft. May be set for Sec. Corner.
Set Brass Cap at Corner Mkd: $\frac{S16}{S21} | \frac{S15}{S22}$ T29S R8W County Surveyor's Office, 1958

New BT's: 10" W. Fir bears S.32°E. 120.0 ft. scribed S22 T29S R8W CS BT.
8" Cedar bears N.83°E. 31.7 ft. scribed S15 T29S R8W CS BT.
14" R. Fir bears N.23°E. 67.7 ft. scribed S15 T29S R8W CS BT.
No trees to West.

FD OK BY K. DeGraaf
1-95 M 121-33 75 CS. 63/52

¼ Section Corner to Sections 15 & 14. 76

Found - Orig. 20", now 24" Oak N.68°W. 62.0 ft. This BT. down & has been down for years. I find good scribing "¼S" on previously opened face.

Find Remains of old Oak that checks bearing & distance for Original N. E. BT.

Set Brass Cap at Corner Mkd: ¼ S15/S14 T29S R8W County Surveyor's Office, 1958.

New BT's: 15" R. Fir bears N.74°E. 11.2 ft. scribed ¼ S14 CS BT.
20" R. Fir bears N.61°W. 12.0 ft. scribed ¼ S15 CS BT.

James W. Byron, Deputy County Surveyor
Hilo Godfrey
S. A. Bilow
September, 1958
C. S. File No. 49/100

Section Corner to Sections 26, 27, 34, & 35. 77

Found - All Four Orig. BT's: All alive & good condition, & All check for bearing & distance.

S. E. & N. E. BT's. have previously been opened. Show good scribing.

The Fir to S. W. bark scribed.
The Cedar to N. W. shows good scar. I do not open.

Set Brass Cap at Corner Mkd: $\frac{S27}{S34} | \frac{S26}{S35}$ County Surveyor's Office, 1958

Orig. BT's O. K. I do not scribed New BT's.

RE-RENEWED CORNER NO. #212

FD. OK
1-12-80
H. JENNINGS
1779-15

¼ Section Corner to Sections 15 & 22. 78

Found - B. Oak, now 16" diam., N.30°E. 46.2 ft. Upper blaze had been opened previously & face rotted, chopped out lower blaze & found "BT" scribing in perfect condition.

Pine, down & dead, now 32" diam, with lower blaze open & "BT" scribing plainly visible. Does not appear to have ever grown over. No trace of upper blaze found, probably bark scribed.

Set Iron Pipe with Brass Cap Mkd: ¼ $\frac{S15}{S22}$ T29S R8W County Surveyor's Office, 1958

Blaze & Scribe 5" D. Fir N.2°E. 22.6 ft. Mkd. "¼ S15 CS BT".
13" Incense Cedar S.62½°W. 22.4 ft. Mkd. "¼ S22 CS BT".

Section Corner to Sections 10, 11, 14, & 15. 79

Found - W. Oak, now 12", S.35°W. 41.6 ft. This tree had been opened several years ago, and plainly visible but badly rotted scribing "T29S R8W S15" can be seen.

Badly rotted Pine Stump, approx. 40" diam. N.40°E. 53.5 ft. Too far gone to find any scribing.

Stump Hole & Dead Oak Shoots N.30°W. 38.3 ft.
No trace of S.E. BT. found.

15" Incense Cedar with "BT" cut in with an axe about 20 yrs. ago N.35°W. 13.3 ft.

Set Iron Pipe with Brass Cap Mkd: " $\frac{S10}{S15} | \frac{S11}{S14}$ T29S R8W County Surveyor's Office, 1958.

Blaze & Scribe: 17" D. Fir S.27½°W. 25.5 ft. Mkd: T29S R8W S15 CS BT.
15" I. Cedar N.35°W. 13.3 ft. Mkd: T29S R8W S10 CS BT.
8" D. Fir S.85°E. 33.3 ft. Mkd: T29S R8W S14 CS BT.
13" D. Fir N.27½°E. 45.2 ft. Mkd: T29S R8W S11 CS BT.

Fence Corner East & South bears S.18°W. 7 feet.