


Douglas County Surveyor's Record of
Government Corners Renewed

29 T. S. 8 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21861

Section Corner to Sections 29, 30, 31, & 32.

Found - 1 1/4" Iron Pipe out of Ground at Fence Corner thus:  97
Coles 18", now 22" Fir S. 49 1/2° E. 29.0 ft., shows good scars, I do not open. - Ren. #4783
Orig. 15" Oak record N. 77° E., should be S. 77° E. 69.9 ft., shows rotted face, no scribing found.
Orig. 30", now 56" Fir 115.5 ft. S. 8° W., shows good bark scribing.
Cole's 20", now 24" Fir Stump N. 60° 30' W. 53.0 ft.
Reset I. Pipe at Fence Corner & Set 3/4" Iron Rod alongside.
New BT's: 5" R. Fir bears N. 63° W. 64.7 ft. scribed S30 CS BT.
12" W. Fir bears S. 87° W. 27.3 ft. scribed S31 T29S R8W CS BT.
9" R. Fir bears N. 61 1/2° E. 13.7 ft. scribed S29 T29S R8W CS BT.

Fd 1925 Blm
B.C. 3/90
1990-0028

James W. Byron, Deputy
Milo Godfrey
S. A. Blilow
October 16, 1958
C. S. File No. 49/100

1/2 Section Corner to Sections 29 & 32.

Found - 1 1/4" Iron Rod & Both BT's as scribed by Boyer, 1939.:
30" Fir, now 34" Fir Stump N. 8° E. 55.0 ft., no scribing found, "cut low".
8", now 12" Laurel, blaze not grown over, parts of scribing visible, S38° E. 118.8 ft.
Note - 1 1/4" Iron Rod at Corner is in Center of graveled road & about 3" under surface.
New BT's: 10" Cedar bears N. 12 1/2° E. 53.2 ft. scribed 1/4 S29 CS BT.
7" R. Fir bears S. 65° E. 56.9 ft. scribed 1/4 S32 CS BT.

98

(c.s. 16/25)

Section Corner to Sections 28 - 29 - 32 - 33.

Found - 30" Cedar S. 5° E. 33 ft., down, scribing visible, and a 4x4 Cedar Post with scribing. SEE REN. NO. 23784
Set - 1" x 30" Iron Pipe
6" Cedar S. 25 1/2° E. 138.5 ft.
6" W. Fir N. 70 1/2° W. 118.2 ft.
5" W. Fir S. 80° W. 52.0 ft.
8" R. Cedar N. 46° E. 126.6 ft.

99

By Howard W. Johnstone
For Rsbrg. Lumber
Jan. 4, 1961
C.S. File No. 51/163

RE-RENEWED CORNER NO. #202

SE
E

N
E
X
T

P
A
G
E