

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 29 S. T. S. R. 8 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97401

147

1/4 Corner to Section 2 and Section 1.  
Set Brass Cap for 1/4 corner as we find no trace of 1924 B.C. or BT's.  
Set at prorated distance and Mkd: County Surveyor's T 29 S R 8 W  
Office, 1969 1/4 S 2 | S 1  
New BT's: 28" W.Oak N. 84° E. 113.9 ft. mkd: "1/4 S 1 CS BT".  
29" W.Oak S. 88° E. 112.2 ft. mkd: "1/4 S 1 CS BT".  
There were no trees available to west of line. 2/20/69

V. "Ray"  
Tracy & Crew  
C.S. 54/80  
M 37-25

148

1/4 Corner to Sec. 4, T29-8W and Sec. 33, T28-8W.  
Found - 1957 Co. Surveyor's Brass Cap which was pulled out when  
N. E. Bearing Tree fell.  
48" D.Fir, now down, N.40°E. 2.6 ft., bark scribe visible.  
48" D.Fir Stump S.65°W. 19.8 ft., "B" visible.  
10", now 12" R.Cedar, S.38°E. 37.1 ft., scribe visible.  
Reset - Brass Cap at 1/4 Corner which was properly marked in 1957, Ren.#49.  
New BT: 12" R.Fir N.50°W. 11.0 ft. mkd: "1/4 S33 CS BT".  
This corner lies about 40 ft. west of small creek. 8/21/69

John M.  
Powell &  
Crew  
C.S. File  
No. 54/38

149

Section cor. of sec. 34 and 35 only, T29S R8W.  
Found-40" D.Fir, now down, rotten, N.80°E. 13.9 ft.  
20" D.Fir, now 27", S.43°E. 30.4 ft. Bark scribe visible "8 W 2".  
30" D.Fir, now down, rotten, S.55°W. 4 ft.  
15" Cedar, now down, N.30°W. 8.6 ft.  
Set - Brass cap at cor. mkd: County Surveyor's T29S R8W S 34 | S 35  
Office 1970 T30S S 2  
New BT's: 26" D.Fir N.25°W. 20.2 ft. Scribed T29S R8W S34 CS BT.  
8" W. Fir N.39°E. 21 ft. Scribed T29S R8W S35 CS BT.  
Reblazed and Rescribed:  
27" D.Fir S.43°E. 30.4 ft. scribed: T30S R8W S2 CS BT.  
Note- This cor. lies approx. 230 ft. East of 34  
213

Feb. 9, 1970

150

Section cor. of sec. 3 and 2 only T30S R8W.  
Found-40" D.Fir, now 47", N.42°E. 21.1 ft. Bark scribe visible "TWB"  
10" Laurel, now down, S.54°E. 15.8 ft. This probable BT has  
old "X" on it, however, out of ground & down hill from where  
it should be. No trace of SW BT.  
Set- Brass cap at cor. mkd: County Surveyor's T 29 S R 8 W S 34  
Office 1970 T 30 S S 3 | S 2  
New BT's-6" Cedar N.4°E. 32.8 ft. Scribed T29S R8W S34 CS BT.  
13" Cedar S.75°E. 31.7 ft. Scribed T30S R8W S2 CS BT.  
35" D. Fir S.2°W. 11.5 ft. Scribed T30S R8W CS BT. S3.  
Note: This cor. lies approx. 230 ft. West of 34/35.  
2 2/9/70

FD. OK  
1-10-80  
H. JOHNSTANE  
1079-15

151

1/4 Corner to Sections 13 and 24.  
Found - 1924 GLO Brass Cap, in place & properly marked, & from which:  
30" Fir, now badly decayed, S.53°W. 17.8 ft., find scribe & reverse.  
36" Fir, now stump, N.73°W. 38.9 ft., scribe visible.  
Both Original BT's. also in evidence, but badly decayed with bark gone.  
New BT's: 11" D.Fir N.83°W. 20.1 ft. mkd: "1/4 S13 CS BT".  
8" D.Fir S.60°W. 17.6 ft. mkd: "1/4 S24 CS BT".  
5" D.Fir S.88°E. 12.6 ft. mkd: "1/4 S24 CS BT".  
This corner lies on steep, westerly slope in dense 2nd. growth, old  
cutting line bears North approximately 200 ft. 7/22/70

ER NO. #168

John M. Powell  
Frank Jones & W. Penley  
C.S. File No. 54/38