

Douglas County Surveyor's Record of
Government Corners Renewed

T. 29 S. T. S. R. 8 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

152

John M.
Powell &
Crew
C.S. File
No. 54/38

OSND 9/2/86
FD 9/2/86
CS 63/9

N. E. Corner D. L. C. No. 42.
Found - Did not find rock used for corner, did not dig up payment. Ren. #13.
14", now 26" W. Oak, S. 62° W. 53.5 ft., shows good scars.
20", now 38" D. Fir, N. 76 3/4° E. 285.8 ft., shows good BT scar and faint bark scribe.
Set - 5/8" I. Rod, flush with road surface, on south edge of road at corner point.
(See Northcraft's Corner on M 42-13)
Reblzd. & Resbd: 38" D. Fir N. 76 3/4° E. 285.8 ft., mkd: "NE DLC 42 CS BT".

9/9/70

153

By: Herbert
Northcraft
For: N. Brown
Map File
M 42 - 13

S. W. Corner D. L. C. 41, J. A. Dryer D.L.C.
Found - 1" Iron Rod 2" below surface of Black Top, Ren. #12.
3 Witness Trees scribed: "S.W. Cor. Cl. 41 BT LS 750".
2" W. O. N. 58° W. 91.0 ft.
3" Fir N. 1° E. 131.5 ft. - CUT BY LANDOWNER (BURGER) 12/88
16" Cedar N. 40 1/2° E. 60.2 ft. STUMP W/ SCARING LEFT

Oct. 1970

154

By: Herbert L.
Northcraft
For: W.M.
Sturmer
Map File
M 40 - 79

RE-RENEWED SET CORNER NO. #210
FD. 1978 - DE. ST. HWY DEPT. 1
SEC. M-3 & 7/15/86
CS 63/9

1/4 Corner between Sections 2 and 11.
Found 1 1/2" Angle Iron for Corner. See Ren. #50.
14" B.O. opened, 1/2" visible, reverse "B" on lower blaze.,
Rescribed "1/4 S11 T29S, R8W."
New BT: 12" B. O. N. 28 1/2° E. 31.2 ft. scribed "1/4 S2 T29S R8W BT".

Sept. 1970

155

James W. Byron, Co. Surveyor
W. Penley
Mar. 17, 1971
C.S. File No. 54/38

JAN 1972

1/4 Corner to Sections 28 and 21.
Found - Orig. 24", now 48" Fir, N. 30° W. 28.4 feet., no original scribing found. We do find good bark scribing on N. E. face, "1/4 S21 T29S R8W BT 1580".
No trace of original S.W. Bearing Tree.
Do find scribed stake at corner and Cedar that shows good scribing bears S. 31° W. 24.0 feet.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office T 29 S R 8 W
1971 1/4 S 21
S 28
No new bearing trees scribed.
Note - Corner at bottom of small draw.
See Statement by Boyer in C.S. File No. 54/38:
I, Arthur Boyer, state that I renewed the 1/4 corner to Sections 21 and 28, T. 29S., R. 8W., W. M., in 1958 by bark scribing the original N. W. Fir BT. on which I observed bark scribe marks and that, at that time, I set a scribed stake at the 1/4 corner using record bearing and distance from the Fir BT. Also that I scribed a small cedar in S.W. Quad. for BT. in Sec. 28.
FD OK BY
K. DEGroot
1/95 M121-33
CS 63/52

3/17/71

157

John M.
Powell &
Crew
C, S. File
No. 54/38

South 1/4 Corner Section 36 only, T29-8W.
Found - 1967 C. S. Brass Cap at Corner, out of position due to logging. Ren. #142
6", now 7" W. Fir, N. 4° E. 31.2 ft., shows good scar.
15" Cedar, now high stump, S. 11° E. 20.2 ft., scribe vis.
Reset - Brass Cap at 1/4 Corner.
New BT: 11" Cedar N. 89° E. 112.2 ft. scribed "1/4 S36 CS BT".

7/5/72

158

Bruce A. Shaner
For: U.S. B.L.M.
Map File M 42 - 67

CORNER
REPORT
OSND - 2/24/86
CS 63/9

Section Corner to Sections 3 - 4 - 9 - 10.
Found - Brass Cap mkd. Co. Surveyor's Office T. 29S, R8W, 4, 3, 9, 10, 1958, See Ren. #81.
Orig. 36" Doug. Fir BT, stump, scribes partially visible, bears N. 87 1/2° W. 8.1 ft.
Orig. 40" Doug. Fir BT, scribes partially visible bears S. 60° W. 15.8 ft.
28" Doug. Fir BT, bark scribe, bears N. 87 1/2° W. 8.1 ft.
16" White Fir BT, bears N. 61° E. 41.1 ft.
Parts of White Fir, CS BT, pushed down, found reversed scribes, bears S. 9° E. 22.4 ft.
New BT: I scribed 12" White Fir "T29S, R8W S10 BT" bears S. 53° E. 26.5 ft.

8/25/72