

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 29 S. T. S. R. 8 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

157A

1/4 Corner to Sections 3 and 10.  
Set Brass Cap Mkd: T29S, R8W, WM 1/4S S3, S10, 1972  
Found - 3/4" Iron Pipe set by Boyer bears S.51 3/4°W., 13.42 ft. Ren.#143.  
10" Pencil Cedar BT., scribes visible bears N.10°E. 32.1,  
scribed by Boyer.  
30" Orig. Doug. Fir BT. Stump, scribes "S10" visible bears  
S.64°E. 13.2 ft.  
16" Doug. Fir BT. scribes partially visible, bears S.52°W., 15.6 ft.  
scribed by Boyer.  
8/25/72

FD B.C. + BT's  
7/18/72  
0540  
CS 23/9

Bruce A. Shaner  
For: B.I.M.  
Map File M 42 - 67

158

Section Corner to Sections 2 - 3 - 10 - 11.  
Set Brass Cap Mkd: T29S, R8W, WM, S3, 2, 10, 11, 1972  
Found - 7"x3"x2' Sandstone marked S2 T29S R8W. Rock now broken into  
two parts., See Ren. #51.  
Orig. 36" Laurel BT., face rotted out, no scribes visible,  
bears N.57°E. 22.4 ft.  
10" Douglas Fir BT bears N.64°E. 29.1 ft.  
Orig. 40" Laurel BT, face rotting out, no scribes visible bears  
S.23 1/2°E. (Rec. S.30°E.), 16.5 ft.  
8" Douglas Fir BT. bears S.86 1/2°E. 39.4 ft.  
16" Douglas Fir BT bears N.86°W. (Rec. N81°W.) 16.0 ft.  
10" Douglas Fir BT bears S.46°W. 43.2 ft.  
8/25/72

FD. OK  
7/9/86  
0540  
CS 23/9

159

Section Corner to Sections 3 & 4 T.29-8 & Secs. 33 & 34 T.28-8  
Found - Brass Cap Mkd. County Surveyor's Office T28S T29S R8W S33 S34  
S4 S3 1957. Ren. #48  
Possible 12" Laurel, broken off, face rotted, bears N.20°W.,  
38.2 ft.  
22" Douglas Fir, bark scribe bears N.73°W., 47.6 ft.  
16" Douglas Fir, bears S.16°W., 18.8 ft.  
Original 36" Douglas Fir, now down, bark scribes visible, Bears  
N.78°E., 37.6 ft.  
Original 18" Laurel, rotted stump, scribes vis. on piece of  
wood inside stump, bears S.80°E., 37.0 ft.  
16" White Fir, now down, bears S.59°E., 18.6 ft.  
New BT's - I scribe 16" Douglas Fir, bears N.22°E., 27.7 ft.  
I scribe 8" White fir, bears S.88°E., 41.6 ft.

JAN 1973

160

East 1/4 Corner for Section 13 only.  
Found - Brass cap at corner & S.W. BT., shows good scar.  
Find low cut stump that checks N.87°W., not S.87°W.  
New BT - 9" R. Fir, bears N.87 1/2°W., 16.0 ft. scribed 1/2 S13 CS BT. #166

J.W. Byron, Deputy  
McFarland & Powell  
May & June 1962  
C.S. 49/139

161

Section Corner to Sec 16,17,20 and 21  
Found 1958 DCS brass cap out of the ground. We find the following bearing  
trees: We find the three orig. BT;s as noted in Ren#74. They occupy their  
record positions.  
We also find the following 1958 CS BT's:  
A 12" now 18" W. Fir bears S76 1/2°E., 30.6 ft. alive and well healed.  
A 6" now 8" yew bears S64°W., 35.2 ft., alive with scribing visible on  
partially healed blaze.  
An 8" now 11" Yew bears N56 1/2°W., 49.1 ft., alive with scribing visible  
on partially healed blaze. The NE Bearing tree is down.  
At the corner point as determined from the above mentioned bearing trees  
we reset the 1958 County Surveyor's brass cap. A 1" X 30" IP Marked  
T 29 S R 8 W

FD OK 1/95  
K. DeGroot  
M121-33  
CS 23/2

Gary L Langlitz  
Clell E Goodwin  
M Lenora Ladig  
A Vic Cangie  
CS 57/39  
12/2/75

COUNTY SURVEYORS OFFICE  
1958

S 17	S 16
S 20	S 21

We add the markings "CS 1975" to the monument and mark the following new  
bearing trees: An 6"D. Fir bears N26°E., 14.6 ft., scribed "T29S R8W S16 CS  
BT" on a double blaze. Note: A 4" X 4" Wooden post, painted white, is  
located approx, 1 ft. east of the corner. The corner is located across a  
small draw at the SE Corner of the Camas Valley Disposal Site.  
Compass Declination Setting: 20° East. 12/2/75