

Douglas County Surveyor's Record of
Government Corners Renewed

29

T. S.

8

R. W. W. M.

FOKE-CHAPMAN CO., EUGENE, ORE. 9181

201

Ronald Geisler, #1988 1/4 Corner for Sections 27 and 28
Champion International Found - County Surveyor's brass cap set on a 1 1/4" I.P. properly mkd. #137
April 1986 13" W. fir bears N.85 1/2°W., 12.80 ft. Healed face. (1967)
C.S. 63/34 18" D. fir bears S.18°W., 20.90 ft. Healed face (1949) Ren. #33
28" D. fir now down bears N.70°E., 21.2 ft. (1967) Healed face.
20" D. fir now down bears N.57 1/2°E., 18.50 ft. bark scribe visible.
New BT - 14" W. fir bears S.19°E., 7.22 ft. Scribed "1/4 S27 BT". (1986).

Ren.

#137

Ren. #33

Healed face.

bark scribe visible.

(1986).

202

Section corner for Secs. 28, 29, 32 and 33.
Found - 1 1/2" I.P. (rec. 1" I.P.) extends 5" above ground. Ren. No. 99
6" cedar, now rotting 5 ft. tall snag, bears S.25 1/4°E., 138.5 ft.
Scribe visible. (1961)
6" Fir, now down and rotted bears N.70 1/2°W., 118.2 ft. Scribing
partially visible. (1961)
12" W. fir bears S.80°W., 51.77 ft. (Rec. 52.0 ft.) Healed
face (1961)
14" cedar bears N.46°E., 126.6 ft. Scribe visible. (1961)
New BTs - 12" D. fir bears S.47°E., 28.5 ft. scribed "T29S R8W S33 BT"
6" D. fir bears N.67°W., 23.47 ft. scribed "T29S R8W S29 BT"

203

Ronald Geisler
For: Champion
International
Oct. 15, 1986
C.S. 63/34

Center 1/4 Corner for Section 28
Set - 2 1/2" alum. cap set on a 1" x 36" iron pipe
BTs - 7" fir bears S.31°E., 13.4 ft.
10" Fir bears S.36°W., 8.4 ft.
Both BTs scribed C1/4 S28 BT.

204

Northeast corner for DLC #43
Found - An unrecorded concrete nail set flush in asphaltic surface
of Burma Road. Bearing trees indicate nail is set over 3/4"
iron rod corner monument set by Byron in survey M 27 - 13 as
recorded in DCSO survey records. (Ren. #120) We do not
disturb road surface to search for 3/4" I.R.
No original evidence found.
Found - 25" Red fir now a 36" DBH D. fir with a fully healed double
blaze bears N.33°E., 60.2 ft. as per rec. Ren. #120
A W. oak now a 27" DBH W. Oak with a fully healed double blaze
bears N. 61° W., 108.6 ft. as per rec. Ren. #120
Bearing Objects found: (not of record)
A 1" iron pipe protruding 2" above the ground and a 1" iron pipe
protruding 4" above (taller pipe set by property owner R.
Halterman to mark position of shorter pipe: property owner
believes pipes mark road R/W, no record of pipe being set
found at DCSO). The 1" I.P. protruding 2" above ground as
mentioned, bears N. 81°E., 30.63 feet.

*EXD 3/91
M111-69
FDOK
3/96 B. Rogers
1997-33*

4/7/87

205

Ronald Geisler
For: Champion
International
Dean Turner >crew
Lynn Sibley
June 30, 1987
C.S. 63/60

1/4 Corner for Sections 22 and 27
Found - 1958 County brass cap, 2 1/2" on a 1 1/2" iron pipe, extends 12"
above ground. Ren. #86
14" cedar bears S.20°E., 7.7 ft. Healed face. Ren. No. 86
6" D. fir bears N.7°E., 14.8 ft. is uprooted, shattered and
out of position. Ren. No. 86
34" fir, now stump, bears N.77°W., 48.8 ft. Lower blaze partially
visible. Original BT.
New BT - 6" D. fir bears N.54°E., 25.3 ft. and scribed "1/4 S22 BT. (1987)
6/30/87

206

Doug. Co. Surveyors
Office
Stephen Flause and
Randall Smith
Deputies
April 25, 1988
C.S. 62/52

Section Corner for 6 and 7 only of T.29-7
Found - 1924 GLO brass cap on a 1" I.D. iron pipe firmly set 32" below
surface of road shoulder. (cap oriented east, not north).
Drill steel guard stake from Ren. #270, T29-7 gone.
(No evidence of orig. BTs found. Positions fall indriveway & roadway. The
OBTs apparently were also Ren. #30, T29-7 BTs.)