

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 29 T. S. R 8 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORG. 21981

206

C O N T. - - - -

Douglas County
Surveyors Office
Stephen Flause
Randall Smith
Deputies
April 25, 1988
C. S. 62/52

From Ren. #110, a 1" I.D. iron pipe, near the corner of fences running south and northeast, firmly set and protruding approx. 2" above ground bears S.01°W., 47.0 ft. as per record. (Survey file CS 18/2 records an I.P. S.1°13'W., 44.7 ft.)
A 10" R. fir now a .19" DBH D. fir with a fully healed double blaze bears S.22°E., 50.8 ft. Ren. #110.
A 2 3/8" dia. 1981 County brass cap on an I.P. (W.P. from Ren. #195) set flush with ground bears N.89°W., 119.4 ft. (Rec. per Ren. #200; Rec. per Ren. #270 of T29-7, N.89°W., 119.2 ft.; orig. 1924 resurvey rec. N.89½°W., 118.8 ft.)
A 5/8" dia. iron rod firmly set and protruding 5" above ground bears N.40°W., 38.51 ft. Ren. #270 of T.29-7.
A 5/8" dia. iron rod firmly set and protruding 4" above ground bears N.18½°E., 39.88 ft. Ren. #270 of T.29-7
Set - Because found monument is deep in ground, we set directly over the brass cap a 5/8" x 30" iron rod with a 1½" dia. alum. cap marked "Douglas Co. Surveyor T29S $\frac{S 6}{S 7}$ R7W".
New monument is approx. 2" below $\frac{S 6}{S 7}$ gravel surface of road shoulder when established.
Monument is in North road shoulder of County Road #140 and between two driveways running north from roadway.

4/25/88

207

Wayne Rogers
Bureau of Land
Management
6/1/89
C.S. 63/87

Section Corner for Sections 2 and 3; and 34 & 35 of T.28-8
Found - 1½" iron post found loosely set projecting 24" above ground.
BT by Boyer, A fir snag 17" bears S.70°W., 77 lks. Ren. #43
BTs by Byron:
A fir 11" bears N.21½°E., 25 lks. healed double blaze.
A fir 14" bears S.8°E., 46 lks. healed double blaze.
A fir 19" bears N.4¼°W., 36 lks. healed double blaze.
Set - Referenced monument and reset 24" in the ground with 8" projecting above ground.
New BT - A fir, 19" bears S.39½°W., 45 lks. mkd. "T29S R8W S3 BT".

6/189

208

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
March 28, 1990
C.S/ 64/6

West 1/16 corner between Sections 9 and 16. (Witness Corner)
Position of corner was referenced by John Read (OSHD). A hub and tack is found at OSHD position of referenced corner, this hub and tack checks well with R.P. hub and tacks set by John Read. Position of BLM BC/IP falls under fill of new highway construction. (OSHD notes attached to this corner report. See C.S. 64/6).
1" car axle noted in 1980 BLM dependent resurvey and W 1/16 cor. and BTs per CS 37/200 are not found.
No accessories found. Apparently BTs cut down and covered up in construction
Set - A 2 3/8" dia. DCSO brass cap on a 1 3/8" O.D. x 31" long I.P. is set west 111.0 ft. from referenced cor. DCSO BC/IP protrudes 9" above ground. Cap stamped "Douglas County Surveyors Office T29S R8W W 1/16 S9 S16 B01 East 111 ft. to cor 1990"
New BTs - From referenced position of DCSO BC/IP (B01)
12" W. fir double blazed and scribed "BO 1 W1/16 S9 CS BT" bears N.19°E., 4.6 ft.
6" W. fir double blazed and scribed "BO 1 W1/16 S16 CS BT" bears S.86°W., 11.1 ft.

3/28/90

209

Ronald Geisler
For: Champion Int'l
March 16, 1990
M 109-72
C.S. 63/113

Section Corner for Secs. 1, 2, 11 and 12
Found - 1924 GLO 2½" brass cap on a 2" I.P. 12" above ground.
21" Fir bears N.13°W., 31.7 ft. (Rec. N.15°W., 31.0 ft.)
Closed face (original BT)
Rotted stump bears N.26°E., 25.7 ft. to face. (original)
Uprooted cedar bears S.75°W., 27.1 ft. (original)
27" fir bears S.12°E., 37.1 ft. (Rec. S.16°E) Closed face. Ren.125
25" cedar bears N.46°E., 53.5 ft. (Rec. N.41°E., 55.0 ft.)
Closed face. Ren. No. 125
14" fir bears N.88°W., 53.3 ft. opened face at base but found no scribing. (No record)
Did not find 1966 BT S.67°W., 59.3 ft.
New BT - 5" W. Oak bears S.82°W., 14.13 ft. scribed T29S R8W S11 BT.

3/16/90