

Douglas County Surveyor's Record of
Government Corners Renewed

29 T. S. 9 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97196

Bonneville Survey
Party A-53.
Filed in 41/251.

E. $\frac{1}{4}$ corner section 25.
Found corner, bearing trees gone.
Set witness trees:
A 26" Oak bears S. $66\frac{1}{2}^{\circ}$ E., 372.2 to center of tree. This Oak is 7 ft. west of the Middle Fork of the Coquille River. Seven feet west of the right bank.
A 4" ash bears S $23\frac{3}{4}^{\circ}$ S., 6.3 ft.
This corner is a $1\frac{1}{2}$ " iron pipe flush with the ground. -REN. No. 12
Both trees are scribed $\frac{1}{4}$ W. T.

22

$\frac{1}{4}$ sec. corner between sec. 24, (T29S, R9W.) and sec. 19, (T29S, R8W.)
Set this corner from O. B. T. in Section 19.
Drove a $\frac{1}{2}$ inch X 20 inch iron pipe for corner from which a $\frac{1}{2}$ inch X 23 inch iron pipe in fence line bears S. $89^{\circ}38'$ W., 20.0 feet and a 1 inch X 19 inch iron pipe in fence line bears N. $89^{\circ}38'$ E., 18.7 feet.
Corner is in County Road. Original B. T. in Sec. 19 still standing. #86
Feb. 7, 1955.

23

Section corner to secs. 24 and 25, (T29S, R9W.) and secs. 19 and 30, (T29S, R8W.).
Found rock with cross on top 18 inches below ground surface on the east shoulder of County Road. (SEE REN. No. 8)
Set a $\frac{1}{2}$ inch iron pipe 18 inches long on top of this cross, on rock, which is 13 feet west of the east side of road as fenced and it is 247.5 feet south of a $\frac{1}{2}$ inch X 30 inch iron pipe which is driven in the fence on the east side of road; This $\frac{1}{2}$ inch X 30 inch pipe is in line with a fence that runs west from the road. #85
February 8, 1955.

24

$\frac{1}{4}$ section corner between secs. 23 and 24.
Searched diligently for witness trees without success, so set this corner midway between the southwest and the northwest corners of this section 24.
Drove a $\frac{3}{4}$ inch X 36 inch iron pipe at the corner. No trees nearby.
Feb. 15, 1955.

25

$\frac{1}{4}$ sec. corner between secs. 13 and 24.
The timber in the vicinity of a 500 foot radius of where this corner should be, has been logged off so that there was nothing to indicate any sign of the witness trees: the distance between the northwest and the northeast is 5282.8 feet.
Set a $\frac{3}{4}$ inch X 48 inch iron pipe midway between section corners from which:
A 9 inch W. O. tree bears S. $80\frac{1}{2}^{\circ}$ E., 32.6 feet., marked $\frac{1}{4}$ S 24 1581 BT.
A 34 inch Fir stump bears N. $10\frac{1}{2}^{\circ}$ E., 29.1 feet., marked $\frac{1}{4}$ S 13 1581 BT.
Feb. 14, 1955.

26

Center $\frac{1}{4}$ section corner to section 24.
Drove a $1\frac{1}{4}$ inch X 50 inch iron pipe at center of section at intersection of the North & South and East & West mid section lines.
There are no trees nor distinguishing points for witness points.
Feb. 17, 1955.

27

$\frac{1}{4}$ corner to sections 26 and 35.
Found 1 inch iron bolt and both B.T.s as renewed in 1951. The 10 inch W. Fir, N. $7^{\circ}30'$ W., 77.9 feet is now dead. (REN. No. 21) SEE ALSO # 21
Blaze and Scribe:
12 inch W. O., N. 63° E., 17.8 feet mkd. $\frac{1}{4}$ S 26 CS BT.

28

Arthur Boyer - Registered Professional Engineer No. 1581.
Witnesses: Bernard Denn
W. E. Howard
Leo Denn
February, 1955.
C. S. File No. 41/353 A.
M 61-2

James W. Byron
Dep. County
Surveyor.
Apr. 5, 1957.
File 47/173.

SEE Vol. 34, Pg. 14029 - B.C.M. 1966 B.C.