

Douglas County Surveyor's Record of  
Government Corners Renewed

29

T. S.

9

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97198

29

$\frac{1}{4}$  corner to secs. 34 and 35.

Found 4 inch x 4 inch sq. post at corner & both original BTs, now snags.

I open Southwest BT and find scribing  $\frac{1}{4}$  S BT and Northeast BT scribed "BT".

Set an iron pipe with brass cap at corner mkd.  $\frac{1}{4}$  S 34/35 T29S R9W, County Surveyor's Office, 1957.

From which:

20 inch W. Fir bears N.  $54\frac{1}{2}^{\circ}$ E., 274.5 feet scribed  $\frac{1}{4}$  S 35 CS BT.

24 inch Cedar stump, N.  $68^{\circ}$ W., 59.4 feet scribed  $\frac{1}{4}$  S 34 CS BT.

James W. Byron, Deputy County Surveyor.  
April 5 - 9, 1957.  
C. S. File No. 47/173.

30

Section corner to secs. 13, 14, 23 and 24.

Found  $\frac{3}{4}$  inch iron pipe at corner and all BTs. The SW is standing-has been opened years ago-no scribing visible-was probably bark scribed. The NE and SE show bark scribing. The NW BT has old blaze - under. The NW, SE and NE BTs down. All four BTs check for bearing and distance.

Set an iron pipe with brass cap at corner mkd. Sec. cor.  $\frac{14}{23}$  |  $\frac{13}{24}$  T29S R9W, County Surveyor's Office, 1957.

From which:

12 inch W. Fir bears S.  $58^{\circ}$ E., 26.7 feet scribed S 24 T29S R9W CS BT.

12 inch W. Fir bears S.  $70^{\circ}$ W., 22.8 feet scribed S 23 T29S R9W CS BT.

10 inch Cedar, bears N.  $9^{\circ}$ E., 57.4 feet scribed S 13 T29S R9W CS BT.

12 inch W. Fir bears N.  $56^{\circ}$ W., 62.8 feet scribed S 14 T29S R9W CS BT.

*1/10/57  
M 25-75  
E. Blum*

31

$\frac{1}{4}$  corner to secs. 33 and 34.

Found 30 inch Fir snag-old blaze opened near base, good scribing found, N.  $88^{\circ}$ W., 34.3 feet. Also found 3 inch x 3 inch sq. stake at corner mkd.  $\frac{1}{4}$  S.

Set an iron pipe with brass cap at corner marked Coos Co. Douglas County Surveyor's Office,  $\frac{33}{4}$  |  $\frac{34}{4}$  cor., 1957.

From which:

28 inch Cedar bears N.  $85^{\circ}$ W., 22.2 feet, scribed  $\frac{1}{4}$  S 33 D CS BT.

6 inch Cedar bears S.  $20^{\circ}$ E., 14.8 feet scribed  $\frac{1}{4}$  S 34 CS BT.

*PND. OK  
4/9/57 M 113-20  
3146 Hoffman  
M 123-59*

32

Section Corner to Section 27, 28, 33, & 34.

Found- All four BTs. as recorded by Porter, 1907, all check for bearings except N.W. BT should be N  $68^{\circ}$ W. All check for distances. The N.W. BT now 48 inch Fir stump, only bark scribed. The S.W. BT now 15 inch dead Alder open & good scribing. The N.E. BT grown over. I do not open. The S.E. BT now 36 inch Fir. Dead snag shows good bark scribing. Also find 24x4x4 inch Fir stake scribed for corner. Bears N  $70^{\circ}$ W 2.0 feet from corner.

Set Brass Cap at corner marked Douglas County Surveyor's Office,  $\frac{28}{3}$  |  $\frac{27}{3}$  T29S, R9W, 1957  $\frac{33}{3}$  |  $\frac{34}{3}$  c.

From Which:

10 inch Hemlock bears S.  $57^{\circ}$ E 38.5 feet S34, T29S, R 9W, CS BT.

14 inch Maple bears S.  $56^{\circ}$ W 23.3 feet S 33, T 29S, R 9W, CS BT.

15 inch W. Fir bears N.  $54^{\circ}$ W 54.6 feet S 28, T 29S, R 9W, CS BT.

**RENEWED - SEE CORNER NO. #100**

James W. Byron  
M. Godfrey  
J. Fee  
July 16, 1957  
C.S. File No. 49/7

33

R9W.  $\frac{36}{1}$  |  $\frac{31}{6}$  T 28 S.  
T 29 S.

Renew Township Corner: Found -  $\frac{3}{4}$  inch iron pipe at corner & one original BT, 15 inch now 24 inch rotted stump N.  $86\frac{1}{2}^{\circ}$ W., 23.8 feet. Good scribing on chip of old face. This corner renewed by C.A.S. (Coos Head Tbr. Co.) August, 1956 per notes on yellow tag. Original BT checks bearing & distance to  $\frac{3}{4}$  inch iron pipe.

I find these BTs. (scribed, 1956):

7 inch R. Fir S.  $8^{\circ}$ W., 22.8 feet scribed BT S 1, T 29 S, R 9 W.

6 inch R. Fir N.  $76\frac{1}{2}^{\circ}$ E, 21.0 feet scribed BT S 31, T 28 S, R 8 W.

24 inch Cedar N.  $3^{\circ}$ E., 86.9 feet scribed BT S 31, T 28 S, R 8 W.

James W. Byron  
M. Godfrey  
J. Fee  
Sept. 10, 1957  
C.S. File No. 49/12

34

Section Corner to Sections 11, 12, 13, & 14.

Found - Orig. N.W. BT., shows good bark scribing. Now Shag.

All other Orig. BT's. would be in existing Roadways.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1958 T29S R9W -  $\frac{S11}{S14}$  |  $\frac{S12}{S13}$ .

New BT's: 10" W. Fir bears S.  $63^{\circ}$ E. 56.3 ft. scribed S13 T29S R9W CS BT.

9" W. Fir bears S.  $31\frac{1}{2}^{\circ}$ W. 133.3 ft. scribed S14 T29S R9W CS BT.

8" W. Fir bears N.  $21\frac{1}{2}^{\circ}$ W. 42.7 ft. scribed S11 T29S R9W CS BT.

10" W. Fir bears N.  $48^{\circ}$ E. 3.3 ft. scribed S12 T29S R9W CS BT.

*1/10/57  
M 25-75  
E. Blum*

James W. Byron, Deputy  
M. Godfrey  
S. Blom  
May 21, 1958  
C.S. File No. 49/7