

Douglas County Surveyor's Record of
Government Corners Renewed

29 T. S. 9 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

D. BONTZ

$\frac{1}{4}$ Section Corner to Sec. 36, T29S R9W, & Sec. 31 T29S R8W. FD OK 2-97 35
MIZL-39
REN. #15
Found - Fir Stump, now 28" diam. S.33°E. 21.8 ft. Chopped out
Lower blaze & found "BT"
Fir Stump, now 48" diam. N.42°W. 5.9 ft. Lower scar has
been chopped into but not opened to original blaze. FD OK PER PIESKE
JAN 1986 M101-13
Found more recent bark scribing " $\frac{1}{4}$ CS".
Set Brass Cap at Corner Mkd: R9W S36/S31 R8W T29S County Surveyor's
Office, 1958
New BT's: 12" W. Fir N.11°E. 32.3 ft. scribed " $\frac{1}{4}$ S31CS BT".
8" W. Fir S.28°W. 13.0 ft. scribed " $\frac{1}{4}$ S36 CS BT".

Township Corner T29S-T30S, R8W-R9W. 36
Found - Sugar Pine Tree, now 45" At Two. Corner.
Sugar Pine, now 45" N.80°E. 3.3 ft.
D. Fir, now 25" diam. S.88°W. 18.5 ft. Cut into this tree
to expose part of upper blaze. Found good scribing "W" &
"S 36".
Fir Stump, now 40" diam. N.50°W. 48.2 ft. Opened Lower scar
but found only charred face.
Remains of badly rotted Laurel Stump S.10°E. 46.2 ft.
Set Brass Cap 10 ft. North of True Corner for Witness Corner Mkd:
T29S
R9W $\frac{S36}{S1} | \frac{S31}{S6}$ R8W "County Surveyor's Office, 1958
W. C. Corner 10 ft. S. FD 1976
BLM - SEE
GIS FILE
Blaze &
T30S
Scribe: 16" D. Fir S.49 $\frac{1}{2}$ °W. 27.5 ft. Mkd. "T30S R9W W.C. S 1 CS BT".
24" D. Fir N.60°W. 32.6 ft. Mkd. "T29S R9W W.C. S36 CS BT".
45" S. Pine (N.E. BT. for true Corner) S.25°E. 10.0 ft.
Mkd: "T30S R8W W.C. S 6 CS BT".
19" W. Fir N.73°E. 33.4 ft. mkd: "T29S R8W W.C. S31 CS BT".

$\frac{1}{4}$ Section Corner to Sections 11 & 12. 37
Found - Orig. 9", now 30" W. Fir N.78°E. 7.9 ft. I open near base,
& find good scribing "BT".
Orig. 15", now 30" Fir, down & partly rotted, checks bearing
& distance S.77°W. 23.8 ft.
Set Brass Cap at Corner Mkd: $\frac{1}{4}$ S11/S12 T29S R9W County Surveyor's
Office, 1958.
New BT's: 12" W. Fir bears S.64°W. 18.7 ft. scribed $\frac{1}{4}$ S11 CS BT.
12" W. Fir bears S.40 $\frac{1}{2}$ °E. 34.1 ft. scribed $\frac{1}{4}$ S12 CS BT.

 $\frac{1}{4}$ Section Corner to Sections 1, T29S R9W & Sec. 6, T29S R8W. 38
Found - Orig. 12", now 28" Fir Stump Corner Tree shows old scars. I
do not open.
Orig. 9", now 24" Fir Stump N.75°W. 13.9 ft. I open & find good
scribing "BT".
No trace of Orig. N. E. BT.
Set Brass Cap for Wit. Cor. to $\frac{1}{4}$ Corner Mkd. Brass Cap, Wit. Cor.
5' South to $\frac{1}{4}$ S1/S6 T29S County Surveyor's Office, 1958.
R9W R8W
New BT's: 12" R. Fir bears N.55 $\frac{1}{2}$ °W. 38.0 ft. scribed WC $\frac{1}{4}$ S1 CS BT.
12" R. Fir bears S.50°E. 76.9 ft. scribed WC $\frac{1}{4}$ S6 CS BT.

Section Corner to Secs. 12 & 13, T29S R9W, & Secs. 7 & 18, T29S R8W. 39
Found - Orig. 12", now 24" Cedar S.12°E. 36.3 ft., previously opened,
shows good scribing "S18T29SR8W BT".
Rotted Fir on ground that checks bearing & dist. for Orig. SW. BT.
No trace of Original N.E. or N. W. BT's.
Set Brass Cap at Corner Mkd: $\frac{S12}{R9W} | \frac{S7}{S18}$ T29S County Surveyor's Office,
R8W 1958
New BT's: 10" W. Fir bears N.72°E. 19.7 ft. scribed S7 T29S R8W CS BT.
10" W. Fir bears S.42°W. 41.4 ft. scribed S13 T29S R9W CS BT.
4" Hemlock " N.34°W. 3.4 ft. scribed S12 CS BT.

James W; Byron, Deputy
M. Godfrey
S. Bilow
July 16, 1958
C. S. File No. 49/100

James W. Byron, Deputy County Surveyor
Chairmen: Milo Godfrey
S. A. Bilow
September, 1958
C. S. File No. 49/100