

Douglas County Surveyor's Record of
Government Corners Renewed

29 T. S. 9 R. W. W. M.

KOKE-CHAPMAN CO. EUGENE, ORE. 21881

James W. Byron, Deputy County Surveyor
Milo E. Godfrey
Clet Putnam
September 28, 1959
C. S. File No. 49/100

$\frac{1}{4}$ Section Corner to Sections 11 and 14.
Found - Orig. 20", now 40" R. Fir North 42.2 ft., shows good bark scribing " $\frac{1}{4}$ " S"
Orig. 10", now 26" Fir S. 21° W. 26.4 ft., shows scar. I do not open.
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959
 $\frac{1}{4}$

S11	T29S R9W
S14	

 ADD BLM 1966
New BT's: 12" R. Fir bears South 35.9 ft. scribed $\frac{1}{4}$ S14 CS BT.
8" Hemlock " N. 49° W. 2.9 ft. scribed $\frac{1}{4}$ S11 CS BT.

RE-RENEWED, SEE CORNER NO. # 98

FD. 1/84
M 95.75
E. Bloom
Vol. 30, Pg. 14029

45

Section Corner to Sections 10, 11, 14 and 15.
Found - 3 Original Bearing Trees as follows:
Orig. 30", now 36" Fir N. 5° E. 35.6 ft., I open & find good scribing.
Orig. 15", now 30" Fir S. 45° E. 22.4 ft., shows good scar, I do not open.
Orig. 40", now large & rotted Fir Stump S. 60° W. 116.2 ft., No scribing found.
No trace of Original N.W. BT. found.
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959

S10	S11	T29S R9W
S15	S14	

New BT's: 13" R. Fir bears N. 52° E. 12.5 ft. scribed S11 T29S R9W CS BT.
7" R. Fir bears N. 55° W. 14.5 ft. scribed S10 CS BT.
10" R. Fir bears S. 29° W. 34.6 ft. scribed S15 T29SR9W CS BT.

46

$\frac{1}{4}$ Section Corner to Sections 23 and 26.
Found - 1" Square Shaft at Corner and (SEE REN. NO. 12)
60" Fir Stump S. 31 $\frac{1}{2}$ ° W. 61.5 ft., no scribing found, stump cut low.
Find Root System of large Fir that checks bearing & distance for N. W. BT.
I do not set Brass Cap at Corner.
New BT's: 24" Fir bears S. 29 $\frac{1}{2}$ ° W. 147.0 ft. scribed $\frac{1}{4}$ S26 CS BT.
7" Fir bears N. 27° W. 112.5 ft. scribed $\frac{1}{4}$ S23 CS BT.

47

$\frac{1}{4}$ Section Corner to Sections 14 and 15.
Found - Both Original BT's as follows:
Orig. 12", now 18" Fir N. 62° E. 44.9 ft., I open & find good scribing "1 S".
Orig. 10", now 16" down Fir S. 51° E. 35.6 ft., shows old face badly burned, no scribing found.
Set 2" Iron Rod at corner, which is on top of N. 45° W. Spur and center of Jeep Road.
New BT: 22" R. Fir bears S. 3 $\frac{1}{2}$ ° E. 30.6 ft. scribed $\frac{1}{4}$ S14 CS BT.

RE-RENEWED, SEE CORNER NO. # 79

48

$\frac{1}{4}$ Corner to Sections 22 and 23.
Found - Orig. 20", now 40" Fir S. 50° W. 7.9 ft, now down, shows good bark scribing " $\frac{1}{4}$ ".
No trace of Original N. E. BT.
Set Brass Cap at Corner Mkd: $\frac{1}{4}$ S22/S23 T29S R9W County Surveyor's Office, 1959
New BT's: 12" Cedar bears N. 27° E. 94.0 ft. scribed $\frac{1}{4}$ S23 CS BT.
12" W. Fir bears S. 29 $\frac{1}{2}$ ° W. 71.0 ft. scribed $\frac{1}{4}$ S22 CS BT.

49

$\frac{1}{4}$ Section Corner to Sections 15 and 22.
Found - Orig. 8", now 18" Maple North 6.6 ft., shows old scars, I do not open. Orig. 50", now 56" Fir S. 80° E. 17.2 ft., I open & find good scribing "S22"
Set Brass Cap at Corner Mkd: $\frac{1}{4}$

S15	T29S R9W
S22	County Surveyor's Office, 1959

 # 107
Note - Corner on Sandstone Ledge, I excavate Hole about 6" deep and Concrete Pipe in Place.
New BT: 18" Cedar bears S. 55 $\frac{1}{2}$ ° E. 42.7 ft. scribed $\frac{1}{4}$ S22 CS BT.

RE-RENEWED, SEE CORNER NO. # 107

50