

Douglas County Surveyor's Record of
Government Corners Renewed

T 29 S T. S. R 9 W R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 91881

James W. Byron, Deputy County Surveyor
Milo Godfrey
Clete Putnam
October, 1959
C. S. File No. 49/100

(continued)

#55

Blaze & Scribe New Trees as follows:

- 8" Fir N.17 $\frac{1}{2}$ °W. 40.1 ft. scribed $\frac{1}{4}$ " S12 CS BT".
- 9" Fir S.82°W. 42.6 ft. scribed $\frac{1}{4}$ " S13 CS BT".

56

Section Corner to Sections 2, 3, 10 and 11.

Found - Fir Tree, 28" diam., S.58°E. (instead of S.65°E.) 19.1 ft.,
Bark Scribing - old - visible "T29S R9 S1". Scar below
suggests "BT" possibly in wood. This tree has been
rescribed in bark more recently "T29S R9W S11 BT",
Looks 10 to 20 yrs. old.

Fir Tree, now 22", N.45°E. 38.9 ft., showing bark scribing
on upper blaze. Has been knocked off by falling rock
but portions of bark scribing remain "BT" plainly visible.
Also shows lower scar. A Rock, 8 ft. x 5 ft. x 3 ft. is
lodged against West Side of Tree. (Rescribed this Tree)
Remains of N.W. & S. W. BT's. - both down, uprooted, which
fit notes for bearing & distance as well as can be determined.

At Corner Set Iron Pipe with Brass Cap Mkd, "County Surveyor's Office
1959 T29S R 9W

S 3	S 2
S10	S11

FD. 1980 BLM Admin.
Survey - REGIS
FILE

- Blaze & Scribe 2 New BT's: 6" Hemlock N.45°W. 5.7 ft. "S3 CS BT."
- 8" Hemlock S. 1°W. 22.0 ft. "S10 CS BT."

$\frac{1}{4}$ Section Corner to Sections 2 and 11.

57

Found - Both Original BT's:

- Orig. 30", now 65" R. Fir S.55°W. 10.6 ft., shows old
scar below & old bark scribing above $\frac{1}{4}$ " S11.
- Orig. 20", now 48" R. Fir N.55°W. 56.4 ft. (record N.55°W.
33.7 ft.) shows good bark scribing above $\frac{1}{4}$ " S11 & old
scar below. East BT. has been rebark scribed about
20 years ago, more or less.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959

$\frac{1}{4}$ S 2	T29S R9W
S11	

- New BT's: 13" Hemlock bears N.52°E. 22.4 ft. scribed $\frac{1}{4}$ " S2 CS BT.
- 9" Cedar bears S.32°E. 27.0 ft. scribed $\frac{1}{4}$ " S11 CS BT.

RE-RENEWED SEE CORNER #99

James W. Byron, Deputy, etc.
October 13, 1959
C. S. File No. 49/100

Section Corner to Sections 21, 22, 27, and 28.

58

Found - Rotted Stump of old Corner Tree, no scribing visible.

Maple Tree, now 15", N.52°E. 44.9 ft. (slope dist.) with
old rotted face exposed. Fragments of unmistakable scrib-
ing visible.

Yew Tree, now 16", with face opened, scribing "T29S R9W S21 BT"
plainly visible. Yew bears N.11°W. 29.4 feet.

The Fir to the S.W. is uprooted & nearly completely buried in
ground. Did not open.

Badly rotted remains of Fir Stump bears S. 7°E. 25 feet., No
face or scribing visible.

At Corner Set Iron Pipe with Brass Cap, alongside of old Hemlock Stump,
Mkd: Douglas County Surveyor's Office, 1959

S21	S22	T29S R9W
S28	S27	

- Blaze & Scribe new Trees: 20" D. Fir S.71°E. 25.9 ft. mkd. T29S R9W S27 CS BT.
- 24" D. Fir N.32°E. 119.0 ft. mkd. T29S R9W S22 DCSET.

59

Section Corner to Sections 26, 27, 34, and 35.

Found - Orig. 24", now 32" Fir Stump N.14°W. 27.7 ft., previously
opened near base, shows good scribing "BT".

Orig. 24", now 32" Fir Stump S.55°W. 10.6 ft. I open & find
good scribing "BT".

No trace of S.E. Or S.W. BT. found.

Set Brass Cap at Corner Mkd: T29S R9W S27 | S26 Douglas County
Add B.L.M. 1966 Vol. 30, Pg. 14029 S34 | S35 Surveyor's Office, 1959.

- New BT's: 10" W. Fir bears N.80°W. 45.9 ft. scribed S27 T29S R9W CS BT.
- 7" W. Fir bears S.53°W. 23.8 ft. scribed S34 T29S R9W CS BT.
- 14" Maple bears S.55°E. 29.5 ft. scribed S35 CS BT.
- 10" Fir bears N.62 $\frac{1}{2}$ °E. 88.5 ft. scribed S26