

Douglas County Surveyor's Record of  
Government Corners Renewed

29

T. S.

9

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Ronald E. Stuntzner  
For: Dr. & Mrs.  
Keizer  
Feb. 1977  
M 63 - 61

South 1/4 Corner for Sec. 36  
Found - 2" I.P. at S 1/4 Sec. 36. Ren. #16  
30" D.F. S.15°W., 46.5 ft. (windfall)  
Remains of 12" D.F. N.k8°E., 40.0 ft.  
New BT's-14" W.F. S.83°W., 30.6 ft. tagged.  
12" W.F. N.13°E., 14.5 ft. tagged.

*FD ok  
D. Benz  
2/97  
M 126-39 89*

2/77

Howard Johnstone  
For: Roseburg  
Lumber Company  
March 8, 1978  
M 65 - 76

Center 1/4 Corner for Sec. 2  
Set - 5/8" Iron rod with Alum. cap stamped 1978  
BT's - 30" Cedar bears S.74°E., 8.8 ft.  
7" Hemlock bears S.28°W., 27.1 ft.

90

3/8/78

Witness Corner for 1/4 Corner for Secs. 3 and 2.  
Set - Witness corner 5 ft. North of true corner.  
Set - 5/8" Iron rod with alum. cap stamped 1978  
BT's 9" Cedar bears N.34°E., 29.0 ft.  
18" Cedar bears S.83°W., 18.5 ft.

91

3/8/78

Gregory Quibell,  
Deputy, Douglas Co.  
Surveyors Office  
Debbie Stewart  
Witness: Sam Bright  
(landowner)  
April 13, 1981  
C.S. 61/19

Section corner for 13 and 24; and Secs. 18 & 19 of T.29-8  
Found - Both of Coles 1920 reference stones buried in their original  
location. Dist. & Brg. between two stones match record exactly.  
1958 DCSO Wit. corner had been knocked out and was at Mr. Harold  
Bright's house. See Ren. #13-40  
16" now 19" W. Oak (in a group of 9 oaks) with well healed double  
blaze bears S.43 1/2°E., 304.8 ft. (Rec. 320.2 ft.) from sec.  
cor. location. Ren. #13-40

92

All original bearing trees are gone.  
Set - Boat spike in asphalt concrete near center of road for section  
corner. Corner was set on line at proper distance between 1920  
stones.  
Brass cap witness corner was set 16 ft. east of section corner  
marked: "Wit. Cor. 16 ft. West to sec. cor. R9W R8W S13 S18  
S24 S19 T29S 1981 Douglas County Surveyor" Brass cap was set  
1 ft. west of easterly stone, 1 1/2 ft. west of old fence., and  
is 8" out of ground.  
New BTs - 48" Cedar with scribed "T29S R9W S24 CS BT" in single blaze bears  
S.89°W., 496.9 ft. to face.  
Power pole #1C 17 11 bears N.11 1/2°W., 114.5 ft.

Survey marker sign bears east 17.5 ft.

4/13/81

Larry E. Monrean, Deputy  
Douglas County Surveyor  
D.L. Stewart, witness  
August 11, 1981  
C.S. 61 / 27

1/4 corner for Sec's. 26, & 27.  
Found -(Orig. 1/4 Sec. post NOT fnd)  
Fnd. a 3/4" (ID) x 30" (Rec. 1" x 30") I.P. Ren. # 11.  
BT's - 31" Dia. Cedar stump (Rec. 30") bears S.60°E., 19.1-ft. No  
blaze or scribing found.  
Dead windfall (orig. 10" Cedar) bears N.62°E., 14.5-ft. Ren.#11.  
with scribed BT visible. Ren.#63.  
20" W. Fir (orig. 8") with well healed blaze bears S.5°E., 48.3-ft.  
22" W. Fir (orig. 9") with well healed blaze bears S. 6 1/2 ° W.,  
68.0-ft. Ren.#76.  
Set - Brass Cap on a 1" x 30" I.P., stamped: Douglas County Srveyor  
T29S R9W 1/4 S27 | S26 1981 . Re-set the fnd 3/4" I.P. alongside.  
New BT's  
- 10" W. Fir blazed and scribed 1/4 S27 CS BT bears N.39 1/2 ° W.,  
62.7-ft.  
14" W. Fir blazed and scribed 1/4 S26 CS BT bears N.75°E., 49.5-ft.  
Note: monument is 3 1/2 ft. East of a N-S fence.

93

8/11/81