

Douglas County Surveyor's Record of
Government Corners Renewed

T 29 T. S. R 9 R.W.W.M.

FOKE-CHAPMAN CO., EUGENE, ORE. 91881

100

Section Corner for Secs. 27, 28, 33 and 34

Found - (Original Post not found) (See also Ren. #32)
Found a 2" x 3" x 2 ft. post with faint scribe marks lying loose on top of ground.
Found 1957 J. Byron monument, a 1" x 36" iron pipe with brass cap properly marked. Monument is leaning northeasterly. We find and use a wooden hub located at the probable plumb position of monument to measure to accessories found.
Orig. 24" Fir now a 5 ft. dia. decayed stump with fragmentary reverse scribing in previously open blaze bears N.66½°W., 27.5 ft. (Rec. N.78°W., 27.1 ft.)
Orig. 12" Fir now a 36" dia. stump approx. 10 ft. high with bark scribing "29S R9W 3" visible and well healed lower blaze bears S.73°E., 114.1 ft.
1907 Resurvey, 10" now 20" Maple with well healed single blaze bears N.57½°E., 15.6 ft. (Rec. N.80°E., 13.9 ft.)
Byron 1957 10" now 20" Hemlock with well healed single blaze bears S.59°E., 38.5 ft. (Rec. S.57°E.)
Byron 1957 14" now 20" Maple with well healed single blaze bears S.54½°W., 24.0 ft.
Byron 1957 15" now 37" Fir with well healed single blaze bears N.53½°W., 54.3 ft. (Rec. N.54°W., 54.6 ft.)

Note: All measurements taken to estimated center of root crown of BTs.
Set - We remove Byron's Brass cap monument and SET a 5/8" x 30" iron rod with alum. cap at plumb position of monument (as mkd. by wooden hub). Alum. cap is marked "Douglas Co. Surveyor". We reset the brass cap monument at location agreeing with original bearings and distances to original bearing trees. Monument is set with 7" above ground. We stamp the additional wording "RESET 1991" on cap. From this monument, the old location as marked by iron rod and alum. cap bears S.17½°W., 5.66 ft.

New Accessories:

Orig. 5 ft. dia. stump bears N.78°W., 27.1 ft.
Orig. 36" Fir stump bears S.70°E., 115.5 ft.
1907 Resurvey 20" maple bears N.75°E., 11.8 ft.
Byron's 1957 20" hemlock bears S.51½°E., 40.4 ft.
Byron's 1957 20" Maple bears S.50°W., 27.6 ft.
Byron's 1957 37" Fir bears N.59½°W., 52.4 ft.

(See sketch in C.S. File 64/15

6/3/91

Section Corner for Sec. 13 & 24; and 18 & 19 of T.29S R8W.

101

Found - Original & stone monument from Ren. #13 NOT found.
Magnetic evidence indicates boat spike in asphalt roadway from Ren. #40 is in place but is now buried below surface shallowly.
All bearings & distances measured from above mentioned monument:
No evidence of 2 rocks from Ren. #13 found. West rock would fall under roadway and east rock not dug for, in order to not disturb brass cap & I.P. from Ren. # 92.
No evidence of witness corner from Ren. #40 found.
A 16" Oak now a 20" diameter breast high White Oak w/fully healed dbl. blaze, in a tight group of 9 oaks, now all fallen & soon to be removed, bears S.43½°E., 304.8 ft. as per Ren. # 92.
From Ren. # 92 a brass cap/I.P. bearing object (erroneously called a witness corner), a bearing tree, & a power pole bearing object are all found.
A 2½" dia. brass cap marked "Douglas County Surveyor" on a 1½" outside dia. I.P. is firmly set, protruding 8" above ground & bears East, 16.0 ft. (as per Rec.) A survey marker sign bears 1½' East from brass cap monument.
A 48" now 52" dia. breast high Cedar w/fully healed single blaze bears S. 88½°W., 498.7 ft. (Rec. S.89°W., 496.9 ft. to face).
A power pole # 1C 17 11 bears N.12½°W., 113.5 ft. (Rec. N.11½°W., 114.5 ft., probably to older power pole as found pole appears new.)

CONTINUED NEXT PAGE - - -

Douglas County Surveyors Office

Larry E. Monrean, Deputy

Randall Smith

June 3, 1991

C.S. File 64/15

(See also, Coos Co. Survey

by Torbeck, filed as M 113 - 20)

Douglas County
Surveyor's Office
Randall W. Smith
Stephen J. Flause
November 4, 1992
C.S. 64/35