

Douglas County Surveyor's Record of  
Government Corners Renewed

T 29 S T. S. R 9 W R. W. W. M.

FOKE-CHAPMAN CO., EUGENE, ORE., 2181

105

1/4 Corner for Sections 22 and 27 continued

Accessories Found -

A Fir, 12" dia. now a 24" dia. 3 ft. tall rotted Fir stump with remains of a healed blaze, now opened to reveal partial illegible scribing, bears N.22°W., 9.3 ft. (rec. per ren. #54: N.22°W., 9.0 ft.) O.B.T.

The bearing tree marked in ren. #54, a 16" R.Fir, now a 24" dia., low cut Fir stump with possible remains of lower blaze edge, bears N.23 3/4°W., 44.4 ft. (rec. per ren. #54: N.22°W., 41.4')

The bearing tree marked in ren. #78, a 17" Fir, now 19" D.B.H. Douglas Fir with a fully healed double blaze, bears S.10°W., 33.5 ft. (as per record)

New Accessories -

A 10" D.B.H. Douglas Fir scribed "¼ S22 CS BT" on a double blaze, bears N.36°E., 13.1 ft.

A 17" D.B.H. Douglas Fir scribed "¼ S27 CS BT" on a double blaze, bears S.49°E., 72.1 ft.

A 9" D.B.H. Madrone scribed "¼ S22 CS BT" on a double blaze, bears N.25°W., 41.0 ft.

Note - Monument lies approx. 25 ft. north of abandoned logging road running easterly-westerly. See sketch in C.S. File

1/4 Corner for Sections 21 and 22

Found - 3 1/4" BLM brass cap on a 2 1/2" O.D. iron pipe, protrudes 5" above ground (1978 BLM)

A probe of area around BC/IP was made, a stone was found along west edge of BC/IP approx. 4" below ground. Stone was not dug out. (original stone?)

Accessories Found -

4" now 9" dia. D.Fir with a fully healed blaze, bears N.38°W., 10.9 ft. to center of root crown (agrees with rec.). Record per 1996 J.Minor survey is N.44°W., 10.5 ft. fits well with center of trunk. Note: BT is a pistol Butt.

No other BT's were found.

New Accessories -

11" dia. Hemlock double blazed and scribed "¼ S21 CS BT" bears S.79°W., 28.4 ft.

8" dia. D.Fir double blazed and scribed "¼ S21 CS BT" bears S.53°W., 14.2 ft. to center of root crown.

4" dia. D.Fir double blazed and scribed "X BT" bears S.9 1/2°E., 13.6 ft.

Note - A large slide is northwesterly of corner.

1/4 Corner for Sections 15 and 22

Found - 2 1/2" dia. brass cap on a 1 1/2" O.D. iron pipe, concreted into a sandstone ledge. BC/IP protrudes 8" See renewal #50

Accessories Found -

Original Maple now gone.

50" now 56" dia. 12 ft. high burnt D.Fir snag, shows evidence of being opened. No scribing visible, bears S.80°E., 17.2 ft. (agrees with rec.) O.B.T.

18" now 27" dia. Cedar, with a fully healed double blaze, bears S.55 1/2°E., 42.7 ft. (agrees with rec.) ren. #50

New Accessories -

6" dia. D.Fir, double blazed and scribed "¼ S22 CS BT" bears S.30 1/2°E., 36.6 ft.

11" dia. Maple, double blazed and scribed "¼ S15 CS BT" bears N.73 1/2°W., 25.4 ft.

6" dia. Madrone, bark scribed "¼ S15 CS BT" bears N.69°E., 31.9 ft.

Note - Corner lies on a steep southerly facing rock bluff.

Douglas County  
Surveyor's Office  
Stephen Flause  
John Pike  
Oct. 15, 1996  
C.S. File 65/9-28

Douglas County  
Surveyor's Office  
Randall Smith  
Stephen Flause  
Oct. 22, 1996  
C.S. File 65/9-29

Douglas County  
Surveyor's Office  
Randall Smith  
Stephen Flause  
Oct. 23, 1996  
C.S. File 65/9-30

106

107