

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 29 $\frac{1}{2}$  S. T. S. R. 7 W. R. W. W. M.

KOBE-CHAPMAN CO., EUGENE, ORE. 97190

Section Corner T29 $\frac{1}{2}$ S  $\frac{S34}{S3}$  |  $\frac{S35}{S2}$  T29S R7W 10

Found - Brass Cap at Cor. & all BT's., except N.E. BT.  
New BT: 6" R. Fir bears N.39°E. 25.0 ft. scribed S35 CS BT.  
FD. O.K. H. JOHNSTONE 1980

$\frac{1}{4}$  Corner to Section  $\frac{S34}{S3}$  T29 $\frac{1}{2}$ S R7W 11

Found - Brass Cap at Corner & N.W. BT. S.E. BT., now stump.  
New BT: 14" R. Fir bears S.43°E. 41.6 ft. scribed  $\frac{1}{4}$  S 3 CS BT.  
FD. O.K. H. JOHNSTONE 10.80

Renew Section Corner  $\frac{S33}{S4}$  |  $\frac{S34}{S3}$  T29 $\frac{1}{2}$ S R7W 12

Found - Brass Cap at Corner. S.E. BT., now stump hole.  
S.W. BT., now dead. N.E. BT. down. N.W. BT. in poor condition.  
New BT's: 9" W. Fir bears S. 3°E. 10.8 ft. scribed S 3 T30S R7W CS BT.  
6" Fir bears S.70°W. 19.0 ft. scribed S4 CS BT.  
11" Cedar bears N.72°W. 18.7 ft. scribed S33 T29 $\frac{1}{2}$ S R7W CS BT.  
23" Pine bears N.19°E. 25.1 ft. scribed S34 T29 $\frac{1}{2}$ S R7W CS BT.

$\frac{1}{4}$  Corner to Sections  $\frac{S33}{S4}$  T29 $\frac{1}{2}$ S R7W 13

Found - Stone and Both BT's. as recorded, BT's now have Rotted Faces.  
New BT's: 0" R. Fir bears S.35°E. 8.0 ft. scribed  $\frac{1}{4}$  S 4 CS BT.  
7" Laurel bears N.17°E. 16.4 ft. scribed  $\frac{1}{4}$  S33 CS BT.

RE-RENEWED SEE CORNER NO. #22

Renew  $\frac{S32/S33}{S4}$  T29S R7W 14

Found - Brass Cap set in 1924 and Fir Stump bearing N.72°W. 10.6 ft.  
Cat Road where Laurel BT. would have been.  
New BT's: 13" Fir N.34 $\frac{1}{2}$ °E. 57.4 ft.  
15" Fir N.28°W. 88.8 ft. scribed T29S R7W S32 CSBT.

Renew North  $\frac{1}{4}$  Corner S33, T29 $\frac{1}{2}$ S R7W. 15

Found - Brass Cap set in 1924. S.E. BT. is a rotted stump,  
scribing ( $\frac{1}{4}$ S 33 T29 $\frac{1}{2}$  BT) visible.  
S.W. BT., down, shows good scar.  
New BT's: 11" Fir S.42°W. 28.5 ft. scribed N $\frac{1}{4}$  S33 CS BT.  
8" Cedar S.28°E. 48.4 ft. scribed N $\frac{1}{4}$  S33 CS BT.

Renew Section Corner  $\frac{S31}{S6}$  |  $\frac{S32}{S5}$  T29 $\frac{1}{2}$ S R7W 16

Found - 24" x 16" x 12" Stone at corner in mound of stones. 5 notches  
on E. face, 1 on W. ~~stone~~ face.  
14", now 20" Fir N.42°E. 9.2 ft. (re-scribed). T29 $\frac{1}{2}$ S R7W CS BT.  
12" Live Oak S.46°E. 7.9 ft. (rotted out)  
22" Fir S.45°W. 50.2 ft. (O.K.)  
46" Fir N.44°W. 37.0 ft. (O.K.)  
New BT: 5" Fir S.11 $\frac{1}{2}$ °E. 30.0 ft. scribed S 5 CSBT.

Renew Corners to  $\frac{S32}{S5}$  T29 $\frac{1}{2}$ S R7W 17

Found - Conglomerate Stone 5" x 12" x 6" above ground.  
 $\frac{1}{4}$  on N. side as recorded.  
8" Fir, now 14" S.12°E. 9.9 ft. (O.K.)  
32" Pine, now 36" N.34°E. 138.6 ft.  
Set - Brass Cap alongside Rock Mkd:  $\frac{1}{4}$   $\frac{S32}{S5}$  T29 $\frac{1}{2}$ S R7W Co. Surveyor's  
Office, 1962  
New BT: 8" Fir N.63°W. 13.0 ft. scribed  $\frac{1}{4}$  S32 CS BT.

James W. Eyrton, Deputy County Surveyor  
Dale McFarland and John Powell  
June 1962  
C. S. File No. 49/139