

Douglas County Surveyor's Record of
Government Corners Renewed

T. 30 S. T. S. R. 1 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

94
 $\frac{1}{4}$ Corner to Section 6 only, T30-1E.
 Found - No trace of Brass Cap nor S.E. BT., Corner falls in old skid road.
 10", now 13" D.Fir, N. 71° E. 11.2 ft., opened for scribe, "BT".
 Set - Brass Cap at Cor.Mkd: County Surveyor's R T 30 S R
 Office, 1968 1 $\frac{1}{4}$ S 6 1
 W E
 Reblazed & Rescribed:
 13" D.Fir N. 71° E. 11.2 ft. mkd. $\frac{1}{4}$ S 6 CS BT.
 New BT: 20" W.Fir S. 60° E. 13.4 ft. mkd. $\frac{1}{4}$ S 6 CS BT.
 Note - This corner lies 248.0 ft. N. of Sec. Cor. 1 & 12, T30-1W.

95
 Section Corner to Sections 6 and 7, T30-1E.
 Found - No trace of Brass Cap.
 22" W.Fir, now stump, N.67°E. 56.1 ft., opened for scribe "6 BT".
 48" D.Fir, now uproot stump, S. 75° E. 26.6 ft.(Rec. 13.9),
 opened for scribe "T30S".
 Chained dist. of 248.2 ft. btwn. $\frac{1}{4}$ Sec. 12 & Sec. Cor. Distance falls in
 uprooted stumps. Dug for old brass cap but not found.
 Set - Brass Cap at Cor.Mkd: County Surveyor's R T 30 S R
 Office 1 S 12 S 6 1
 1968 W S 7 E
 New BT's: 8" W.Fir S. 8° E. 5.0 ft. mkd. T30S R1E S7 CS BT.
 8" D.Fir N. 5° E. 82.7 ft. mkd. T30S R1E S 6 CS BT.
 14" D.Fir N. 10° W. 23.5 ft. mkd. T30S R1W S12 CS BT.

96
 $\frac{1}{4}$ Corner to Section 24 only, T30-1W.
 Found - Stone at corner, no marking.
 30" D.Fir, now snag, S. 75° W. 2.0 ft., shows scribing " $\frac{1}{4}$ S24".
 30", now 36" D.Fir, N. 58° W. 33.7 ft., shows good face.
 Set - Brass Cap at Cor.Mkd: County Surveyor's R T 30 S R
 Office 1 $\frac{1}{4}$ S 24 1
 1968 W E
 New BT: 24" D.Fir N. 85° W. 19.0 ft. mkd. $\frac{1}{4}$ S24 CS BT.
 Note - The Sec. Cor. of Secs. 18 & 19, T30-1E. lies 236 ft. N., see below.

97
 Section Corner to Sections 18 and 19 only, T30-1E.
 Found - Brass Cap, U.S. GLO, properly marked in 1923.
 22" D.Fir, now windfall, N. 2° E. 40.9 ft., shows good face.
 17", now 20" D.Fir S. 66° E. 11.9 ft., shows good face.
 New BT: 10" Cedar N. 10° E. 28.3 ft. mkd. "T30S R1E S18 CS BT".
 Note - The $\frac{1}{4}$ cor. of Sec. 24 only, see above, lies approx. 236 ft. South.

98
 $\frac{1}{4}$ Corner to Section 13 only, T30-1W.
 Found - No trace of Corner Stone.
 30", now 42" D.Fir, S. 3° W. 30.4 ft., shows scar.
 36", now 39" D.Fir, N. 66° W. 42.2 ft., opened for scribe "3".
 Set - Brass Cap at $\frac{1}{4}$ Cor.Mkd: County Surveyor's R T 30 S R
 Office, 1968 1W $\frac{1}{4}$ S 13 1
 LE
 Bearing Trees O.K. and Tagged - Corner on steep, north slope.

99
 Section Corner to Sections 7 and 18, T30-1E.
 Found - GLO Brass Cap, properly marked in 1923.
 26" D.Fir, now down, N. 64° E. 31.0 feet.
 8" D.Fir, now 13", S. 62° E. 56.8 feet.
 New BT: 23" D.Fir N. 63° E. 43.1 ft. mkd. T30S R1E S7 CS BT.
 Note - This corner lies on steep south slope.

100
 Section Corner to Sections 12 and 13 only, T30-1W.
 Found - Corner Stone, out of place.
 12", now 24" D.Fir, S.13°W. 70.0 ft., shows good scar.
 20", now 22" Pine, N.48°W. 7.3 ft., scribe visible.
 Set - Brass Cap at Cor.Mkd: County Surveyor's R T 30 S R
 Office 1 S 12 1
 1968 W S 13 E
 Bearing Trees O.K. & Tagged.
 Note - This corner lies 236.3 ft. S. of the $\frac{1}{4}$ Cor. Sec. 7, T30-1E which
 is a Brass Cap in good condition.

John M. Powell
 Frank Jones & W. Penley
 June & July, 1968
 C. S. File No. 54/59

SEE GOV'T
 PLAT FOR
 COR. ON.
 W.M. ALSO
 RENEWALS
 #128-129