

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 30 S. T. S. R. 1 W. R.W.W.M.

KOKE-CHARMAN CO., EUGENE, ORE. 21001

Section Corner to Sections 34 & 35, T30-1W. 101  
 Found - GLO Brass Cap at Corner, properly marked in 1923.  
 14", now 16" W.Oak, N.45°E. 33.7 ft. scribe visible "35".  
 18", now 36" D.Fir, S. 40° E. 4.0 ft., shows good scar.  
 18" D.Fir, now down, N. 80° W. 17.8 ft.  
 New BT: 12" D. Fir N. 32° W. 15.6 ft. mkd. T30S RLW S34 CS BT.  
 N. E. and S.E. Bearing Trees, O.K. and Tagged.  
 Note - This corner is on W. slope 207.5 ft. E. of Cor. Secs. 3 & 2, T31-1W.

Closing Corner to Sections 3 and 2, T31-1W. 102  
 Found - GLO Brass Cap at corner, properly marked in 1923.  
 40", now 40" D.Fir, S. 24° E. 15.8 ft., shows good scar.  
 38" D.Fir, now stob, S. 27° W. 9.2 ft., shows good scar.  
 New BT: 7" Maple S. 48° W. 29.5 ft. mkd. T31S RLW S3 CC CS BT.  
 S.E. BT. O.K. & Tagged.  
 Note - This corner lies on W. slope 207.5 ft. W. of Sec. Cor. 34 & 35, T30-1W.

$\frac{1}{4}$  Corner to Sections 14 and 13. 103  
 Found - U.S. G.L.O. Brass Cap, properly marked in 1923, from which:  
 13" Pine, now 15" Stump, N. 44  $\frac{3}{4}$ ° W. 167.0 ft., opened  
 & found scribing of "4".  
 No trace of SE. Bearing Tree.  
 New BT's: 8" Sugar Pine S. 41° E. 9.1 ft. mkd. " $\frac{1}{4}$  S13 CS BT".  
 7" D. Fir N. 45° W. 16.3 ft. mkd. " $\frac{1}{4}$  S14 CS BT".

$\frac{1}{4}$  Corner to Section 3 only, T31S-RLW. 104  
 Found - U.S. G.L.O. Brass Cap, properly marked in 1923, from which:  
 30" D. Fir, now snag, S. 84°W. 239.0(Rec.225.7) opened for scribe.  
 Reset - Brass Cap at Orig. Distance from  $\frac{1}{4}$  Corner of Sec. 34 only, T30-1W,  
 which is a Brass Cap in good condition, 180.2 ft. East of  $\frac{1}{4}$  corner  
 in a large mound of stone.  
 No trees within reason in South Quad.  
 New BT: 18" D.Fir N. 59° W. 129.0 ft. mkd.  $\frac{1}{4}$  S 3 CS BT.  
 Note - Mound of Stone 2x2x2, south 19.2 ft. of  $\frac{1}{4}$  Corner.  
 This corner lies on east slope, in a large opening, all rock.

Section Corner to Sections 12 and 13, T30-1W. 105  
 Found - U.S. G.L.O. Brass Cap, properly marked in 1923.  
 36", now 39" Pine S. 28° E. 103.0 ft., shows good scar.  
 Set - 24", now 30" Pine, N. 20° W. 87.8 ft., shows good scar. #175  
 New BT's: 15" D. Fir S. 41° W. 11.2 ft. mkd.  $\frac{1}{4}$  S13 CS BT.  
 8" D. Fir N. 15° E. 10.2 ft. mkd.  $\frac{1}{4}$  S12 CS BT.  
 Note - This corner lies approx. 50' S. of E-W fence post line and  
 west of N-S fence line, approx. 75.0 ft.

$\frac{1}{4}$  Sec. Corner to Sec. 19, T30-1W. and Sec. 24, T30-2W. 106  
 Corner established 1857 Gen.Land Office, survey by Hathorn.  
 Orig. survey states: Set Wooden Post for corner,  
 A Fir 36" diam. bears N.10°E. 8 lks.  
 A Fir 15" diam. bears N.15°W. 34 lks.  
 No corner evidence found.  
 Set - 2" x 30" I.P. with Brass Cap, stamped: 

R	T 30 S	R
2	$\frac{1}{4}$ S 24	S 19 1
W	O.L.S. 536	W

  
 New BT's: 16" Fir bears N.57°E. 19.4 ft. mkd. " $\frac{1}{4}$  S19 T30S RLW  
 20" Fir bears West 3.5 ft. mkd.  $\frac{1}{4}$  S24 T30S R2W.  
 Note - Also placed USFS bearing tree signs on both trees breast  
 high and facing the pipe monument.

John M. Powell  
 Frank Jones & W. Penley  
 July, 1968  
 C. S. File No. 54/59

Glenn S. Baughman  
 For: U.S. Forest Service  
 June, 1968  
 C.S. File M 36 - 11 & M 36-12