

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 30 S. T. S. R. 1 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

114

South  $\frac{1}{4}$  Corner to Section 35 only, T29-1W.  
Found - Stone - Fir Stump 50" N. 65° E. 25.50 ft.  
45" Fir, down, N. 60° W. 32.50 ft.  
Set - 2 $\frac{1}{2}$ " Aluminum Cap and 9" Fir N. 16° W. 14.5 ft.  
4" Fir S. 24° W. 16.00 ft.  
Nov. 1968 - Found, Aluminum Cap and 4" D. Fir S. 24° W. 16.0 ft. (Dead)  
9" D. Fir N. 16° W. 14.5 ft. (Down)  
Set - 8" D. Fir, N. 32° E., 19.9 ft.; Mkd. S $\frac{1}{4}$ -S35-BT.

RE-RENEWED, SEE CORNER NO. #238

115

Section Corner to 2 and 3 only, T30-1W.  
Found - 26" White Fir Stump, S. 86° W., 59.20 ft.  
30" Cedar Stump S. 85° E. 39.40 ft.  
Set - 2 $\frac{1}{2}$ " Aluminum Cap and 6" Fir S. 56° E., 22.45 ft.  
12" Fir S. 27° W. 27.50 ft.  
5" Fir, N. 20° W., 42.95 ft.  
F.D. OR. 117/77 - D. GAYLORD - Doug. Co. Deputy, C.S. 59/42

RE-RENEWED, SEE CORNER NO. #159

116

Section Corner to Sections 35 and 36 only, T29-1W.  
Found - Sugar Pine Stump (Corner)  
26" Sugar Pine, N. 35° E. 5.30 ft. (Down)  
16" Fir N. 53° W. 34.50 ft.  
Set - 2 $\frac{1}{2}$ " Aluminum Cap  
24" Fir N. 45° E. 13.70 ft.

RE-RENEWED, SEE CORNER NO. #230

117

Section Corner to Sections 2 and 1 only, T30-1W.  
Found - Brass Cap and 30" Hemlock, S. 40° W., 11.20 ft.  
Set - 32" Fir S. 46° E. 20.90 ft.  
28" Fir S. 60° W. 17.50 ft.  
34" Fir N. 41° 30' E., 45.80 ft.

RE-RENEWED, SEE CORNER NO. #226

118

$\frac{1}{4}$  Corner between Sections 1 and 2.  
Set - 2 $\frac{1}{2}$ " Aluminum Cap  
10" Cedar S. 41° W., 12.90 ft.  
12" Fir N. 59° E., 26.00 ft.

RE-RENEWED, SEE CORNER NO. #190

119

Section Corner to Sections 1 - 2 - 11 and 12.  
Found - 36" Fir S. 32° E., 21.10 ft.  
Set - 2 $\frac{1}{2}$ " Aluminum Cap  
7" Fir N. 44° 30' E., 22.15 ft.  
6" Cedar N. 2° W., 11.75 ft.  
6" Cedar S. 33° 30' W., 22.70 ft.  
12" Fir S. 05° 30' E., 23.85 ft.

Fd 7/16/86  
R. GEISLER  
C.S. 63/34

120

Closing Corner to Sections 9 and 10.  
Found - Stone, approx. size, with 3 notches, out of ground. No place where it is from, as corner falls in cat. trail.  
12" D. Fir, now down, S. 41° W. 36.3 ft., tree opened, scribe visible.  
No trace of S. E. Bearing Tree.  
Set - Brass Cap at Cor. Mkd. County Surveyor's Office  
1969 CC S 9 | S 10  
New BT's: 10" Cedar S. 67° W. 49.5 ft. mkd: T30S RLW S9 CC CS BT.  
18" D. Fir S. 62° E. 38.3 ft. mkd: T30S RLW S10CC CS BT.

RE-RENEWED, SEE CORNER NO. #155

8/15/69

121

$\frac{1}{4}$  Corner section 3 only.  
Found - Brass cap at  $\frac{1}{4}$  cor. mkd: County Surveyor's T30S RLW  $\frac{1}{4}$  S 3.  
See REN. #67 Office 1968 S10  
6" Hemlock S. 86° E. 11 ft. scribed  $\frac{1}{4}$  S10 CS BT.  
8" Hemlock N. 1° E. 16.3 ft. scribed  $\frac{1}{4}$  S30CS BT.  
Remarked brass cap to refer to sec. 3 only. Destroyed 6" Hemlock S. 86° E. 11 ft.  
New BT: 6" Hemlock N. 42° E. 11 ft. scribed  $\frac{1}{4}$  S3 CS BT.  
Jan. 15, 1970

Thomas E. Shrum, Jr.  
For U. S. Plywood - Champion Papers, Inc.  
June, 1967 - Filed July, 1968  
C. S. File No. 55/106 Map M 36 - 14

John M.  
Powell  
& Crew  
C.S. File  
No.  
54/59