

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 30 T. S. R 1 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21081

Dennis Gaylord, U.S.F.S.
Deputy- Douglas County Surveyors Office
Witness - Randal Lopez
November 17, 1977
C.S. 59/42

William Ruppert
Witness: D. Stringer
For: U.S. Forest
Service
Sept. 1, 1977
C.S. 58/156

158

1/4 Corner for Sections 3 and 2.
Found - Stone, 12"x10"x6", set solidly in the ground, marked "1/4"
on the N.W. face.
A 23" Cedar stump bears S.70°W., 43.2 ft. (Rec. 43.56 ft.)
Traces of scribing visible on burned face.
A 45" D. Fir, bears N.25°E., 29.6 ft. (Rec. 32.34 ft., slope
dist. is 32.5 ft. at 45%) Has a healed blaze.
Set - Moving the stone aside, I set in its place a 2 1/2" brass cap
on a 1" I.P. marked: County Surveyors Office T 30 S R 1 W
1977 1/4 S 3 S 2
I buried the corner stone alongside.
New BT - A 13" Yew bears N.81°W., 11.2 ft. scribed "1/4 S3 CS BT" on a
double blaze.
Placed County BT signs on all three accessories.

11/17/77

159

Section Corner for Secs. 3 and 2 only. (North)
Found - 2 1/2" Alum. cap stamped US.P.C. Prop. Cor. 1967 Do not disturb
T30S RLW $\frac{35}{3 \overline{) 2}}$ RE 4287 Ren. #115
Orig. Cedar now a 32" stump bears S.85°E., 38.6 ft. (Rec. 39.4 ft.)
scribing visible "RLW S2 B" on a partly healed blaze.
A 8" D. Fir bears S.56°E., 22.5 ft. Has a single healed blaze.
A 15" D. Fir bears S.27°W., 27.0 ft. (Rec. 27.5 ft.) Some scribing
visible on a nearly healed blaze.
A 8" D. Fir bears N.20°W., 42.6 ft. (Rec. 42.95 ft.) Scribing
visible "5 BT T29S RLW". The orig. BT to the SW is gone.
I placed BT signs on all accessories.
DID NOT RENEW.
This corner lies on a very steep west slope.

11/17/77

160

Section Corner for Secs. 34 and 35 only, T.29-1.
Found - Stone, 8"x8"x10" above ground surface. Stone is solidly set &
marked with 2 notches on the east edge and 4 notches on the
west edge.
A 2 1/2" Alum. cap on a 3/4" I.R. is set so the cap is over the
SW edge of the corner stone. The Al. cap, not of record, is
stamped 1967 U.S.P.C. Prop. Cor. RE 4287 34 35 3 T29S RLW
Do not disturb.
The orig. 48" now 53" D. Fir bears N.59 1/2°W., 56.8 ft. Has a
healed scar. This tree is almost dead.
Orig. BT to the NE is down & well decayed. Stump hole bears N.58°E.
12.54 ft.
Bearing trees not of record, as follows:
A 14" D. Fir bears N. 1 1/2°W., 14.5 ft. Has a single healed blaze.
A 23" W. Fir bears N.49°E., 30.7 ft. Some scribing visible on a
nearly healed blaze.
A 6" D. Fir bears S.29 1/2°W., 7.0 ft. scribing visible on a
single blaze "S3 BT T30S RLW"
I placed BT signs on all accessories.

11/17/77

161

1/4 Corner for Sections 32 and 33.
Found - 1 1/2" x 40" steel shaft with 3 1/4" flange on top. Ren. #10
29" Cedar windfall approx. 8 ft. south, no scribe visible
50" D. Fir stump bears N.10°W., 46.5 ft. Good scar.
12" Fir, bears N.53°45'E., 38.5 ft. Good scar.
24" Madrone bears N.85°50'E., 37.6 ft. Scars
8" Cedar bears S.53°30'E., 22.6 ft. Scribe visible.
Set - 2" x 30" Gal. Pipe with a 2 1/2" brass cap marked T30S RLW 1/4
S32 S33 PLS 866 1977.
New BT - 10" White fir bears N.47°30'W., 74.4 ft. scribed 1/4 S 32 BT.
Tagged 3/4" washer RLS 866.
Replace steel shaft alongside brass cap. Set 6 ft. steel post 4 ft. north
of cap. Attached USFS signs - 54-2 and 54-4.

9/1/77