

Douglas County Surveyor's Record of
Government Corners Renewed

T 30 T. S. R 1 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97501

169

1/4 Corner for Secs. 11 and 14

Found - A 7" x 11" x 14" stone, apparently set but no marks or record,
From which:

a 1" by 36" I.P. with brass cap bears N.48°E., 24.0 ft. set 8"
above ground and marked "Douglas County Surveyor T30S R1W S11
S14 1/4 1976. Ren. #152

Brass cap is at record bearing and distance from orig. Pine BT.
A 12" now 18" B. Oak bears N.78°E., 20.3 ft. (Rec. N.89°E., 19.8 ft.)
with a completely rotted out blaze.

A 40" now 48" Pine stump bears S.78°E., 23.1 ft. with an
opened double blaze and scribing "BT".

A 36" now 24" B. Oak bears S.25°E., 32.8 ft. (Rec. S.3°W.,
46.2 ft.) with scribing "1/4 S14 CS BT" in a single blaze.

A 14" Fir, bears N.43°E., 35.4 ft. (rec. N.32°E., 11.2 ft.)
with scribing "1/4 S11 CS BT" in a partly healed single blaze.

Set - I reset brass cap at intersection of record distances from face
of blazes. This location lines up with approx 50 yr. old fences
to south and west. Causes section line to fall between bearing
trees, falls in center of unrecorded but apparently set stone and
blazes from both OBT's face it. I reset stone at west edge of
brass cap. Cap is 3" above ground and marked:

"Douglas County Surveyor" T30S R1W S11 S14 1/4
Reset 1978 1976.

I set a 5/8" x 30" Iron rod with alum. cap 5" above ground and marked "Douglas
Co. Surveyor" at old location of B.C. RP.

2/27/78

Section Corner for Secs. 12 and 13 only.

170

Found - 1923 G10 brass cap on a 2" I.P. set 6" above ground properly mkd.

A 12" now 20" D. Fir bears S.14°W., 190.6 ft. (Rec. S.8 1/2°W.,
186.8 ft.) with scribing "3" in opened bottom blaze of well
healed double blaze.

A 12" now 19" Ash bears N.27°W., 118.0 ft. (Rec. N.24 1/4°W., 114.8
with a partially healed rotted out blaze. (OBT).

A 11" now 14" D. Fir bears S.39°W., 32.7 ft. (Rec. S.43°W.) with
scribing visible in partially healed double blaze. Ren. #128

A 10" D. Fir bears N.61°W., 36.0 ft. (Rec. N.64°W.) with scribing
"T30S R1W S12 CS BT" in double blaze.

Condition report only. No new monument or accessories.

Note Corner was under a 24" log which has now been sawed away, in a small
seasonal easterly drainage.

2/16/78

1/4 Corner for Secs. 1 and 12

171

Set - Brass cap marked: T30S R1W 1/4 S1 S12 RLS 866 1978.

BT's - 15" D. Fir N.12°51'W., 24.4 ft. scribed "1/4 S12 BT".

7" W. Fir, S.60°15'W., 5.3 ft. scribed "1/4 S1 BT".

1/78

AP 1 for Secs. 1 and 12.

172

Set - Brass cap marked: T30S R1W AP1 S1
S12 RLS 866 1978.

Found - Stump bears S.52°E., 17.2 ft. scribed "BT".

New BT's - 12" W. Fir, N.31°03'E., 24.6 ft.

6" W. Fir S.56°11'E., 10.0 ft.

1/78

1/4 Corner for Secs. 11 and 12.

173

Set - Brass cap marked T30S R1W 1/4 S11 S12 RLS 866 1978

BT's - 11" W. Fir, S.58°21'W., 46.9 ft. scribed "1/4 S11 BT"

10" W. Fir, S.83°39'E., 32.3 ft. scribed "1/4 S12 BT".

1/78

Center 1/4 Section 12.

174

Set - Brass cap marked T30S R1W C1/4 S12 RLS 866 1978

BT's - 8" W. Fir, N.59°09'W., 5.9 ft. "C1/4 S12 BT".

8" D. Fir, N.62°34'E., 3.0 ft. "C1/4 S12 BT".

1/78

RE-RENEWED SEE CORNER NO. # 228

R. B. Kimberling
P. L. Earle
Doug. Co. Surveyors
Office
Feb. 27, 1978
C.S. 59/46

Gary L. Langlitz
R. B. Kimberling
N. L. Livers
Doug. Co. Surveyors
Office
Feb. 1978
C.S. 59/46

FD. OK 4/86
R. GEISLER
C.S. 63/34

William Ruppert
LS #866
For: U.S. Forest Ser.
Jan. 1978
M 65 - 80