

Douglas County Surveyor's Record of
Government Corners Renewed

T 30

T. S.

R 1

R.W.W.M.

ROKE-CHAPMAN CO., EUGENE, ORE. - 21881

James D. Artman
L.S. #2268
June 14, 1990
C.S. 63/104

1/4 Corner for Sections 7 and 8

239

Found - 1" iron pipe with 2 1/2" brass cap 12" above ground. Ren. #76
26" hemlock snag bears N.48°E., 12.4 ft. scribe visible.
24" hemlock (dead) bears S.26°E., 39.6 ft. scribes visible.
9" D. fir bears N.67 1/2°W., 29.8 ft. healed blaze. Ren. #235
(Down ehmllock N.18°W., 22.3 ft. not looked for)
Set a 6 ft. alum. post 3 ft. west of iron pipe.
Corner on flat ridge in heavy brush.

6/14/90

Bruce Shaner
For: Umpqua Nat.
Forest, Tiller Dt.
Sept. 23, 1992
R.M. 3-76 C.S.63/96

Center 1/4 for Section 34.

240

Set - Chiselled an "X" on a 20' x 20' hard rock, as it was too hard to place a rock cap on it.
New Accessories (used existing BTs) - See Renewal # 198.
16" Cedar BT, scribes visible, bears N.34°E., 35.8 ft.
24" Cedar BT, scribes visible, bears N.5 1/2°W., 54.7 ft.
Reference Monument- 2 1/2" brass cap on a 2" x 28" galv. I.P. marked
"RM→7.02 feet, RLS 430, 1992" bears West 7.02 ft.
Reference Monument- 2 1/2" brass cap on a 2" x 28" galv. I.P. marked
"RM↑19.71 feet, RLS 430, 1992" bears South 19.71 ft.
Note - Found 1980 monument & remarked as R.M. to new corner position on rock.
Note - Corner lies 80' east of Beaver Creek & 300' north of end of private road in SW 1/4 of section. Reach corner from end of said prvt. Rd.

10/23/92

Bruce Shaner
For: Seneca
Jones Timber Co.
July 1999
M 132-9
65/23-15

N 1/4 cor. Sec. 10 only

241

Found - Bateman's monument missing probably due to small local landslide, however, from proper position of monument found: (Ren # 188 & 242)
12" W.Fir BT (was 7") face overgrown, bears C.S. S.28 1/4°W., 16.5 ft.
17" Pacific Yew BT, scribes visible, bears S.50 1/4°E., 41.0 ft. (rec. 42.3 ft.)
Set - 2 1/2" x 28" alum. pipe with a 3 1/4" alum. cap mkd:

SHANER ENGINEERING INC

S 3

N 1/4 S 10 ONLY

RLS 430 1999

See Ren # 242 for corrected BTs from Ren #188

Corrected Ren. #188

David K. Bateman
Timberland Services
For: US Forest Service
July 7, 1979
M 72-36
(Corrections made
11/1/1999)

1/4 Cor. Sec. 10 only

242

Set - 2 1/2"x30" galvanized iron pipe with brass cap.
17" Pacific Yew, ~~S.50°E., 42.3~~ 1/4 S10 BT, corrected to read S.45°E., 40.8 ft.
7" Grand Fir, ~~S.26°W., 16.5~~ 1/4 S10 BT, corrected to read S.35°W., -17.9 ft.
Corner is 150' East of creek-S.22°W., 15.6

***The orig. map was corrected by David Bateman on 8-17-1978, but the corrected bearings & distances were not added to the corner renewal record until it was brought to our attention - 11/1/1999, DCSO (jc)

See
next
page