

Douglas County Surveyor's Record of  
Government Corners Renewed

30 T. S. 2 R. W. W. M.

SEC. COR. 19-30(R 2 W) 24-25 ( R 3 W)  
Found 1" iron bar and old B. T.'s. REN.#23  
15" Oak N 45° E 38.9 ft.  
15" Oak N 74° E 36.9 ft.  
15" Oak S 54° W 24.2 ft.  
18" Oak N 38° W 93.0 ft.

RE-RENEWED SEE CORNER NO. 259  
All B. T.'s. in poor shape so marked new ones.  
21" Madrona N 29° 26' E 30.9 ft.  
18" Madrona N 49° 50' W 26.0 ft.  
16" Madrona S 64° 32' W 18.2 ft.  
16" Madrona S 31° 25' E 9.3 ft.

6

George J. Wenderoth  
Deputy County Surveyor  
Frank Loso  
John H. Howell  
Witnesses  
March 1948  
CS 29/121

1/4 COR. WEST SIDE OF SEC. 30  
Found steel auto axle SEE e.s. 16/11  
54" Fir N 47° 30' W 41.0 ft.  
10" Fir S 49° W 29.7 ft., slope measurement.  
Last named B. T. recorded wrong by Boyer. REN.#1

Fd OK  
12/25-2/86  
H. Johnston  
M100-21

7

Section Corner Secs. 14-15-22 & 23

At corner point found original stone beside which I drove  
a 1/2x24" iron pipe. A fence runs North and East from this corner.  
Original B.T.s all in good condition viz:

Fir N 74° E 23.0  
Fir S 10° E 18.5  
Fir S 45° W 5.2  
Fir N 85° W 14.5

THIS COR. IN SLIDE AREA  
UNABLE TO FIX TRUE POSITION  
OF CORNER - 6-563 J.W. Byron

June 24, 1949

John H. Markham Jr. R.E.No.2880

8

CS 40/185

1/4 SEC. COR. SEC. 29  
Found granite stone with "X" two O.B.T.s chopped out.  
8" Fir N 5° E, 14 lks.  
8" Fir N 41° W, 25 lks.  
Blaze and scribe new B.T.s  
18" Fir N 45° W, 33.3 ft. Marked So. 1/4 S 29, C.S.B.T.  
10" Fir N 24° E, 13.1 ft. Marked So. 1/4 S 29, C.S.B.T.

RE-RENEWED SEE CORNER NO. 134

9

1/4 SEC. COR. SEC. 32 (North)  
Found granite stone with "X" and one O.B.T. 8" Laurel, S 60° E, 50 lks.  
Chopped out and dead. Blaze and scribe new B.T.s.  
20" Fir. S 5° E, 21.1 ft. Marked No. 1/4 S 32, C.S.B.T.  
12" Fir, S 84° E, 21.3 ft. Marked No. 1/4 S 32, C.S.B.T.

RE-RENEWED SEE CORNER NO. 133

10

A. R. Evans - Dep. Co. Surveyor  
April, 1951  
RM 1-30  
CS 44/121

1/4 COR. SEC. 32 (South)  
Found two O.B.T.s  
8" Cedar N 60° W, 13 lks. (down)  
12" Laurel, N 65° E, 68 lks.  
Set 4" x 4" x 42" Cedar Stake for Cor. 24" in ground marked N side 1/4 S 32  
Blaze and scribe B.T.s  
16" Fir, N 66° E, 46.1 ft. Marked 1/4 S 32 C.S.B.T.  
18" Fir, N 39° W, 16.4 ft. Marked 1/4 S 32 C.S.B.T.

RE-RENEWED SEE CORNER NO. 78

11

East 1/16 corner between section 6-7, T30s, R2W, W.M.  
A midpoint between the North 1/4 cor. Sec. 7 and the N.E. cor. Sec. 7  
T30s, R2W, I drove a 3/4" solid steel shaft.  
From which  
A La. 10" diam. bears N85E, 8.0' dist. mkd. 1/16s B.T.  
A Sugar Pine 12" diam. bears N30°W 15.5' dist. mkd. 1/16s B.T.

12

John H. Markham Jr.  
Witness:  
J. F. Johnson  
E. H. Johnson  
Blair Sutton  
Sep. 8, 1952  
CS 5/1174

Section Corner 5-6-7-8,  
All 4 old B.T.s standing-I remark each tree.  
At corner point set 1" x 30" I.P.

RE-RENEWED SEE CORNER NO. 140

13

1/4 Section Corner 6-7, as determined by O.B.T.  
A Pine 26" diam. bears N80E, 40.0' dist. O.B.T.  
At corner point fd. old stone and set 1" x 30" from which  
A La. 8" diam. bears N3E, 32.6' dist. mkd. s, s6, 2880,  
B.T.  
A Pine 26" diam. bears S86E 149.0' dist. mkd. S7 s B.T.  
An old fence bears East and West from corner.

14

RE-RENEWED SEE CORNER NO. 166