

Douglas County Surveyor's Record of
Government Corners Renewed

30

T. S.

2

R. W. W. M.

HOKE-CHAPMAN CO., EUGENE, ORE. 97196

John H. Markham Jr.
Witness: E. R. Sutton
March 1, 1955.
C. S. File 41/369.

$\frac{1}{4}$ corner to secs. 5 and 8.
Determined by O. B. T.s.

A 30 inch Fir bears North 19.8 feet, O. B. T. I found scribe on this Fir
At corner point set stone from which:

A 16 inch Ia. bears N.69°W., 29.4 feet dist. mkd. $\frac{1}{4}$ S 5 B. T.
A 5 inch Cedar bears S.16°E., 14.0 feet dist. mkd. $\frac{1}{4}$ S B. T.
Northwest corner sec. 8, bears West 2648.0 feet.
Corner lies just on South side of main ridge.

RE-RENEWED SEE CORNER NO. #163

28

Robert M. Thompson
Jan. 12, 1956.
C. S. File No. 42/199.

$\frac{1}{4}$ corner to sections 1 and 2,

I find corner stone in position and Madrone B. T. in Section 1 standing but
with face rotted out. No trace of the Fir B. T. in Section 2.

I scribe 2 new B.T.s as prescribed by law:

18 inch D. Fir, N.84 $\frac{1}{2}$ °W., 21.9 feet.
40 inch Sugar Pine, N.30°E., 47.6 feet.

RE-RENEWED SEE CORNER NO. 139

29

Arthur R. Evans
May, 1951.
C. S. File No. 44/121.

Center $\frac{1}{4}$ corner to section 32.

Location for corner determined by intersection of N-S and E-W centerlines.

Mkd. 16 inch Fir for corner. Blaze and scribe on E. side C $\frac{1}{4}$ cor. S. 32,

C. S. West side is line, South side proper dist.

Blaze and scribe B. T.s:

14 inch Cedar, S.7°E., 5.2 feet mkd. C $\frac{1}{4}$ S 32, C. S. B. T.
22 inch Cedar, S42 $\frac{1}{2}$ °W., 31.4 feet mkd. C $\frac{1}{4}$ S 32, C. S. B. T.

RE-RENEWED SEE CORNER NO. #282

30

James W. Byron, Deputy Co. Surveyor
M. Godfrey
S. Bilow
May 7, 1958
C. S. File No. 49/86

South $\frac{1}{4}$ Section Corner to Section 30.

Found - Mound of Rock & BT's. as recorded by B. B. P. 1940.

N.E. BT. should be 60" Fir, recorded 10" Fir. - REN. #15

Both BT's. alive & in good condition & both show good scribing.

Set Brass Cap in Mound of Rock Mkd. S $\frac{1}{4}$ S30 T30S R2W.

County Surveyor's Office, 1958.

Scribed New BT. In N.E. - 14" W. Fir bears N.27 $\frac{1}{2}$ °E. 49.5' Scribed $\frac{1}{4}$ S30 CS BT.

Note - The N. $\frac{1}{4}$ Corner Section 31 has good Rock (with + on Top & 4 on S. Side)
Also both BT's. O.K.

RE-RENEWED SEE CORNER NO. 261

31

Corner to Section 30, T30S, R2W, & Secs. 25 & 36, T30S, R3W.

Found - BT. as recorded by Boyer, 1939.

16", now 24" Fir N.52°45'W. 23.0 ft.

Orig. 11", now 20" Cedar N.67 $\frac{1}{2}$ °E. 17.8 ft.

Both BT's. have good scribing & are alive & in good condition.

Set Brass Cap Mkd. County Surveyor's Office, 1958 T30S R3W S25/S30 R2W

New BT's: 72" R. Fir bears N.33°E. 14.5 ft. S30 T30S R2W., S36/S30 R2W
CS BT, Bark Scribed.

SEE C.S. 16/11

32

Note - I find Closing Corner for
Pipe & BT's O.K. R3W

S36 | S30 | As recorded by
S31 | R2W | Boyer, 1939.

SEE REN. No. 2

SEE CORNER # 2

33

John H. Markham, Jr.
Wit. R. G. Boyd
For Stomar Lbr. Co.
C. S. File 42/421
Dec. 1958

$\frac{1}{4}$ Corner to Sections 1 & 12.

As Determined by O.B.T.'s.

7" Fir bears S.48°E. 13.2 ft. O.B.T., found scribe.

8" Fir bears N.40°E. 6.0 ft. O.B.T.

At Corner Point Found 14" Cedar Mkd. on North Face - I rescribe on

East Face $\frac{1}{4}$ S & Set 1" x 30" I.P. at base of tree from which:

7" Fir bears N.69°E. 11.2 ft. dist. mkd. $\frac{1}{4}$ S12 B.T.

5" Fir bears S.30°W. 9.0 ft. dist. mkd. $\frac{1}{4}$ S12 B.T.

5" Yew bears N.14°W. 10.2 ft. dist. mkd. $\frac{1}{4}$ S12 B.T.

Road bears East 450.0 ft. distance.

RE-RENEWED SEE CORNER NO. 184

34