

Douglas County Surveyor's Record of
Government Corners Renewed

T 30 S T.S. R. 2 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

East $\frac{1}{4}$ Corner to Section 13, T30S R3W. - West Boundary of Sec. 18, T30-2W.
Found - Both Orig. BT's. Orig. 30", now 36" Rotted Cedar Stump
N.46 $\frac{3}{4}$ °E. 94.7 ft. Orig. 12", now 18" Fir N.71°W. 17.8 ft.,
shows good scribing. Also find 36" Fir S.70°W. 14.5 ft, not
18.5 ft., shows scribing. (This BT. scribed 1908)
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962 **59**
E $\frac{1}{4}$ S13 T30S R3W

James W. Byron, Deputy
D. McFarland & J. Powell
March 1962
C.S. File No. 49/47

No. New Bearing Trees needed.
Note - I find both BT's., now stumps, each shows good scribing, for **59A**
West $\frac{1}{4}$ Cor. S18 T30S R2W. I also find 1 $\frac{1}{4}$ " I.P. Set for corner
with 6" x 2" painted white yewwood post alongside. The Brass
Cap at $\frac{1}{4}$ S13 bears South 86.0 ft., now 92.4 ft. **#265**
From the 1 $\frac{1}{4}$ " I.P., now 30" Fir Stump bears N.66°E. 31.7 ft., not
N.40°E. Now 30" S. Pine Stump bears S.27°E. 17.2 ft., not
S.60°E. Bearing trees face to 1 $\frac{1}{4}$ " I.P.

RE-RENEWED, SEE CORNER NO.

$\frac{1}{4}$ Corner to Sections 4 and 9., as det. by O.B.T:
40" Fir Snag N.46°E. 9.9 ft. O.B.T., fd. scribe.
At Corner Point found 11" Cedar mkd. on South face - O.B.T.
Set - $\frac{1}{2}$ " x 24" I. R. from which:
13" Fir N.67°E. 4.6 ft. mkd: $\frac{1}{4}$ S4 BT.
10" Fir S.57°W. 9.0 ft. mkd; $\frac{1}{4}$ S9 BT.
Centerline Road bears East 58.0 feet.
10/15/68 Found O.K. J.M.P.

60

$\frac{1}{4}$ Corner to Sections 15 and 16. as det. by O.B.T's:
25" Fir uproot N.75°W. 10.6 ft., O.B.T.
20" Fir Snag S.20°E. 3.3 ft. O.B.T.
At Corner Point Set $\frac{1}{2}$ " x $\frac{1}{2}$ " angel Iron from which:
30" Cedar S.32°W. 40.7 ft. mkd: $\frac{1}{4}$ S16 B.T.
18" Fir N.80°E. 33.0 ft. mkd: $\frac{1}{4}$ S15 B.T.
50" Fir S.35°E. 21.7 ft. mkd: $\frac{1}{4}$ S15 B.T.

61

Section Corner to Sections 15 - 16 - 21 - 22., as det. by O.B.T's:
12" La. N.25°W. 24.4 ft., O.B.T., fd. scribe.
20" Fir uproot S.54°W. 6.6 ft., O.B.T.
22" Fir uproot N.41°E. 10.6 ft. O.B.T.
At Cor. Point found Stone & Set 1 $\frac{1}{2}$ " x 30" I.P. from which:
10" Cedar N.47°W. 7.8 ft. S16 B.T.
9" W.Fir bears North 28.7 ft. S15 B.T.
5" Fir N.18°E. 21.0 ft. mkd. SXXX B.T.
15" Fir N.62°E. 42.0 ft. mkd: SSS B.T.

62

West $\frac{1}{4}$ Corner to Section 6 only.
Found - Orig. Cor. Tree & both Orig. BT's., each shows good
scars & check O.K.
Set - Brass Cap at Cor. along East edge of Corner Tree &
Mkd: County Surveyor's Office, 1962 West $\frac{1}{4}$ S6 T30S R2W.
New BT: 7" R.Fir bears S.38°E. 41.9 ft. scribed $\frac{1}{4}$ S6 CS BT.

63

East $\frac{1}{4}$ Corner to Section 1, only, T30-3W.
Found - Both Orig. BT's. Orig. SW. BT. shows good scribing.
New BT: 7" R.Fir bears S.51°W. 15.0 ft. scribed $\frac{1}{4}$ S1 CS BT.

64

Renew
R3W S1 S6 T30S
R2W

65

Found -Orig. 10", now down 14" Fir S.68°W. 23.8 ft., shows
scribing. No other Orig. BT's. found.
Do Find Shattered Stone at Corner.
Set - Brass Cap at Corner Mkd: County Surveyor's Office, 1962
New BT's: 9" Fir bears S.77°W. 13.9 ft. scribed S1 T30S R3W CS BT.
10" Hemlock bears N.78°E. 33.6 ft. scribed S6 T30S R2W

John H. Markham, Jr.
For Stomar Lumber Co.
Witness: J. R. Markham
July 10, 1962
C. S. File No. 42/421

James W. Byron, Deputy Co. Surv.
Mike Darby and Wm. Storrel
December 1962
C. S. File No. 52/126

FWD. OK
2/91 M 111-49

FD OK
11/84
M 97-65

FD OK
11/84
M 97-65