

Douglas County Surveyor's Record of
Government Corners Renewed

T 30 S T. S. R 2 W R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

1/4 corner for Sec. 3 and 10.

185

Found - 3/4" I.P. buried and disturbed by recent logging activity.
An orig. 24" fir, now a 24" stump, peeled, treated with preservative and covered with metal roofing. We also find a 30" fir stump with an old, well healed scar. The orig. notes call for only one BT the aforementioned capped stump, We do not open. We also find Markhans bearing trees. Ren. #52

Set - 1" x 30" I.P. with brass cap attached mkd:
COUNTY SURVEYORS T 30 S
OFFICE S 3
1974 1/4 S 10
R 2 W

We deposit the found I.P. alongside and note the existing BT's:
An orig. 24" fir, now a 24" stump bears N.14 1/2°E., 9.9 ft.
A 30" fir stump bears S.42°E., 20.0 ft.
A 7" now 11" W. Fir bears S.63°E., 10.1 ft. (Rec. per Ren. 52 S.67°E., 10.1 ft.) alive and well healed.
A 13" W.Fir now a 15" stump bears N.57°E., 22.0 ft. well healed.
A 6" W.Fir, now a 10" stump bears N.21°W., 8.8 ft. illegible scribing visible on damaged face.
A 7" now 11" W. Fir bears S.21°W., 15.9 ft. alive and well healed.
Compass declination setting: 20° East.

12/2/74

187

1/4 Corner for Secs. 24 and 25.

This corner set from survey of the south line of section 24, its location determined by single proportionate measurement. An exhaustive search of the area yielded no trace of the original corner.

At the corner point we set:

A 1" x 30" I.P. with brass cap attached mkd:

COUNTY SURVEYORS T 30 S
OFFICE S 24
1974 1/4 S 25

RE-RENEWED, SEE CORNER NO. #255

From which:

A 20" D. Fir bears N.51°E., 51.7 ft. scribed "1/4 S24 CS BT".

Note: the blazes on this BT face south.

A 10" Madrone bears S.3°W., 24.0 ft. scribed "1/4 S25 CS BT"

Compass declination setting: 20° East.

12/9/74

JAN 75

North 1/4 Sec.4

REN#150

188

Found-Brass cap laying 6" under surface in Large pit caused by uprooted tree, cap is County Surveyors 1968 properly marked cap.
BT's-32" D.Fir now 52" dia. stump, bears S 20°E., 24.4 ft. (to blaze) Partial acribing on blaze.

14" cedar now 23" Dia. bears S 20°W, 31.9 ft, has good blaze.

6" Hemlock now 8" Dia. bears S 2°E, 19.0 ft, has good blaze.

SET-Reset brass cap at north quarter corner sec.4, T30S, R2W, marked as noted. This corner lies 43.7 ft. east of 1/4 sec. 33, T29S, R2W (Rec. 42.2 ft)

Set 12" dia. cedar post 5 ft' long, 2 ft. into ground approx. 1.5 ft north of corner monument. The 1/4 corner falls in large pit caused by uprooted fir.
Mag. Dec. 20° E. 12/18/75

L.E. Monrean
P.L.E.
J.H.C.
12/18/75
C.S.57/39

North CC to Sec.15 & 16

189

Found: Orig. 10" now 13" D.Fir corner tree, alive with well-healed blazes on south, east and west faces, and a 3/4" I.Pipe set at the base of the corner tree by Markham in 1960. (Ren #50)

From Which the original bearing trees are located as follows:

An orig. 12" now 15" D.Fir bears S 22 1/2°E., 33.7 ft., alive and well healed.

An orig. 7" now 11" D.Fir, alive and well-healed bears S33 1/2°W., 26.4ft

Bearing trees marked by Markham in 1960 are located as Follows:

A 10" now 11" grand fir, scribed visible on partially-healed blaze, bears S 50°E., 15.5 ft. (Rec. S 50°E., 14.4ft.)

Note: 14.4 ft. distance matches from pipe to BT.

A 18" now 15" I Cedar, scribing visible on partially healed blaze, bears S 21°W., 47.0 ft.

Note:

This corner is located at a corner of fences running south and east, approx. 600 ft. west of BLM's Dompier Crk Rd. Mag. Dec.: 20° East 12/17/75

Gary L Langlitz
M.Lenora Ladig
CS 57/39
12/17/75

Gary L. -Langlitz, County Surveyors Office
P. Earle
C.S. 57/12
December 1974

M 55-2