

Douglas County Surveyor's Record of
Government Corners Renewed

30 T. S. 2 R. W. W. M.

KOBE-CHAPMAN CO., EUGENE, ORE. 21881

#193

A 5" now 6" chinquapin, in poor condition, scribe visible bears N 72°W., 25.8 ft.
(Rec. N 69°W., 25.8 ft.)

At the corner point, we set a 1" x30" I Pipe, 26" in the ground, with brass cap attached, marked T30S

DOUGLAS CO. SURVEYOR	R	S12	S 7	R
1975	2	S13	S18	1
	W			W

We place the corner some on the east and Markham's pipe on the west side of the Brass cap and mark the following BT

A 5" D fir, scribed " NW S18 CS BT" on a double blaze bears S68°E., 32.3 ft.

Compass declination setting: 20° East 12/18/75 *FD OK, Dec. '94, M121-45*

Center 1/4 Corner Sec.13

Set 2" pipe with 3" Dia. Brass Disk top stamped T 30 S, R 2 W

C
C1/4 S18

From Which

C
PLS 961 1975

A 14" pine bears S 17° W, 37.0' scribed C 1/4 S 13 BT

A 11" Chinquapin bears S58°W., 13.3' scribed C1/4 S 13BT.

1/4 corner to sec. 4 & 5

REN#57

195

Found-A 40" D. Fir stump, Scribed "1/4 S BT" on an unhealed face. (Ren#57)

All other evidence of the orig. or resurvey corner and bearing trees has been destroyed.

At the corner point, as determined by the above mentioned BT stump, 40" D. fir bearing N69°E., 8.8 ft.

Set- 1"x30" Iron pipe, 24" in the ground, with a brass cap attached marked

T30S R2W

DOUGLAS CO. SURVEYOR
1976

1/4
S5 | S4

New BT's- A 12" grand fir bears S35°E., 75.3 ft. scribed "1/4 S4 CS BT" on a double blaze

A 16" Hemlock bears S78°W., 60.7 ft. scribed "1/4 S5 CS BT" on a double blaze

Compass Declination setting 20° East 2/3/76

South 1/4 Cor. for Sec. 36 and north 1/4, Sec. 1, T.31-2

196

Found - Remains of an orig. BT, a 50" Pine, now a hollow, burnt & rotting stump. After a diligent search, we find a well-preserved piece of wood with good scribing "BT" visible. This piece of wood was fd. at the base of the stump.

We also find a hollow oak snag at the proper location for the orig. NW BT, however we find no evidence of cor. marking.

At the true cor. point as determined by the record bearing and distance from the aforementioned remains of the orig. SE BT, an orig. 50" Pine now a badly deteriorated stump, bearing S.55°E., 19.8 ft. from the cor. point

We Set - A 1"x30" I.P. 25" in the ground with brass cap attached marked:

Douglas County Surveyor
1976

T30S R2W

1/4
S36
S 1

T31S R2W

We find no trace of the orig. corner monument.

New BT's - A 9" D. Fir bears N.75°W., 60.9 ft. scribed "1/4 S36 CS BT" on a double blaze.

A 15" D. Fir bears S.2 1/2°E., 50.7 ft. scribed "1/4 S1 CS BT" on a double blaze.

We deposit the found scribing at the base of the Pine stump.

Note: A fence corner of nearly new fences running south and east bears S.36°W., 58 ft.

Compass declination setting: 20° east.

4/22/76

Section Corner for Secs. 32 and 33 only.

197

Found - 22" Fir, S.26°E., 33.5 ft. County Ren. #82

18" Fir, N.50°E., 38.2 ft. Down OBT.

36" Fir, N.3°W., 26.4 ft. Down OBT.

Reset Corner S.26°E., 33.5 ft. from 22" Fir.

New BT - 7" Fir, N.88°E., 71.9 ft.

SEE CORNER NO. #225
226

7/15/76

Umpqua Nat'l For
Dec. 1975
Larry J Friar
M 59-11

Gary L Langlitz
Peter L Earle
James H Cook
CS59/2
2/3/76

Co. Surveyor Off.
Gary L. Langlitz
A. Victor Cangie
D. Stewart
April 22, 1976
C.S. 59/8

Howard Johnstone
For: Roseburg Lbr.
July 15, 1976
M 56 - 49