

Douglas County Surveyor's Record of
Government Corners Renewed

T 30 T. S. R 2 R. W. W. M.

ROSE-CHAPMAN CO., EUGENE, ORE. 21881

275

C O N T - - - -

12" now 13" dia. W. fir with a partially healed single blaze scribing visible "S16 BT" bears N.29°E., 37.8 ft. (Record N.31°E., 37.8 ft.) Ren. No. 251
6" now 6" dia. 18" high burnt cedar stump with scribe marks "BT" visible on burnt blaze, bears S.24°E., 28.0 ft. (agrees with record) Ren. No. 251

New Accessories:

8" dia. I. Cedar double blazed and scribed "T30S R2W S16 CC CS BT" bears N.72°E., 24.8 ft.
32" dia. 2 ft. high D. fir stump with an 8" long boat spike set through BT tag near center of stump, boat spike is stamped "BO 1". B. Spike bears S.84°E., 15.1 ft.
36" dia. 3 ft. high D. fir stump with an 8" long boat spike set near center of stump, boat spike is stamped "BO 2". B. spike bears S.31°E., 20.4 ft.
DCSO BC/IP T30S R2W SW Cor Sec. 17 bears North, 100 ft.

3/22/91

276

1/4 Corner Section 20 only, East side.

Found - 2½" 1970 DCSO brass cap on a 1½" O.D. x 36" long iron pipe tipped over east of plumb, 1 ft. below ground. Ren. #178
72" now 60" dia. 7 ft. high charred D. fir stump with blazes bears N.62°W., 47.5 ft. (original)
6" now 12" dia. 2½' ft. tall D. fir stump tipped on face out of position, near record brg. < dist. (N.14°W., 51.1 ft.) is in a slide. Ren. No. 178
7" now 9" dia. 5 ft. high hemlock stump scribing visible on an unhealed blaze "1/4 S20 CS" bears N.40°W., 27.4 ft. Ren.#249
Set - DCSO BC/IP returned to plumb, now protrudes 8" above ground. (Corner is in a rock slide)
New BTs - 12" dia. 12 ft. high pistol butt maple stump with a PK nail set through BT tag on south side of stump, 2 ft. above ground, PK nail bears S.40°W., 3.4 ft.
12" dia. 3 ft. high maple stump with a boat spike stamped "BO 1" set through BT tag near center of stump. B.spike bears N.2°E., 65.1 ft.

3/22/91

277

Section Corner for Secs. 20, 21, 28 and 29

Found - A 2½" dia. 1968 County brass cap on a 1½" O.D. iron pipe, firmly set and protruding 1 ft. above ground. No evidence of original corner monument found. Ren. No. 172
A 24" fir, now a 28" dia. down, out of position, broken and burned snag with a possible burned healed blaze, the root hole of which bears S.04°E., 20.5 ft. distant. (orig.) per record.
A 10" fir, now a 24" dia. 4½ ft. tall burned fir stump with a fully healed double blaze bears N.76°W., 23.8 ft. (Original)
No evidence of the northeast and southwest original bearing trees found.
6" D. fir now an 8" dia. down out of position burned snag with a fully healed double blaze, the root hole of which bears S.58°W., 35.6 ft. distant. Ren. No. 172

New Accessories:

An 8" DBH D. fir scribed "T30S R2W S28 CS BT" on a double blaze bears S.03°E., 46.8 ft.
An 8" long boat spike, stamped "BO 1" on top surface, driven in top of a 32" dia. 2 ft. tall pine stump bears S.27 3/4°W., 65.2 ft. distant.
An 8" long boat spike, stamped "BO 2" on top surface, driven in top of a 40" dia. 3½ ft. tall fir stump, bears N.05°W., 25.0 ft.

Monument lies 50 ft. west and approx. 15 lower than BLM Road #30-2-

3/19/91

Douglas County Surveyors Office
Randall Smith, Deputy
Stephen Flause - Terrie Franssen
March 22, 1991
C.S. 64/13

Douglas County Surveyors Office
Stephen John Flause
T. R. Franssen
March 19, 1991
C.S. 64/13