

Douglas County Surveyor's Record of
Government Corners Renewed

30

T. S.

3

R. W. W. M.

KOKI-CHAPMAN CO., EUGENE, ORE. D7196

Northeast corner of D. L. C. No. 37. 58

Renewal of Renewal, as determined by a 2" iron pipe set by C. S. in 1918.

SEE REN. #4A

At corner point found 2" iron pipe, from which (MARKED NEW TREES)

A B. O. 16" diam., bears S56°W., 141.8' dist. mkd. D. L. C. No. 37 B. T.

A W. O. 12" diam. bears S.14°W., 170.0' dist. mkd. NE 37 B. T. Fences run N-S-W from corner.

John H. Markham Jr.
Witness:

Dennis Vaughn.
Done for Mrs. P. Snow.

August 15, 1953
File 41/185

$\frac{1}{4}$ corner between secs. 26 and 35. 59

At the Quarter corner common to Sections 26, and 35, I find a stump of the original bearing tree which was a 24" Oak ascertained by an excellent scribed "BT" and negative. As this stump was described as being S 89 $\frac{1}{2}$ ° E and 462.0 feet distant from the orig. cor., I set a flag 4.6 feet directly north of the center of the stump.

I then proceed to the section corner common to sections 26, 27, 34, and 35 which is a 4" iron rod flush with the top of the ground from which the following bearing trees were found:

14" Pine S 83°45' E., 131.5 links

14" W. Oak S 19° W., 26.3 feet.

Setting a flag over the true corner I range the transit in until the instrument is on a true line between the two flags. I then set a 1 inch iron pipe six inches under the surface of the ground on the true line and 462 feet distant from the oak stump. I then scribe the following bearing trees:

24" White Oak S. 88°43' E., 384.0 feet marked $\frac{1}{4}$ S35BT.

22" White Oak S. 27°08' E., 533.5 feet marked $\frac{1}{4}$ S35BT.

$\frac{1}{4}$ corner on South boundary of section 35. 60

From the $\frac{1}{4}$ corner between secs 26 and 35 I run due South and fall 27.9 feet west of the south quarter corner which is an 8" Hemlock marked "S" on north face, said cor. being 250.0 feet south of the North quarter corner. As none of bearing trees are left at the south quarter corner of section 35, I scribe the following bearing trees:

28" Cedar S 33° E., 37.2 feet marked $\frac{1}{4}$ S2BTRE3024.

18" Hemlock N 30° W 40.1 feet marked $\frac{1}{4}$ S35BT.

I also set a 1 $\frac{1}{2}$ " iron pipe as a witness corner 1.0 ft. N. of the true cor. marked "WC" on N. face and "RE 3024" on South face.

Section cor. to 6 and 7 only. 61

Set 1 inch iron pipe with Brass Cap marked:

1 | 6 Co. Sur. Off.
R4W | 7 R3W
1953

Corner positively identified from chiseled rock at cor. and BT an

18 inch W. Fir South Now dead.

Blazed and scribed the new bearing trees:

12 inch W. Fir T3OS, R3W., S 6 CS BT., N.79°E., 206.0 ft. dist.

18 inch W. Fir T3OS, R4W., S 1 CS BT., S50°W., 32.0 feet dist. & brass disc.

24 inch Maple, T3OS, R3W., S 7 CS BT, S18°E., 25.5 ft. dist.

$\frac{1}{4}$ Section corner between secs. 34 and 35. 62

Found:

2 inch W. stake mkd. R. Thompson et al.

Rotted stump of 24 inch Fir B. T. with scribing N75°15'W., 64 lks.

30 inch Fir B. T. down and dead, S.76°E., 54 lks.

Set 1 $\frac{1}{2}$ inch Gal. iron pipe with tag mkd. RE3024.

Scribed following:

10 inch Fir, S.38°40'W., 10.2 feet, marked "S 34 BT".

16 inch Cedar, S.79°30'W., 27.5 feet marked "N $\frac{1}{4}$ S 34 BT".

Filed in 41/196

Richard L. Templin Jr.
Surveyed for Oregon Conference of Seventh Day Adventists at
Milo, Oregon October 1, 1953

C.S. 41/196

180

Ben B. Irving
J. Byron
Ray Irving
Nov. 16, 1953
Sur. file No. 45/219

Richard L. Templin Jr.
Survey done for Milo
Church School.
November 7, 1954
C. S. File 41/317.

RE-RENEWED SEE CORNER NO. 218

RE-RENEWED SEE CORNER NO. 230

RE-RENEWED SEE CORNER NO. 172