

Douglas County Surveyor's Record of
Government Corners Renewed

T. 30. S. T. S. R. 3 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21681

James W. Byron, Deputy County Surveyor
Mike Darby and Wm. Stoffel
January and February 1963
C. S. File No. 52/138

1/4 Corner to Sections 27 and 26. 132
Found - 32" Fir N.44°E. 64.2 ft., down, found scar & tag. REN. #95
26" Pine S.74°W. 62.6 ft., down, found scribing.
Orig. BT., 15" Oak N.10°W. 66 ft., rotten stump
Set - Brass Cap at Cor. Mkd: County Surveyor's 1/4 S27/S26 T30S R3W CS BT.
Office, 1963
New BT's: 19" Pine N.20°W. 52.8 ft. scribed 1/4 S27 CS BT.
14" Laurel N.18°E. 45.8 ft. scribed 1/4 S26 CS BT.

1/4 Corner to Sections 21 and 22. 133
Found - Rock at Cor. as recorded. Also find both BT's, each shows good scars.
Orig. 12", now 19" R.Fir N.43°E. 5.9 ft.
Orig. 15", now 32" R.Fir S.17°W. 35.7 ft., not 37.0 ft.
Set - Brass Cap alongside Cor. Stone & Mkd: County Surveyor's Office, 1963
1/4 S21/S22 T30S R3W
No New Bearing Trees scribed.

1/4 Corner to Sections 29 and 28. 134
Found - Stone at Cor. & USGS B.M. bears S.82°45'E. 28.2 ft. - M 11-59 REN. #3
Also find Orig., now 48" R.Fir N.N.15°E. 148.5 ft., shows scar.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
1/4 S29/S28 T30S R3W.
1/4 I.R. at Fence Corner bears N. 9° W. 29.8 ft.

Section Corner to Sections 26 - 27 - 34 - 35. 135
Found - Axle with flange up and flush with surface at corner. REN. #5
Also find S.W. & S.E. BT's in good condition.
N. E. & N. W. BT's. not found.
Center of Paved Road is North 52.0 ft. from Section Corner.
No trees near to N.E. & N.W. *Book 2/98 Ray Brown 1993-0022918*
FO. D.K. MAR. 1968 - C.S. 54/52

1/4 Corner to Sections 11 and 14. 136
Found - Both Orig. BT's. Orig. 28, now 44" Fir N.30°E. 26.7 ft., shows scar.
Orig. 5", now 13" Fir S.5°E. 18.7 ft, shows scribing.
Corner Stone not found.
Set - Brass Cap at Cor. Mkd: County Surveyor's 1/4 S11 T30S R3W
Office, 1963 S14
Rescribe Now 13" Fir S.5°E. 18.7 ft., 1/4 S14 CS BT.

1/4 Corner to Sections 26 and 25. 137
Found - Both BT's. recorded by Richardson. 12", now 16" W.Oak N.27°W.
97.0ft., now N.30°W., shows scribing. REN. #1
36", now 44" R.Fir S.72°E., not S.75°E. 30.3 ft., shows scar.
Note - Corner falls infield.
Set - Wit. Cor. 18.0 ft. N. Mkd: Brass Cap: County Surveyor's Office, 1963
W. C. 18' South to 1/4 S26/S25 T30S R3W
New BT's: Rescribe, now 16" W.O. N.33°W. 81.5 ft. WC 1/4 S26 CS BT.
14" R.Fir bears N.35°E. 84.4 ft. scribed W.C. 1/4 S25 CS BT.

Renewed Corner CC T30S R3W. 138
Found - Drill S7/S8 Steel at Corner with 1" x 18" I.P. alongside. REN. #38
Orig. 16", now 24" Fir N.7 1/2°W. 18.5 ft., shows good scar & bark scmg.
Find Stump of Original S.W. Bearing Tree.
New BT: 8" Maple bears S.2°W. 14.0 ft. scribed CC T30S R3W S7 CS BT.
E. W. Wire Fence 9 ft. North.

Renew Corner S 6/S 5 T30S R3W. 139
Found - I.Pipe at corner & 12" Maple S.46°W. 14.5 ft., shows scribing. REN. #39
Set - Brass Cap at Corner & alongside I.P. & Mkd: T30S R3W S6/S5
County Surveyor's Office, 1963
New BT: 6" R.Fir bears N.49°E. 21.9 ft. scribed S5 CS BT.
Note - Corner Thus:

