


Douglas County Surveyor's Record of
Government Corners Renewed

T. 30 S. T. S. R. 3 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21891

FWD OK
10/92 R. Brown
M 112-62

South $\frac{1}{4}$ Corner to Section 6. 154
Found - Stone at Corner & both BT's. as recorded, now 16" W.O.
N. 65° W. 7.3 ft., shows scribing. N.E. BT. fair condition.
Fences Thus: REN #16



Set - Brass Cap alongside Cor. Stone & Mkd: County Surveyor's
Office, 1963 South $\frac{1}{4}$ S6 T30S R3W.
New BT: 10" W.Oak, inclump, bears S. 46° E. 5.0 ft. scribed $\frac{1}{4}$ S CSBT.
Note - Marks not found on corner stone.

West $\frac{1}{4}$ Corner to Section 6, T30-3W. 155
Found - Orig. 12", now 24" B.Oak S. 62° E. 89.1 ft. We open & find
good scribing "12".

Orig. S.W. BT., down & rotted, & in slide area. - See C.S. 37/133
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963 RENEWAL
West $\frac{1}{4}$ S6 T30S R3W.
New BT's: 10" W.Oak bears N. 27° E. 5.0 ft. scribed W $\frac{1}{4}$ S6 CS BT.
7" W.Oak bears S. 32° E. 15.5 ft. scribed W $\frac{1}{4}$ S6 CS BT.

West $\frac{1}{4}$ Corner to Section 30, T30-3W. 156
Found - 12", now 20" Fir N. 70° E. 38.0 ft. We open & find good scribing.
22" Fir Stump N. 65° E. 41.6 ft., shows bark scribe marks.
30" Fir Stump S. 84° E., not S. 80° E. 52.8 ft., shows scribe mks.
Do not find Iron Pipe set at Corner. - REN #32

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
W $\frac{1}{4}$ S30 T30S R3W
New BT: 15" R.Fir bears N. 7° E. 22.6 ft. scribed W $\frac{1}{4}$ S30 CS BT.
Note - Corner is 70 ft. North of private road.

Renew East $\frac{1}{4}$ Corner of Section 24 only, T30-3W. 157
Found - Orig. BT's. as recorded by Markham., and 7" W.Oak by Markham. REN #37

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
E $\frac{1}{4}$ S24 T30S R3W.
New BT: 5" Laurel bears S. 43° E. 27.5 ft. scribed $\frac{1}{4}$ CS BT.
No other trees near.
Note - Corner is at top of steep north slope.

Corner between T30-3W. & T30-2W. 158
R3W $\frac{1}{4}$ S18 R2W
S19
Found - Brass Cap at Corner. N.E. BT. is in good condition.
S. E. BT., now down.
New BT: 17" Cedar bears S. 25° E. 37.8 ft. scribed S19 CS BT. T30S R2W.

$\frac{1}{4}$ Corner to Sections 23 and 26. 159
Found - Orig. 18", now 26" Rotted Oak Snag S. 68° E. 43.6 ft., shows scribing.
Orig. 18", now 30" Down & rotted Oak N. 50° E. 85.8 ft., " "
Renewed BT's. which show good scribing about 20 yrs. old.
We rescribe both Fir Bearing Trees.

Note - Corner is under Butt Section of down 36" Fir.
Set - Brass Cap at Cor. Mkd: County Surveyor's $\frac{1}{4}$ S23 T30S R3W
Office, 1963 S26
New BT's: 27" R.Fir bears S. 64° E. 48.7 ft. scribed $\frac{1}{4}$ S26 CS BT.
26" R.Fir bears N. $56\frac{1}{2}^{\circ}$ E. 66.0 ft. scribed $\frac{1}{4}$ S23 CS BT.

Section Corner to Sections 17 - 18 - 19 - 20. 160
Found - Iron Pipe at Corner & all BT's. N.W. & S.W. BT's. now stumps. REN #51 #206
New BT: 24" R.Fir bears S. 44° W. 81.7 ft. scribed S19 T30S R2W CS BT.
Note - No trees near to N.W. - Corner is under 36" Log.

RE-RENEWED

James W. Byron, Deputy County Surveyor
Mike Darby and Wm. Stoffel
February and March 1963
C. S. File No. 52/138