

Douglas County Surveyor's Record of
Government Corners Renewed

T. 30 S. T. S. R. 3 W. R.W.W.M.

MOKE-CHAPMAN CO., EUGENE, ORE. 21881

187

South $\frac{1}{4}$ Corner to Section 32 only.
 Found - I. Pipe at $\frac{1}{4}$ Corner, See Ren. #73.
 Orig. 36" D. Fir N. 71° E. 10.0 ft., shows good scar.
 9" Laurel, now 11", N. 50° E. 52.0 ft. (S.B. 48.8 ft.)
 scribed $\frac{1}{4}$ S32 BT.
 10" Live Oak, now 13", S. 46° E. 41.0 ft. (S.B. 34.4') scribed $\frac{1}{4}$ S32 BT.
 23" D. Fir, now 25", S. 7° E. 38.0 ft., bark scribed $\frac{1}{4}$ S32 BT.
 Set - Brass Cap alongside I. Pipe at $\frac{1}{4}$ Cor. Mkd: T30S R3W
 County Surveyor's Office, 1966 $\frac{1}{4}$ S 32 T31S R3W

All BT's. in good condition.

188

Sec. Cor. to Sections 34 & 35 only,
 Found - I. Pipe at Sec. Cor. See Ren. #72.
 Orig. 42", Fir N. $74\frac{1}{2}^{\circ}$ E. 45.2 ft., shows scar.
 10", now 13" Fir N. 69° E. 35.7 ft., shows good scar.
 7" Laure, now 10", N. 79° W. 10.5 ft. scribed T30S R3W.
 20" Laurel S. 8° W. 22.5 ft. "BT" in wood, bark scribe.
 24" Laurel S. 36° E. 18.0 ft. "BT" in wood, " "
 Set - Brass Cap at Cor. alongside I. Pipe Mkd: T30S R3W
 County Surveyor's Office, 1965 S 34 / S 35 S 3 T31S R3W
 BT: 24" Laurel S. 36° E. 18.0 ft. Reblazed & Scribed T31S R3W S3 CS BT.
 As noted Corner lies on top of ridge.

*FD. OK 8/83
H. JOHNSON
M 95-6*

189

Sec. Cor. To Sections 33 & 34 only.
 Found - Iron Pipe at Sec. Cor. See Ren. #83.
 Orig. 40" Fir, now 41", S. 71° E. 19.8 ft., shows good scar.
 30" Laurel S. 34° E. 18.0 ft. scribed "S4" & bark scribed.
 20" D. Fir, now 17", N. 88° W. 11.4 ft. scribed "S33" visible.
 15" D. Fir, now 18", S. 62° W. 15.8 ft., rotten scribe visible.
 28" D. Fir, now 29", S. 84° W. 26.8 ft., bark scribed.
 Set - Brass Cap at Cor. alongside I.P. Mkd: T30S R3W
 County Surveyor's Office, 1966 S 33 / S 34 S 4 T31S R3W
 New BT's, reblazed & scribed:
 29" D. Fir S. 84° W. 27.5 ft. scribed T31S R3W S4 CS BT.
 18" D. Fir S. 62° W. 15.8 ft. scribed S4 CS BT.

*FD. OK 8/83
H. JOHNSON
M 95-6*

190

South $\frac{1}{4}$ Corner to Section 34 only.
 Found - I. Pipe at Corner, See Ren. #71.
 Orig. 13" Maple, now 25", S. $66\frac{1}{2}^{\circ}$ E. 5.9 ft., prev. opened for scribe.
 Orig. 5" Fir, now 20", N. $54\frac{1}{2}^{\circ}$ E. 31.0 ft., shows scar.
 19" Fir S. 73° W. 16.0 ft., shows parts of scribing.
 18" Maple N. 77° E. 53.0 ft. scribed $\frac{1}{4}$ S34 BT.
 Set - Brass Cap alongside I. Pipe at Cor. Mkd: T30S R3W
 County Surveyor's Office, 1965 $\frac{1}{4}$ S 34 T31S R3W

*FD. OK 8/83
H. JOHNSON
M 95-6*

191

South $\frac{1}{4}$ Cor. to Section 33 only.
 Found - No trace of 4' x 4' Stone. See Ren. #40.
 4" Alder, now 6", S. 57° E. 12.0 ft. Opened tree for scribe,
 found some but tree was too rotten to identify. Also
 bearing S. B. S. 37° E.
 8" Fir, now 15", S. 49° W. 25.0 ft., shows good scars.
 Set - Brass Cap at $\frac{1}{4}$ Cor. Mkd: County T30S R3W
 Surveyor's Office, 1966 $\frac{1}{4}$ S 33 T31S R3W
 New BT: 4" Hemlock N. $13\frac{1}{2}^{\circ}$ E. 28.0 ft. scribed $\frac{1}{4}$ S33 CS BT.
 Note - Corner lies directly under large windfall. Creek bears west
 about 150 ft. Corner is on E. - W. cutting line.

*FD. B.C. 480
BIM ADMIN. Survey
SEE GIS FILE*

John M. Powell
 Frank Jones & Joe Brady
 Dec. 1965 & Jan. 1966
 C. S. File No. 52/63