

Douglas County Surveyor's Record of
Government Corners Renewed

T. 30 S. T. S. R. 3 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21001

198

Section Corner to Sections 13 - 14 - 24 - 23.
Found - Co. Surveyors Brass Cap at Sec. Cor., See Ren. #97.
8" Cedar, now badly burnt, N. 24° W. 29.0 ft.
24" Cedar S. 59½° W. 35.3 ft., scribe visible, "T30S R3W S22 CS BT".
8" W. Fir, now 10", S. 38° E. 8.4 ft., shows good scars.
26" D. Fir N. 85° E. 58.3 ft., shows scribing.
New BT: 13" Maple N. 22½° W. 59.6 ft. mkd. T30S R3W S14 CS BT.
Note - This corner lies on N - S slope approx. 600 ft. west of Road.

199

Section Corner to Sections 14 - 15 - 22 - 23
Found - Orig. 30" Fir Snag, face burnt, S. 10° E. 19.8 ft.
Orig. 38" Fir Snag, face burnt, N. 45° W. 19.2 ft.
14", now 16" D. Fir, S. 24° W. 56.6 ft., "BT" visible. #213
3" D. Fir, now burnt, S. 18° W. 15.9 ft., shows scar. REN#93
3" D. Fir, now burnt, S. 58° W. 7.6 ft., shows scar.
2" D. Fir, now burnt, N. 74° E. 6.3 ft., shows scar & part of scbng.
1" Iron Pipe at Section Corner.
New BT's: 48" D. Fir S. 10° W. 80.3 ft. mkd. T30S R3W S22 CS BT.
14" D. Fir S. 52° W. 74.7 ft. mkd. T30S R3W S22 CS BT.
Note - Corner now falls in burn, no other trees within reason to scribe.
Corner lies on steep west slope approx. 40.0 ft. north of sm. ravine.

MICROFILM TO HERE 10/67

200

¼ Corner to Sections 15 and 14.
Found - 5/8" Iron Road at ¼ Corner, See Ren. #92. #212
12" Yew, now down & burnt, N. 28½° W. 27.5 ft., scribe visible, "B S".
No trace of N.E. Bearing Tree.
New BT's: 16" Hemlock N. 21° W. 34.7 ft. mkd. ¼ S15 CS BT.
21" Hemlock N. 4° E. 55.2 ft. mkd. ¼ S14 CS BT.
Note - This corner lies approximately 10.0 ft. E. of small creek.

201

¼ Corner to Sections 27 and 34.
Found - 39" D. Fir, now stump, N. 70° E. 36.3 ft., tree opened, "S"
visible, Open for "BT". Ring count places D. Fir face
approximately 98 years.
No trace of Laurel S.W.
Set - Brass Cap at Cor. Mkd: County Surveyor's T30S R3W
Office ¼ S 27
1968 S 34
New BT's: 20" Laurel N. 60° E. 80.6 ft. mkd. ¼ S27 CS BT.
55" D. Fir N. 82° E. 46.0 ft. mkd. ¼ S27 CS BT.
No trees for good control in the south quad.
Note - This corner lies on steep south slope approx. 350 ft. N. of
Milo Store & Post Office. March, 1968

MARCH 71

202

1/4 Corner to Sections 30 and 29.
Nothing found at ¼ Corner., Set by prop. measurement.
Set - Brass Cap Stamped: T30S R3W (SEE #12)
¼ S 30 S 29 242
RLS 934
from which: 1972
A 10" Cedar scribed "T30S R3W 1/4 S30 bears West 6.4 ft.
A 9" D. Fir scribed "T30S R3W ¼ S29 bears S. 82° E. 42.6 ft.

203

Center of Section 29.
Set - Brass Cap Stamped: T30S R3W
C 1/4 S 29
from which: RLS 934
1972
A 42" W. Oak scribed "T30S R3W C ¼ S29" bears N. 8° 10' W. 258.0 feet.
A 32" B. Oak scribed "T30S R3W C ¼ S29 bears S. 49° 10' W. 242.3 ft.
A fence corner, fences S. & W., bears S. 10° 45' E. 25.0 feet.

Victor M. McLind
For Murray & Washburn
May, 1972
Map File No. M 42 - 63

JAN 1973

John M. Powell
Frank Jones & Joe Brady
November, 1967
C. S. File No. 54/52

RE-RENEWED CORNER NO. #213
RE-RENEWED CORNER NO. #212
RE-RENEWED CORNER NO. #223