

Douglas County Surveyor's Record of
Government Corners Renewed

30 T. S. 3 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

206

L.E. Monrean
P.L. Earle
J.H. Cook
1/22/76
C.S. 59/2

Continued-----

1 " iron pipe along side.
New BT's: Douglas fir, 9" dia. bears N58 1/2°W., 61.5 ft. Tree blazed and scribed "T30S R3W S18 CS Bt"
A red fir, 40" dia. bears N48 1/2°E, 48.1 ft.
Tree blazed and scribed T30S R3W S17 CS BT" Mag Dec. 20°E 1/22/76

Closing Corner to Secs. 1 and 12 only, T30-4. See Ren. #57 T 30-4 and 1965 BLM Resurvey

Found: Original 29" D. Fir which bears N. 29° W. 14 ft. Visible scribing on previously opened SE blaze, NE face had been cut out. Alive but damaged.

Original 20" now 24" D. Fir which bears S. 80° W. 11 ft. Blaze healed over, tree alive and well.

3/4 " X 17 1/2" Iron Pipe set at corner point.

Set: At corner point determined by original BT's I set 1" X 30" Iron Pipe with Brass Cap stamped:

Douglas County Surveyor 1976
T 30 S
R 4 W | R 3 W
S 1 | S 7
S 12

Replaced found 3/4" Iron Pipe in ground North side of Brass Cap.
New BT's: 10" G. Fir bears N. 71° W. 79.3 ft distance mkd. "T30S R4W S1 CC CS BT" in a double blaze.
Compass Dec. 20° East.

A. Victor Cangie
Peter L. Earle
County Surveyors
March 31, 1976
C.S. 59/8

208

1/4 Corner for Secs. 35 and 36.

Found - A 20" now 35" Fir, bears S.66 3/4°E., 15.2 ft. Tree has been previously opened but shows no scribing. Alive and well.
A 30" now 50" Pine bears N.63 1/2°W., 37.0 ft. Tree has been previously opened and shows "1/4" on old face. Alive and well.
A 2" wooden post at the corner point. Did not find orig. stone.

Set - A 1"x30" Iron pipe with brass cap stamped:

DOUGLAS CO. SURVEYOR T 30 S R 3 W
S 35 | S 36
1/4
1976

A. Vic Cangie
Jim Cook
Karen Cheney
Doug. Co. Surveyors
Sept. 2 1976
C.S. 59/24

9/2/76

1/4 Corner for Sec. 36 only. East side.

Found - a 7" Maple bears N.60 1/4°W., 14.5 ft. Tree is dead & shows old opened face. Rotted & no visible scribing.

A 6" now 8" Laurel stump bears N.28 1/4°E., 15.8 ft. No visible scribing.

The intersecting point from above BT's places cor. point approx. .10 chs. North of an east-west ravine as per orig. line notes. Also found orig. Fir line tree approx 4.40 chs. North of cor. point. At the cor. point, we find a 40" windfall making it impossible to occupy. We set a witness corner:

Set - 1" x 30" iron pipe with brass cap stamped:

Douglas Co. Surveyor 1976 Witness Corner
T 30 S
R 3 W | R 2 W
S 36 |
1/4 South ↓
47.3'

New BT's - A 7" W. Fir, bears S.84 1/2°W., 9.8 ft. mkd. "WC 1/4 S36 CS BT" in a double blaze.

An 8" D. Fir, bears S.40 1/2°E., 11.9 ft. mkd. "WC 1/4 RP CS BT" in a double blaze.

9/8/76

210

Closing Corner For Secs. 36 and 31, T30-2, only.

Found - An orig. 26" now 36" Fir that bears N.59 1/2°E., 64.5 ft. (rec. 67.3') Alive & well. Shows good scar.

An orig. 30" now 36" Cedar, bears N.16 1/4°W., 48.5 ft. Tree is alive & shows good scar.

An orig. 29" now 31" stump that bears S.82 1/2°E., 24.4 ft. Visible scribing showing.

CONT. NEXT PAGE

A. Victor Cangie
Jim Cook
Mike Tompkins
Co. Surveyor's Office
Sept. 14, 1976
C.S. 59/24

A. Victor Cangie
Pete Earle
Douglas Co. Surveyors Office
Sept. 8, 1976
C.S. 59/24